#### AMENIA TOWNSHIP LANDFILL START ONE ADMINISTRATIVE RECORD FILE INDEX OF DOCUMENTS

#### 1.0 FACTUAL INFORMATION/DATA

#### 1.2 Site Investigation

P.	100001-	Report: Engineering Investigations at Inactive Hazardous Waste Sites in
	100104	the State of New York, Phase II Investigation, Old Amenia Landfill, Site
		No. 314006, Town of Amenia, Dutchess County, New York, prepared by
	, , , , , , , , , , , , , , , , , , ,	Lawler, Matusky & Skelly Engineers, prepared for New York State
		Department of Environmental Conservation, April 1993.

P. 100105Report: Test Pit Installation Report, Old Amenia Town Landfill Site,
prepared by Tams Consultants, Inc., prepared for Superfund Standby
Program, New York State Department of Environmental Conservation,
October 6, 1998.

#### 2.0 DECISION DOCUMENTS

#### 2.3 Documentation of State Involvement

P. 200001- Letter to Mr. Richard Caspe, Director, Emergency & Remedial Response Division, U.S. EPA, Region II, from Mr. Michael J. O'Toole, Jr., Director, Division of Environmental Remediation, New York State Department of Environmental Conservation, re: Amenia Town Landfill Site (#3-14-006), Amenia(T), Dutchess County, Request for Emergency Removal, October 5, 1998.

#### 3.0 PUBLIC PARTICIPATION

#### 3.3 Fact Sheets

P. 300001- Fact Sheet: "EPA Superfund Removal Program, Amenia Town Landfill, 300002 Amenia, New York," prepared by U. S. EPA, Region II, December 1998.



Millbrook Round Table Register Herald The Voice Ledger January 21 , 1999 The Pawling News Chronicle STATE OF NEW YORK **Publications Dutchess Magazine Hudson Valley Guide** COUNTY OF DUTCHESS Weekend Melissa A. Swart , being duly sworn, says she is the Legal Ad Manager of the Taconic Media Inc. and that the advertisement attached has been published in the following newspaper(s) for 1 consecutive weeks, commencing on the 21st day of January , 1999 and ending on the 21st day of January , 1999 . ☐ Gazette Advertiser, Rhinebeck, NY Harlem Valley Times, Amenia, NY Hyde Park Townsman, Hyde Park, NY Millbrook Round Table, Millbrook, NY Register Herald, Pine Plains, NY ☑ The Voice Ledger, LaGrange & Pleasant Valley, NY The Pawling News Chronicle, Pawling, NY Sworn to before me this \_\_\_\_\_ day

Taconic Press PO Box 316:

914/677-8241 Fax 914/677/6337

Newspapers
Gazette Advertiser
Harlem Valley Times
Hyde Park Townsman

Front Street and Merritt Avenue Millbrook, NY 12545-0316

Therese K. Mustello
Notary Public, State of New York
No. 01MU5011959
Qualified In Dutchess County
My Commission Expires 6/15/99

January

### NOTICE OF PUBLIC

The United States Environmental Protection Agency Announces

The Availability of the Administrative Record for

#### the Amenia Town Landfill Site

The U.S. Environmental Protection Agency (EPA) announces the availability for public review of files comprising the administrative record for the selection of the removal action at the Amenia Town Landfill Site. The EPA seeks to inform the public of the availability of the record file at this repository and to encourage the public to comment on documents as they are placed in the record file.

The administrative record me includes documents which form the basis for the selection of a removal action at this Site. Documents now in the record file include: the state referral letter, Test Pit Excavation Report and a Fact Sheet. Other documents may be added to the record files as site work progresses. These addiinclude, but are net life-ited to, other technical reports, validated sampling data, comments, new data submitted by interested persons, and the EPA responses to significant comments.

The administrative record files are available for review during normal business hours at

Amenia Free Library, Main Street, Amenia, NY 12501, Attention. Miriam Devine, (914) 373-8273; U.S. EPA Region II, Removal Action Branch, 2890 Woodbridge Avenue, Bidg. 209, Edison, NJ 08837, (732) 906-6813.

Additional Information is available at the following location: Guidance documents and technical literature-U.S. EPA-Region II, Removal Records Center, 2890 Woodbridge Avenue, Bidg. 205, Edison, NJ 08837; Phone: (732) 906-6980.

Written comments on the Administrative Record should be sent to: Immer Henry, On-Scene Coordinator, Removal Action Branch, U.S. EPA-Region II, 2890 Woodbridge Ave., Edison, NJ 08837.

# ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES

# PHASE-II INVESTIGATION

Old Amenia Landfill Site No. 314006
Town of Amenia Dutchess County, New York

DATE: April 1993

Report



New York State
Department of
Environmental Conservation

50 Wolf Road, Albany, New York 12233 Thomas C. Jorling, *Commissioner* 

Division of Hazardous Waste Remediation Michael J. OToole, Jr., P.E., Director

By: Lawler, Matusky & Skelly Engineers

#### ENGINEERING INVESTIGATIONS AT INACTIVE HAZARDOUS WASTE SITES IN THE STATE OF NEW YORK PHASE II INVESTIGATION

# OLD AMENIA LANDFILL Town of Amenia, Dutchess County, New York NYSDEC I.D. No. 314006





#### Prepared for

DIVISION OF HAZARDOUS WASTE REMEDIATION
NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION
50 Wolf Road, Albany, New York 12233
Thomas C. Jorling, Commissioner

LMSE-93/0501&576/058

Prepared by

LAWLER, MATUSKY & SKELLY ENGINEERS
Environmental Science & Engineering Consultants
One Blue Hill Plaza
Pearl River, New York 10965

**April 1993** 

## TABLE OF CONTENTS

LIST OF FIGURES	iii
LIST OF TABLES	iv .
LIST OF PHOTOS	<b>v</b> ·
1 EXECUTIVE SUMMARY	1-1
2 OBJECTIVES	2-1.
3 DESCRIPTION OF PHASE II INVESTIGATION	3-1
3.2 Site Reconnaissance 3.3 Geophysics Survey 3.4 Soil Gas Survey	3-1 3-1 3-1 3-3 3-4
	3-4 3-5
3.6 Air Monitoring	3-6
4 SITE ASSESSMENT	4-1
4.1 Site History 4.2 Site Topography 4.3 Site Hydrogeology 4.4 Phase II Results	4-1 4-5 4-6 4-7
4.4.1 Site Inspection 4.4.2 Geophysics Data 4.4.3 Soil Gas Data 4.4.4 Surface Soil Data - Mobile Laboratory 4.4.5 Surface Soil Data - Fixed Laboratory 4.4.6 Surface Water Data	4-7 4-8 4-10 4-12 4-12 4-14
4.4.7 Sediment Data 4.5 Conclusions	4-16 4-18

Page No.

# TABLE OF CONTENTS (Continued)

	-					·.			Page No.
	4.5.1	Geophysics Survey					·		
		Soil Gas Survey				1			4-18
	4.5.3					٠			4-18
r	4.5.4	Surface Water/Sediment							4-19 4-21
4.6	Recor	mmendations	* ',	<del></del>		<del></del>			4-21
* *		Soil Complian				• .			
	4.6.1 4.6.2	Soil Sampling							4-22
	4.6.3	Test Trenches		•				•	4-22
	4.6.4	Groundwater Monitoring							4-23
	7.0.7	Biomonitoring Program	:						4-26
REFE	RENC	ES CITED							R-1
									K-1
LIST	OF SU	PPORTING DOCUMENT	ATION	•	, ,				R-3
ADDE		~c				•			
AFFE	NDICE	သ			1				
Α	- Data	Usability Summary		•	. *				
В	- Perti	nent Files or Records			•		•		•

PLATE - Aerial Photographs of Site

## LIST OF FIGURES

Figure No.	Title	Following Page
	Site-Location	1-1
1-2	Site Sketch	
i <del> <b>3-1</b>:</del>	Soil Gas Sampling Locations	<b>3-3</b>
3-2	Typical Soil Gas Point Construction	3-4
3-3	Soil Sampling Locations	3-4
3-4	Surface Water/Sediment Sample Locations	3-5
4-1	Magnetometry Results	4-8
4-2	Soil Gas Results	4-10
4-3	Recommended Test Trench Locations	4-22
4-4	Recommended Monitoring Well Locations	4-23
4-5	Number of Samples Required to Detect Difference at $\alpha = 0.05$ , $\beta = 0.10$ , and Various Coefficients of Variation	4-26

#### LIST OF TABLES

Table No.	Title	Page No.
3-1	Field Measurement Data for Surface Water Samples	3-5A
4-1	Geophysical Results - Vertical Electrical Soundings	4-9A
4-2	Soil Gas Data Summary (November 1991)	4-10A
4-3	Surface Soil Field Data Summary (November 1991)	4-12A
4-4	Surface Soil Data Summary (November 1991)	4-12B1
4-5	Surface Water Data Summary (November 1991)	4-15A1
	C. P. Dave Summer (November 1991)	4-16A1

#### LIST OF PHOTOS

Photo No.	Title	Following Page		
1	Southern half of central site area, taken	1-1		
	from center of helipad looking south	,		
2	Helipad and central site area, taken from	1-1		
	top of ridge in southwestern portion of site looking northeast			
3	Drum disposal area west of access road near southern end	1-1		
4	Scrap metal disposal area on western bank of	1-1		

#### CHAPTER 1


#### **EXECUTIVE SUMMARY**


The Old Amenia Landfill site is located on the west side of Route 22 in the Town of Amenia, Dutchess County, New York (Figure 1-1). Except for a period between the end of 1968 and April 1971, the town used the 10-acre site as a municipal dump from the late 1940s until 1976. The northern portion of the site, currently owned by Mr. Karl Saliter of Sharon, Connecticut, is occupied by the Sharon Oil & Gas Company fuel storage enclosure, which consists of a number of aboveground storage tanks within a fenced, bermed area (Figure 1-2). Mr. John Segalla of Amenia is the present owner of the southern portion of the site. With the exception of a small helipad and paved access road, the southern portion is a well-graded, maintained, grassy area. Photos 1-4, which depict the site, are oriented to Figure 1-2.

During the period of operation of the site as a landfill, the ownership of the property changed several times. The Town of Amenia rented the property from William and Mary Murphy for disposal of municipal wastes from approximately 1947 until December 1968, when the property was sold to Salvatore (Ben) Surico. The town discontinued dumping at the site and opened an emergency disposal area on the property immediately north of the site.

Industrial wastes were known to be present at the site during the time Mr. Surico operated the landfill, from 1969 until April 1971. Dutchess County Department of Health (DCDOH) inspection records, a local newspaper article, and an aerial photograph of the site dated April 1970 confirm the presence of a large number of 55-gal drums stored in a bermed area at the site. Industrial wastes were reportedly removed from the barrels and transported off-site in tanker trucks; the empty drums were sold or crushed and buried on-site. Local residents, however, noted oil on the surface of the water in the nearby wetlands area and oil-like odors emanating from the site. In addition, DCDOH inspection reports document that industrial wastes were leaking onto the ground surface from barrels stored at the site.

In 1971 the Town of Amenia assumed responsibility for the operation of the landfill when Mr. Surico filed for bankruptcy. The town continued to operate the landfill for the disposal








PHOTO 1. Southern half of central site area, taken from center of helipad looking south.




PHOTO 2. Helipad and central site area, taken from top of ridge in southwestern portion of site looking northeast.




PHOTO 3. Drum disposal area west of access road near southern end.



PHOTO 4. Scrap metal disposal area on western bank of site near northern end of access road.

of municipal wastes until it was officially closed on 16 April 1976. Closure of the dump involved application of a soil cover of unknown depth and grading of the site.

The landfill was listed with the New York State Department of Environmental Conservation (NYSDEC) as a Reported Hazardous Waste Site in 1980 based on a site inspection that revealed evidence of drums in the southwest corner of the site in an area with no vegetative growth. The U.S. Environmental Protection Agency (EPA) identified the Old Amenia Landfill as a Potential Hazardous Waste Site in 1981. A Phase I investigation in August 1986 concluded that a Phase II investigation was needed to confirm the presence of hazardous wastes at the site and to determine whether any contamination present poses a significant threat to human health or the environment. In 1987 EPA collected a soil sample along the western side of the landfill during a limited field investigation. The sample contained 170 ppm of polychlorinated biphenyls (PCBs) (Aroclor 1248).

Lawler, Matusky & Skelly Engineers (LMS) was retained by NYSDEC to perform the Phase II investigation, which consisted of a geophysical survey, soil gas survey, and sampling and analysis of site soils, surface waters, and sediments. In addition, a literature search and an interview with a local resident familiar with the site history were conducted to obtain any available information on past waste disposal practices at the site.

The geophysical survey located several areas of potentially large concentrations of buried metallic materials. The results correlated well with the soil gas survey data, which identified three areas of high volatile organic compound (VOC) contamination in close proximity to the location of the identified magnetic anomalies. Vinyl chloride concentrations as high as  $340,000 \ \mu g/m^3$  were detected in soil gas samples obtained from the central site area between the helipad and the Sharon Oil fuel storage enclosure. It is suspected that a relatively large mass of buried metallic materials may exist at this location.


Surface soil samples collected along the western slope of the landfill during the Phase II investigation were analyzed for PCBs using an on-site mobile laboratory. Fifteen of the 20 samples analyzed contained detectable levels of PCBs, with concentrations ranging from 2.3 to 250 mg/kg. The sample with the highest identified PCB concentration was obtained from

the same area as the NUS Corporation sample collected in 1987 that contained 170 ppm PCBs (Aroclor 1248). Ten of the 20 surface soil samples with the highest PCB concentrations were also analyzed for VOCs in the on-site mobile laboratory. Only one sample had detectable concentrations of a VOC (ethylbenzene).

Four additional surface soil samples were collected from the locations showing the highest PCB concentrations in samples analyzed by the mobile laboratory; these samples were sent to a fixed laboratory for analysis. All four samples contained detectable levels of PCBs, with concentrations ranging from 0.12 mg/kg in the sample obtained at the southern end of the site near the apparent drum disposal area to 48 mg/kg in the sample obtained near the western end of the Sharon Oil fuel storage enclosure fence. These samples did not show detectable levels of VOC contamination, although the soil gas survey found moderate to high levels of VOCs at several locations. Because of the high mobility of VOCs in soil, volatile constituents in surface soils are likely to have volatilized to the atmosphere or migrated to subsurface soils or groundwater. The relatively high levels of VOCs detected in the soil gas indicate the likelihood of a substantial source of subsurface contamination.

Surface water and sediment samples were collected from the wetlands adjacent to the site. Significant VOC, semivolatile organic, pesticide, or metals contamination was not detected in the surface water/sediment samples. PCBs, however, were detected in three of the sediment samples and in one of the surface water samples, indicating that PCBs are migrating from the site to the adjacent wetlands.

Based on the detection of PCBs in site soils, surface water, and sediments, the New York State Division of Fish and Wildlife has determined that the Old Amenia Landfill poses a significant threat to wildlife. Therefore, the Old Amenia Landfill has been classified as a Class 2 site. A remedial investigation of the site is warranted to fully delineate the extent and magnitude of the contamination present, assess the degree and rate of migration of contaminants from the site, and evaluate the threat posed to human health and the environment by the contamination.



- Soil Sampling: Additional soil samples should be collected throughout the site
  to delineate the extent of PCB contamination. In addition, subsurface samples
  should be collected from soil borings installed at the site to determine whether
  PCB contamination exists below the surface.
- Test Trenches: LMS recommends the installation of approximately five test pits to locate and immediately remove any buried drums containing industrial or hazardous wastes. The test trenches should be excavated in areas that showed magnetic anomalies indicative of buried masses of metallic objects and had VOC concentrations in the soil gas samples, as determined during the Phase II investigation.
- Groundwater Monitoring: A groundwater monitoring program is recommended to assess the existence and migration of VOC or PCB contamination in the aquifer underlying the site. This program would involve the installation of at least one upgradient and three downgradient monitoring wells to obtain pertinent data on the site stratigraphy, groundwater flow regime, and water quality.
- Biomonitoring: LMS recommends a biomonitoring program to determine the extent of bioaccumulation of PCBs in aquatic organisms in the wetlands adjacent to the site. A two-stage program is the most cost-effective approach. Appropriate species for monitoring would be identified in the first stage, and an adequate number of organisms to provide statistically significant results for evaluating the impact of PCB contamination on aquatic species would be obtained and analyzed in the second stage.

#### **OBJECTIVES**

Lawler, Matusky & Skelly Engineers (LMS), under contract to the New York State Department of Environmental Conservation (NYSDEC), conducted a Phase II investigation of the Old Amenia Landfill site located in the Town of Amenia, Dutchess County, New York. The investigation was targeted to (1) confirm the presence of hazardous wastes at the site; (2) adequately assess whether contaminants from the site have been released to the surrounding environment; (3) determine whether there is a significant threat to the environment or public health: (4) prepare final Hazard Ranking System (HRS) scores if directed to do so by NYSDEC; and (5) make recommendations for any appropriate future actions at the site.

Specific objectives of this Phase II investigation were to:

- Conduct a literature search to obtain any available information on past waste disposal practices at the site.
- Conduct a geophysics survey, a soil gas survey, and environmental sampling and
  analysis to identify and evaluate the presence, concentration, and nature of
  contamination and determine, to the extent limited by the scope of work, its
  release (if any) to the environment.
- Using information compiled in the study, determine the significance of any contaminant release and the degree to which it may threaten surrounding areas.
- Prepare a report documenting all findings, with a recommendation to classify or delist the site, if appropriate, or to proceed with additional site investigative work.

The Old Amenia Landfill Phase II investigation is discussed in detail in Chapters 3 and 4. This report includes the following appendices:

- A Data Usability Summary
- B Pertinent Files or Records

#### CHAPTER 3

#### DESCRIPTION OF PHASE II INVESTIGATION

#### 3.1 LITERATURE REVIEW

Before initiating field activities, LMS reviewed relevant files on the Old Amenia Landfill at the Dutchess County Department of Health (DCDOH), the New York State Department of Health (NYSDOH), the NYSDEC Region 3 and Central offices, and EPA Region II offices. In addition, a local resident familiar with the history of the site was interviewed (Ref. 1). The literature review was performed to update the site history information presented in the Phase I report and to reevaluate it for completeness and accuracy. Site history details obtained in the literature review are presented in Section 4.1.

#### 3.2 SITE RECONNAISSANCE

The Late Talkers in the

LMS personnel conducted a site reconnaissance on 9 October 1991 (Ref. 2). The objectives of the site visit were to confirm site conditions as described in the approved work plan, determine ease of equipment access, and perform air monitoring. Potential soil gas sampling and test trench locations were also identified during the reconnaissance. Results of the site reconnaissance are discussed in Section 4.4.1.

#### 3.3 GEOPHYSICS SURVEY

A geophysics survey was performed to locate the best areas for test pit excavation as recommended in the work plan for the Old Amenia Landfill site. Results of the survey were reviewed in conjunction with the soil gas survey results to determine whether the two surveys agreed on the locations of potential areas of subsurface contamination.

Two methods of geophysical investigation were used at the site: a surface magnetometry survey and resistivity measurements. The magnetometer accurately records the total magnetic field at many individual locations. Thus, magnetometry surveys are most applicable for

3-1

locating buried masses of metallic objects such as drums. The total magnetometer reading measures several components: the main magnetic field (which remains constant over a period of time), an external field (which changes over relatively short time intervals during the survey), and a third field that results from any anomalies that affect the main field. The external field varies over the course of the day; to effectively compensate for this, additional readings are collected at a fixed base station of known field intensity. The variations recorded at this location during the survey are then used to adjust the corresponding main-field measurements.

Anomalies within the main field may be created by both small and large magnetic masses. Force created by a magnetic object is directly proportional to the mass of the object and inversely proportional to the distance of the object from the point of measurement. The main field is created by a large mass (the earth's core) at a vast distance from the ground surface; this field may be altered by a relatively small object much closer to the point of measurement. A larger object or mass at a greater depth could also affect the main-field measurement.

The magnetometry survey was conducted over the entire site surface. The only areas excluded were on the northern and western sides of the site where the steep slopes made transversing for measurement collection nearly impossible. Areas within the confines of the chain-link fence (Sharon Oil & Gas Company property) and the footprint of the helipad were also not surveyed. A 10-ft grid pattern was used for data collection. Multiple readings were made at each station to measure the stability of the external field. Results of the magnetometry survey are discussed in Section 4.4.2.

An electrical resistivity survey was conducted at five locations on the site. Electrical resistivity surveys measure the apparent resistivity of subsurface materials by introducing an electrical current into the ground between two electrodes separated by a known distance. A second pair of electrodes is used to measure the difference in potential. Various spacings of electrodes are used to measure the apparent resistivity of materials at different depths above and below the saturated zone. The results of each measurement can be compared with known values for specific materials and subsurface conditions. The data and known values


depth to water table, and generalized stratigraphic layering can be determined by using vertical electrical soundings (VES).—Results of the electrical resistivity survey are also included in Section 4.4.2.

#### 3.4 SOIL GAS SURVEY

A soil gas survey was conducted at the Old Amenia Landfill site between 5 and 7 November 1991. The 24 soil gas points installed at the locations shown on Figure 3-1 were concentrated in areas identified during the site reconnaissance as potential locations for test trenches. Twelve points were installed south of the Sharon Oil fuel tank enclosure in the central landfill area; two points, immediately inside the fuel storage area fence; one point, in the peninsula north of the Sharon Oil enclosure; five points, around the unvegetated, slumped area on the southwest side of the central portion of the site; two points, at the northern end of the access road leading to the reported drum disposal area; and two points, near the drum disposal area in the southwest corner of the site. Soil gas samples were analyzed on-site for volatile organic compounds (VOCs) by Tetra•K Testing of Westfield, Massachusetts, using a mobile laboratory (Ref. 3).

To obtain the best results, soil gas points were installed 3 to 6 ft below grade to prevent groundwater from being introduced into the sampling system. A slam bar was used initially to drive the guide hole. Upon removal, the slam bar was inspected for moisture to determine whether the saturated zone had been penetrated. If the slam bar met refusal, a new hole was made 1 to 2 ft away.

The steel soil gas point was then assembled with Teflon tubing, inserted into the original hole, and driven to the desired depth. The hammer and rod assembly was subsequently removed from the hole, leaving the point and attached tubing in place. Sand was used to backfill around the tubing up to 1 ft above the point to provide a capture area for soil gases. Bentonite powder and water were then used to backfill the remainder of the hole, thus creating a seal above the point. A clay seal was installed around the tubing at grade level to prevent any inflow of ambient air during purging and sampling of the hole. Finally, a clay



plug was inserted at the end of the tube to prevent debris from entering the tubing prior to sampling. (The construction details of a typical soil gas point are shown in Figure 3-2.)

Measured soil gas samples were obtained using a portable pumping system. Samples can be obtained at any time after installation of a point except immediately after precipitation. Sampling is typically delayed for 24 hrs following a rainstorm to allow the saturated upper soil layer to reach equilibrium.


#### 3.5 SAMPLING


#### 3.5.1 Surface Soil Sampling

Surface soil sampling was conducted at the Old Amenia Landfill site on 7 and 8 November 1991 to confirm and quantify any PCB contamination present. Samples were analyzed in the on-site mobile laboratory so that if "hot spots" were found, additional soil samples could be collected from those locations for analysis at a fixed laboratory. Twenty surface soil samples were collected from a depth of 0-6 in. at the locations shown on Figure 3-3. Eight of these samples were taken from locations corresponding to sampling locations NY66-S1, -S2, -S3, and -S4 selected by NUS Corporation (under contract to EPA) during the 1987 field investigation of the site (Ref. 4). Samples were collected every 50 ft (total of 10) at the base of the western slope of the site beginning at the northern end of the Sharon Oil enclosure fence line. The remaining two samples were collected at the locations of highest observed PCB concentrations based on the on-site mobile laboratory analyses.

All soil samples were analyzed on-site for PCBs using the mobile laboratory. In addition, the 10 (of 20) soil samples with the highest levels of PCB contamination as determined by on-site analyses were analyzed for target compound list (TCL) VOCs.

On 11 November 1991 four additional surface soil samples were collected for analysis at a fixed analytical laboratory. Two samples were collected from the locations with the highest field-measured PCB concentrations (SS-17 and -18, as shown on Figure 3-3). One sample was collected from the unvegetated bare spot in the southwestern portion of the central site area





(SS-19) and one from the drum disposal area in the southwestern corner of the site (SS-20). Matrix spike/matrix spike duplicate (MS/MSD) samples were collected at sampling location SS-19. All samples were packed in ice chests and shipped via overnight courier to a fixed laboratory for full TCL organics (including PCBs), metals, cyanide, extraction procedure (EP) toxicity, reactivity, ignitability, and corrosivity analyses.

#### 3.5.2 Surface Water/Sediment Sampling

An LMS crew sampled surface water and sediments according to NYSDEC protocols at five locations (Figure 3-4) between 20 and 23 November 1991 (Ref. 5). All locations were selected by LMS personnel according to work plan recommendations and were approved by a NYSDEC representative before sampling commenced. Surface water/sediment sample AMSW/AMSD-1 was collected from the stream in the wetland area that borders the landfill to the north. AMSW/AMSD-2 through -5 were collected from the pond that borders the landfill on the west.

Samples were submitted to Nytest Environmental Inc. of Port Washington, New York, for VOC, semivolatile organics, pesticides, PCBs, metals, cyanide, and conventional parameter analyses. In addition, samples were sent to Aquatec Inc. of Colchester, Vermont, for low-level PCB analyses. Surface water samples were collected directly into the sample containers or with Teflon dip buckets. Sediment samples were collected with stainless steel core tubes or with a petite ponar. Temperature, pH, and specific conductance were measured at each sampling location. The results of these field measurements are presented in Table 3-1.

Samples were collected in precleaned bottles/vials provided by Aquatec and Nytest. All sample containers were labeled with the site name, job number, sample I.D., date, time, and parameters for analysis. Preservatives were added in the field where appropriate. Sample containers were packed in ice chests maintained at 4°C and shipped via overnight courier to Nytest and Aquatec for analysis under chain-of-custody protocol.

Because of damage incurred during shipping, surface water samples AMSW-3, -4, and -5 had to be resampled on 23 November 1991 for the volatile organic, semivolatile organic, and




TABLE 3-1

# FIELD MEASUREMENT DATA FOR SURFACE WATER SAMPLES

Old Amenia Landfill - NYSDEC I.D. No. 314006

SURFACE WATER I.D.	TEMPERATURE (°C)	SPECIFIC CONDU (µmhos/cm @	pH UNITS
AMSW-1	8.1	459	7.8
AMSW-2	8.1	408	8.0 8.0
AMSW-3 AMSW-4	8.3 8.4	408	 - 8.4
AMSW-5	8.4	444	7.9

pesticide fractions. Identical sampling protocols were used to collect the second set of surface water samples, which were submitted to Nytest for analysis.

#### 3.6 AIR MONITORING

During the site reconnaissance visit, an air monitoring program was conducted using an HNU photoionization detector (PID), an OVA flame ionization detector (FID), and an MSA combustible gas indicator (CGI) as discussed in the site inspection report (Ref. 2). Air monitoring, conducted in accordance with the NYSDEC-approved work plan, consisted of traverses of the site within the property boundaries. The survey objectives were to determine whether any previously unidentified sources of air contamination were present at the site and to confirm that the proposed level of personnel respiratory protection was appropriate.

Air monitoring was performed at ground level and within the breathing zone (4 to 5 ft above grade) (Ref. 2). This information was used to prepare the final site-specific health and safety plan (HASP) followed by LMS and subcontractor personnel during field investigation activities (Ref. 6). Based on site conditions, Level D personal protective equipment was specified for field activities. As a contingency safety measure, Level C equipment, including full-face, air-purifying respirators, was available at the site at all times.

#### **CHAPTER 4**

#### SITE ASSESSMENT-

ทั้งใช่เพื่อเพิ่ม ( 15 กร้างได้โดยสาร ทั้น

#### 4.1 SITE HISTORY

The Old Amenia Landfill site is an inactive municipal dump located on the west side of Route 22 in the Town of Amenia, Dutchess County, New York. Operation of the site as a dump began in the late 1940s. A Dutchess County Department of Health (DCDOH) inspection report dated 24 October 1947 identified the site as a municipal dump and noted unsatisfactory conditions. The property was owned at that time by William and Mary Murphy, who purchased a 22-acre site, which includes the 10-acre parcel under investigation, from Anna Kaplan Paley in May 1945.

During the Murphys' ownership of the land, the town rented the property and operated the dump. A 26 April 1963 DCDOH inspection report states that the dump was jointly operated by the highway departments of Amenia and the Town of Sharon (Connecticut); users of the site were listed as the Town of Sharon and the Sharon Hospital. Additional site users were listed in an October 1966 DCDOH inspection report as the Town of Amenia, residents of the Town of Sharon, Tri-Wall Corporation, and two unnamed commercial haulers.

Operation of the landfill continued until December 1968, when William Murphy sold the 22-acre site to Salvatore (Ben) Surico. At this time the Town of Amenia discontinued dumping at the site and opened an emergency disposal area immediately north of the site on property owned by Walt and Eleanor Culver. This area (not included in this Phase II investigation) was operated for approximately one year, starting in January 1969.

In late 1968 Mr. Surico applied to Dutchess County and the Town of Amenia for permits to operate a landfill on the former Murphy property. The county health commissioner granted permission for the site to be used for the disposal of refuse in January 1969; the town, however, refused. Later in the year the town was forced to grant the permit as the result of an Article 78 proceeding.

Mr. Surico operated the landfill from 1969 until approximately April 1971. The landfill permit allowed for the disposal of household refuse only. Gerald Wilcox, a local resident interviewed as part of the Phase II investigation, indicated that it was common knowledge in Amenia at that time that industrial wastes were present at the site (Ref. 1). An article in the Harlem Valley Times dated 25 June 1970 states that at a Town Board meeting a local resident asked whether industrial wastes were being dumped at the Amenia Landfill site (Ref. 7). A town supervisor responded that cutting oil was being handled at the site in an area enclosed by a 6-ft embankment. The cutting oil, from manufacturing plants in Connecticut and Massachusetts, was held at the landfill; after a full tankerload was collected, it was trucked to New Jersey for resale. No oil or waste products were reported to have been disposed of at the landfill; however, oil was routinely applied at the site to keep the dust down. The resident noted that oil had been seen floating in the adjacent stream and that there had been reports of odors.

A DCDOH internal memoradum dated July 1970 notes the presence of drummed industrial wastes at the site (Ref. 8). An inspection report dated 23 October 1970 reported the spillage and accumulation of liquid industrial wastes on the ground, and a letter was subsequently sent to Salvatore Surico by DCDOH requesting that this condition be rectified (Ref. 9). A 26 October 1970 DCDOH memorandum reported the presence of several hundred barrels of industrial wastes at the site; some had been punctured and were discharging chemicals to the ground surface (Ref. 10). The report states that no industrial waste was observed in or near the surface waters at the site. The DCDOH inspector noted the following names of companies and contents listed on the barrels:

- Remington Rand Electric Shaving Division 60 Main Street Bridgeport, Connecticut Contents: Crystoton [Crystolon?]
- U.S. Polymeric
  Contents: P.F. Etchant Ferris [ferrous] chloride
- ALRAC Division Radiation Research
   649 Howe Street (P.O. Box 2109)
   Stamford, Connecticut
   Contents: 2 Pyorrolidone [2-pyrrolidone]

The Hubbard Hall Chemical Co.
 Waterbury, Connecticut
 Contents: Mineral Spirits

The inspection report also notes that the chemicals were reportedly pumped out of the barrels for shipment to New Jersey. Undamaged empty barrels were sold; damaged barrels were crushed and buried on-site.

An aerial photograph dated 12 April 1970 obtained from the Dutchess County Real Property Tax Office shows approximately 200 drums lined up in a bermed area of the site (Plate). According to Mr. Wilcox, the bermed area was located behind a small ridge that obscured any view of the drums from passersby on Route 22. Mr. Wilcox stated that it was believed that solvents were being dumped into a pit located at the rear of the site and that the wastes being disposed of at the Old Amenia Landfill were similar to those disposed of at the Sarney site (Ref. 11).

The Sarney Farm is a National Priorities List (NPL) site consisting of a 5-acre former landfill located on Benson Hill Road in the Town of Amenia, approximately 5 miles south of the Old Amenia Landfill site. A Phase II investigation of the Sarney site was completed in June 1985, and a Record of Decision was issued by EPA in September 1990. Buried drums containing liquid solvents were found at the Sarney site. Wastes reported to be disposed of on-site included 55-gal drums of ethylene dichloride, cleaning solvents, inks, acids, water-based glues, and machine oils. Contaminants identified in the soils at this site included high concentrations of toluene, 2-butanone, 2-methyl-2-pentanone, trichloroethene, bis(2-ethylhexyl) phthalate, di-n-butylphthalate, naphthalene, and 2-methyl-naphthalene. Groundwater contaminants detected included 1,2-dichloroethane, vinyl chloride, bis(2-ethylhexyl)phthalate, and trace amounts of other organic chemicals. No pesticides or PCBs were identified in any contaminated media at the Sarney site.

In April 1971 a nearby resident filed a complaint with NYSDEC concerning odors similar to the smell of old oil emanating from the Old Amenia Landfill (Ref. 12). However, a DCDOH memorandum dated 27 April 1971 reported that the industrial waste storage area at the landfill was being dismantled and that the barrels were being removed (Ref. 13). In June of

1971, Mr. Surico transferred the property to the Tri-Town Landfill Corporation (Tri-Town), of which he was president. In August of 1971, 2 acres of the total 22-acre dump site were sold by Tri-Town to Thomas C. Romano, Peter J. Brevi, and Archie Deane, Jr., all of Amenia. This 2-acre portion of the site, currently owned by Karl Saliter of Sharon, Connecticut, is used by Sharon Oil for fuel storage; several aboveground tanks are located in this area in a bermed and fenced area. Mr. Saliter and his wife are the owners of the Sharon Oil & Gas Company.

Mr. Saliter stated that in October 1982, when the fuel oil storage area on the northern portion of the site was being constructed, he encountered approximately 10 ft of garbage and fill material during excavation. He also observed, on the northern bank of the site, three or four drums leaking a substance he believed to be fuel oil (Ref. 14).

A November 1971 DCDOH inspection report for the landfill states that Mr. Surico was in bankruptcy and that the Town of Amenia had assumed responsibility for operating the landfill. The town continued to operate the landfill until it was officially closed on 16 April 1976, although the property was transferred several times during this period. In July 1972 the 20-acre site formerly owned by Tri-Town was sold to Alistair Martin by the bankruptcy court. The property was then transferred by Mr. Martin to his wife, Edith Park Martin, in September 1972, then to the Curtiss-Wright Corporation by Mrs. Martin in June 1973.

Throughout the remaining period of operation of the landfill by the Town of Amenia (1971 to 1976), numerous violations were documented by DCDOH inspectors, including uncovered refuse, rodents, blowing papers, improper landfilling techniques (e.g., improper slope on completed areas), and unauthorized burning. In May 1974 the Curtiss-Wright Corporation (then owner of the property) was cited by the county for allowing the Town of Amenia to operate the dump in violation of NYSDEC regulations. A DCDOH inspection report dated February 1972 indicated that a fire had occurred at the site as a result of dumping of chemicals from the Sharon Hospital (Ref. 15). In July, September, and October 1973 DCDOH inspections reported the presence of barrels of liquid wastes at the rear of the site. A February 1974 DCDOH report indicated that the barrels had reportedly been removed (Ref. 15).

The town ceased operation of the landfill in 1976 at about the time that the Harlem Valley Landfill opened 0.25 mile southwest of the site. Closure of the dump involved application of a soil cover of unknown depth to the main fill area by a local contractor hired by the Town of Amenia. Following closure, the property remained under the ownership of the Curtiss-Wright Corporation until December 1982, when it was transferred to Metal Improvements Co., a wholly owned subsidiary of Curtiss-Wright. The property was then sold to the current owner, John Segalla, of Amenia, in July 1986.

The landfill was listed with NYSDEC as a Reported Hazardous Waste Site in April 1980. A 13 November 1979 inspection revealed evidence of drums in the southwest corner of the site in an area with no vegetative growth. A NYSDEC internal memorandum dated 14 November 1985 stated that an unknown number of 55-gal drums were stored at the site at the time of the landfill's closure and that some of the drums were later removed. No drums were observed during the 1986 Phase I site investigation. A NYSDEC/NYSDOH inspection in September 1990 did not reveal any drums at the site.

EPA identified the landfill as a Potential Hazardous Waste Site in 1981 and conducted a site inspection and limited field investigation in February 1987. Groundwater, surface water, soil, and sediment samples were collected by NUS Corporation. The analytical results of this investigation are included in Appendix B (Ref. 4). Analysis of a soil sample from the west side of the landfill, approximately 6 ft from the end of the fence that surrounds the Sharon Oil tank storage area, detected a PCB (Aroclor 1248) concentration of 170 ppm. In addition, phthalate compounds were identified in several of the soil, surface water, and sediment samples. The 1986 Phase I investigation concluded that a Phase II investigation was needed to determine the existence and extent of hazardous waste contamination at the site.

#### **4.2 SITE TOPOGRAPHY**

The Old Amenia Landfill site is approximately 10 acres in size. The former landfill area is well graded and relatively flat. The site is vegetated with grass and slopes to the north and west. The northern portion of the site is occupied by the Sharon Oil fuel storage enclosure.

The oil storage tanks are contained within a fenced, bermed area. A helipad in the center of the site is reached by a small paved road. Access to the site is unrestricted.

The site is adjacent to a wetland through which runs a permanent stream (an unnamed tributary of Wassaic Creek). The western and northern sides of the former landfill area are steeply sloped, dropping approximately 20 to 40 ft down to the wetland, and densely vegetated with bushes and trees. The southern portion of the site slopes gently upward to the top of a small rise, then climbs more steeply to the top of a densely wooded hill. A cleared access road (unpaved) runs from the top of the rise at the southern end of the site along the western edge of the wooded hill.

Two lakes upgradient (i.e., 20 ft higher in elevation) of the site are located approximately 1500 ft to the west. Both discharge to the permanent stream running through the wetland/pond area adjacent to the site. The nearest residence is approximately 1350 ft to the west. The nearest commercial building is about 2 miles northeast of the site. There are no national or state parks or forests within 2 miles.

#### 4.3 SITE HYDROGEOLOGY

The site is directly underlain by glacial outwash sand and gravel deposits that are confined to the valley floor and are of limited areal extent. Approximately 1 mile north of the site, the sediments are at least 70 ft thick and comprise 28 ft of water-bearing gravel overlain by 42 ft of clay with a gravel lens (Ref. 16). There are no site-specific data to confirm the presence of this thick clay, however. The unconsolidated deposits that blanket the adjacent hillsides are composed of glacial till.

The glacial sediments are underlain by marble bedrock of the Cambrian-Ordovician Age Stockbridge Formation. There are several thrust faults related to the Taconic Orogeny within 1 to 2 miles of the site. The bedrock is present at or within 3 ft of the ground surface at several locations throughout the valley, including the hills north and south of the site (Ref. 17).

Both the glacial sediments and marble bedrock (designated as Aquifer No. 74 in Ref. 17) have been developed for domestic (rural area) and public (Town of Amenia) water supplies and are considered to constitute the aquifer of concern. The glacial sediment portion of the aquifer of includes the sand and gravel deposits that are bounded by the adjacent glacial till-covered mountains (Ref. 17). Based on the available literature, hydraulic connection between these two general aquifers cannot be confirmed. However, because bedrock is reportedly within 3 ft of the ground surface in the immediate vicinity of the site, both the bedrock aquifer and the glacial sediment aquifer may be affected by conditions at the site.

## 4.4 PHASE II RESULTS

### 4.4.1 Site Inspection

The results of the site inspection conducted on 9 October 1991 indicated that the vegetative cover over the main landfill area is well maintained (Ref. 2). Fill material, e.g., broken glass and rubber, was evident in only a few areas. A number of small bare spots were observed on the southern half of the site. Three slumped areas were seen along the western edge of the landfill and in the center of the site near the helipad. The vegetation adjacent to the Sharon Oil enclosure was stressed, and there was a small patch of standing water. Light leachate staining was noted on the soil in an area located in the southeastern corner of the site.

A small ditch on the western slope of the landfill near the end of the Sharon Oil enclosure fence contained exposed fill material, several rusted (empty) drums, a tire, and several brown bottles. A similar ditch with fill material and rubbish was also observed farther to the south on the western slope. An apparent scrap metal disposal area on the western slope near the beginning of the access road to the drum disposal area contained a topless empty drum; several other drums protruded from the ground. Other scrap metal, e.g., old appliances, was also piled in this area.

An apparent drum disposal area was located in the wooded area west of the access road near the southern end of the road. The ground surface in this area was hummocky, and 10 to 12 drums protruded from the ground. The drums did not appear to be crushed.


## 4.4.2 Geophysics Data

The results of the magnetometry survey conducted at the site showed a varied pattern of magnetic signatures (Ref. 18). Two areas exhibited relatively stable magnetic patterns, indicating that the fill materials do not extend into these areas. The first area was located at the northwestern corner of the site, north of the Sharon Oil fuel storage enclosure; the second area, at the southern end of the landfill along the base of the tree-covered hill. Several outcrops were noted in this area and field measurements ranged between 53,000 and 55,000 gammas, indicating a relatively uniform subsurface material at this location. It is believed that the fill does not extend into or beyond this area.

Several zones within the confines of the landfill exhibited a pattern consisting of a low anomaly to the north with a corresponding high to the south (Figure 4-1). The most prominent zone, located between the Sharon Oil enclosure and the helipad, had a relatively high magnetic field strength trending in an east-west direction across the site. A large area protrudes to the south along this anomaly near the western side. Because no measurements were taken on the Sharon Oil property, no correspondingly low anomaly could be associated with this area. The fencing and reinforcing rods within the concrete of the helipad could cause these magnetic variations; however, the high intensity of the data indicates a nearly linear east-west pattern approximately 360 ft long and 30 to 40 ft wide. Features of this type are generally more indicative of larger-scale disturbances, such as trenches, pipelines, or other buried metallic masses.

A second anomaly oriented in an east-west direction was recorded at the grade change in the southern portion of the central site area. This appears to be a lift of fill or cover material with an approximate 15-ft difference in elevation. Corresponding high and low anomalies were found on either side of this sloped area. These anomalies trended in an east-west direction across the width of the site.

A third area with a characteristic pattern of opposing anomalies was found along the base of the tree-covered hill at the southern end of the site. Although the strength and variation of the magnetic readings are characteristic of a magnetic structure or object, it is believed that



this pattern indicates the beginning of the fill zone. As stated previously, a very stable magnetic area believed to be associated with the presence of bedrock in this area was identified immediately south of this zone.

Two smaller areas had more localized signatures, indicating the presence of magnetic material. One area was located along the western side of the landfill at the beginning of the access road leading to the southern end of the landfill. This area was identified during the site reconnaissance as the apparent scrap metal depository area. Several car bodies, empty tanks, and drums are exposed at the edge of the fill area in this location. The concentration of metallic material is believed to be localized, as the contour interval from the magnetic survey is very steep and drops rapidly a short distance eastward. The second area, located along the access road near its southern end, was identified during the site inspection as the apparent drum disposal area. A significant number of partially exposed 55-gal drums were contained in the soil. No drums protruded from the several other mounds in the soil in this area.

Vertical electrical soundings (VES) were taken at five locations across the surface of the landfill (Table 4-1). VES 1 and VES 5 were taken along the eastern side of the landfill. VES 1 was located along the south side of the helipad; VES 5 was taken 200 ft farther south atop the elevated area. The results indicated the presence of three identifiable layers of comparable thicknesses in each location. The first two layers consisted of fill less than 10 ft thick with a layer of soil in between. The third layer was between 13 and 15 ft thick at both of the sounding locations. The dramatic increase in the resistivity values at the two sounding locations (three to five orders of magnitude) is believed to be caused by the bedrock surface. Outcrops were noted near VES 5, indicating that bedrock may be found at shallow depths in this area.

Sounding locations VES 2 and VES 4 were located in the central and western portions, respectively, of the landfill area south of the Sharon Oil fuel storage enclosure. These locations also consisted of three layers. Resistivity values of the materials at each sounding location decreased with depth. The thickness of the first identified layer was between 2.7 and 5.8 ft, which may be indicative of dry fill material or areas where less moisture is present in the upper zones. The second layer was more extensive and showed a marked decrease in

TABLE 4-1
GEOPHYSICAL RESULTS - VERTICAL ELECTRICAL SOUNDINGS

Old Amenia Landfill NYSDEC I.D. No. 314006

VES No. LAYER T	HICKNESS	(ft) APPARE	ENT RESISTIVITY (ohm-m)
1 1 (surface)	6.1		8.12 22.7
	8.7		$5.6 \times 10^3$
2 1 (surface)	2.7		152
2	22.8		18.4
<b>3</b>	· ·		8.9
3 1 (surface)	9.0		55.5
2	11.3	ر از از از استوراز و در از	48.7
3	•		15.2
4 1 (surface)	5.8	na di kacamatan da kacamatan da Bandarian da kacamatan da kacama	74.1
<u>2</u>	38.0		17.8
3	•		28.6
5 1 (surface)	8.6		22.6
2	4.4		7.5
3	· · ·	· · · · · · · · · · · · · · · · · · ·	1.81 x 10 <sup>5</sup>

resistivity at both locations. Thicknesses ranged between 22.8 and 38 ft for the second layer. This interval is believed to be composed of fill materials possibly moistened or saturated with conductive leachate. The third layer produced even lower resistivity values and had no identifiable maximum depth. There was nothing to distinguish the bottom of the fill area interface with unconsolidated materials or bedrock. The lower interval of the third layer, although difficult to determine, may be the lower limit of the fill materials at the site.

Although bedrock generally has greater resistivity (as encountered at sounding locations VES 1 and VES 5), the interface between fill and clay would be difficult to discern. Also, if unconsolidated materials beneath the fill are partially or fully saturated with low-conductivity leachate, resistivity values would decrease. The data indicate that this condition may exist at sounding locations VES 2 and VES 4.

VES 3 was located north of the Sharon Oil storage facility in the wooded peninsula area. Although the VES results indicated a three-layer system, the apparent resistivity measurements were similar for all layers. The upper layer was 9 ft thick and the second layer was 11.3 ft thick. The overall difference in resistivity between the two layers was less than 10 ohm-m. The decrease in resistivity may be a result of encountering unconsolidated materials with increasing moisture content.

#### 4.4.3 Soil Gas Data

Soil gas points were installed throughout the site from the peninsula north of the Sharon Oil fuel storage area to the southernmost portion of the site along the access road leading to the drum disposal area. The sampling procedures employed for the soil gas survey are described in Section 3.4. The survey results generally indicate that VOCs were present at varying concentrations in the soil gas at a number of locations (Ref. 3). Results of the survey are summarized in Table 4-2 and areas of identified volatile organic contamination are shown in Figure 4-2.

The greatest concentration of contaminants was detected in samples obtained from the northeastern sector of the site in the area between the helipad and the Sharon Oil enclosure.



**TABLE 4-2** 


# **SOIL GAS DATA SUMMARY (NOVEMBER 1991)**

NYSDEC I.D. No. 314006 Old Amenia Landfill

PARAMETER	SG-1	SG-2	SG-3	8G-4	8G-5	SG-8	SG-7	8G-8	5G-9	SG-10	5G-11	8G-12
VOLATILE ORGANICS (µ	g/m³)			ı			1		,	14	al. 1	ı
Vinyl chloride	8,400	ND	ND	ND	ND	ND	<b>★</b> ************************************	3,100	ND	ND :	₩ ND	ND
Benzene I	1,500	4,800	ND	ND	ND	300	F • 1	4,900	ND:	5,600	2,200	ND
PCE	27,000	1,300	ND .	ND	ND	ND	•	<sup>2</sup> ND <sup>4</sup>	ND"	ND :	排 ND	ND
Toluene	BDL	33,000	ND :	ND	ND	1,400	i trak	3,300	5,400	15,000	<b>3,700</b>	2,000
Ethylbenzene	20,000	12,000	ND	ND	ND .	6,700	• 4	7,900	· ND	7,600	27,000	ND
m-Xylene	71,000	18,000	ND	ND .	ND	11,000	• 37	15,000	· ND (	7,600	<b>19,000</b>	ND
o,p-Xylene	41,000	15,000	ND	ND :	, ND	7,600	e • € 80	19,000	· ND	6,200	୍ବ 23,000	ND
Methylene chloride	ND	ND	ND	ND	ND	. ₹ND	•	ND.		ND :	ND,	ND
1,1,1-Trichloroethane	ND	ND	ND	ND .	ND	ND	<b>★</b> 178	" ND"	, ND	ND	ND ND	ND
TCE/	ND	ND	ND	ND :	ND.	ND	•,	r ND :	ND	ND.	∰ ND	) ND
cis/trans-1,2-Dichloroethe	1,000	ND -	ND	ND√	ND	ND	•	ND	ND;	ND	ND ND	ND

	PARAMETER	5G-13	SG-14	8G-15	SG-16	8G-17	8G-18	8G-19	SG-20	8G-21	SG-22	80-23	SG-24
	VOLATILE ORGANICS (µ	g/m³)		. They	11 11		tit Ge	Ja - Salaha	general state		HO War and	la l	
, .	Vinyl chloride	ND	340,000	6,000	ND	ND	1,700	17,000				28,000	21,000
1.	Benzene	ND	38,000	9,700	ND	ND	8,900	33,000	ND	700	4,200	30,000	2,300
1	PCE	ND	79,000	ND -	ND	ND	ND	ND	ND	' ND	13,000	ND .	.↓ ND
	Toluene	1,300	1,700,000	8,800	1,600	1,000	5,300	26,000	400	1,200		25,000	2,100
1	Ethylbenzene	ND	560,000	11,000	, ND	, ND	46,000		ND :	2,600	16,000	35,000	ND
	m-Xylene	ND -	1,100,000	16,000	' ND	ND	72,000		, ND	6,100	12,000	68,000	
	o,p-Xylene	ND .	730,000	17,000	ND .	ND ·	55,000	42,000	ND.	ND	20,000	46,000	
1 .	Methylene chloride	ND	6,300	, ND	ND .	ND	ND	ND	ND	ii ND ,	Present of	ND	ND
	1,1,1-Trichloroethane	ND .	14,000	ND	ND *	ND	ND	ND	ND	ND	ND	ND	ND
	TCE	ND	170,000	ND	- ND	ND :	ND "	ND	ND	ND /	ND .	ND	ND
	cis/trans-1,2-Dichloroethe	ND	440,000	ND a	ND	ND	ND	67,000	. ND	ND	8,500	ND	2,500
1 .	1,1-Dichloroethene	ND	3,400	' ND	ND	ND :	ND	ND,	ND	ND	ND	ND	ND
Ì	1,1-Dichloroethane	ND	5,700	ND	ND 1	ND	ND	ND	ND	ND	ND :	ND	ND
	2-Butanone	ND	1,100	ND	ND	ND -	ND	ND:	ND	ND	ND	ND	ND

Not run, water encountered; no sample was obtained.
 ND - Not detected at analytical detection limit (Ref. 3).
 BD - Below detection limit



Ten soil gas sampling points were installed in this area, which was approximately 100 to 150 ft in diameter. Soil gas samples collected from nine of these 10 locations contained vinyl chloride in concentrations ranging from 1700 to 340,000  $\mu$ g/m³. Benzene, toluene, ethylbenzene, and xylene compounds (BTEX) were detected in nearly every sample from this area. Concentrations of the BTEX compounds varied between 300 and 1,7000,000  $\mu$ g/m³. Tetrachloroethylene (PCE) was identified in four closely grouped samples in this area, with concentrations of 1300 to 79,000  $\mu$ g/m³. Methylene chloride, 1,1,1-trichloroethane, and trichloroethylene were identified at a single location in this area at concentrations of 6300, 14,000, and 170,000  $\mu$ g/m³, respectively.

Five other areas on the property, primarily along the western side of the site, were also investigated. The first area is the peninsula north of the Sharon Oil enclosure, where only one point was installed (SG-20); 400 µg/m³ of toluene was detected in the sample. As toluene is a common component of petroleum products, its presence in this area is most likely due to its proximity to the fuel storage tanks rather than to underlying VOC contamination. Samples SG-3 through -6 were grouped in an area on the western side of the site approximately halfway from the northern end. The ground surface in this area was characterized by a moderate depression that showed evidence of possible periods when standing water may have been present. Moderate concentrations of the BTEX compounds were detected in sample SG-6 only.

Five soil gas points were installed on top of the rise in the southwestern portion of the central site area. This location was marked by a very pronounced depression with definite signs of recent stagnant water. Sample point SG-7, installed at the bottom of the depression, contained water and therefore could not be sampled. Three of the remaining four points showed moderate concentrations of BTEX compounds. Sample SG-8 also contained 3100  $\mu g/m^3$  of vinyl chloride.

Two soil gas points were located in the scrap metal disposal area and at the drum burial location at the southern end of the site. Low concentrations of toluene were detected in all four of these samples. No other VOCs were present above the detection limits in these samples.

## 4.4.4 Surface Soil Data - Mobile Laboratory

Twenty soil samples were collected at the locations shown on Figure 3-3 and analyzed for PCBs-by-Tetra•K Testing using the mobile laboratory. In addition, the 10 samples with the highest detected PCB concentrations were analyzed by the mobile laboratory for TCL VOCs. The chemical data obtained for these soil samples are summarized in Table 4-3 (Ref. 3).

4.4.4.1 Volatile Organic Compounds. Of the 10 surface soil samples analyzed at the site for VOCs, only one showed evidence of VOC contamination. Ethylbenzene was detected at a concentration of 0.22 mg/kg in sample SS-5. All other VOCs tested for in the analysis were below detection limits in this sample.

4.4.4.2 PCBs. PCBs were detected in 15 of the 20 surface soil samples collected at the site and analyzed by the mobile laboratory. Aroclor 1248 was the PCB identified in 13 of the samples; the remaining two samples contained Aroclor 1254. The PCB concentrations detected ranged from 2.3 to 250 ppm; only one sample contained a PCB concentration of greater than 50 ppm.

## 4.4.5 Surface Soil Data - Fixed Laboratory

Surface soil samples for analysis in a fixed analytical laboratory were collected at the four locations shown on Figure 3-3. Sampling was conducted as described in Section 3.5.1. The chemical data for these samples are summarized in Table 4-4 and are discussed below (Ref. 19). The validation and usability assessment for all data from the fixed laboratory is discussed in the Data Usability Summary (Ref. 22) based on the Data Validation Report (Ref. 23).

4.4.5.1 Volatile Organic Compounds. The surface soil samples were analyzed using EPA Method 624. All samples collected contained low levels of methylene chloride; however, methylene chloride was also found in the associated method and trip blanks, indicating that it may have been the result of laboratory contamination rather than actual site contamination. 1,1,1-Trichloroethane was detected in only one sample (AMSS-20) at a level of 0.006 mg/kg,



**TABLE 4-3** 

# SURFACE SOIL FIELD DATA SUMMARY (NOVEMBER 1991) Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER SS:1A SS:1B BS-2A	98-2B 98-3 89-4 98-5 89-6 69-7 89-8
VOLATILE ORGANICS (mg/kg) Ethylbenzene ND NR ND  PCBs (mg/kg) Aroclor 1248 25 ND 12 Aroclor 1254 ND ND	ND NR ND 0.220 ND NR NR 250 ND 15 38 42 8.0 5.0 ND ND ND ND ND ND ND

PARAMETER	18 AE-83	S-9B SS-	10 SS-11A S	95-11B 95-	12 59-13 9514	8816 9816
VOLATILE ORGANICS		NR NE	D NR	NR N	R NR NR	ND ND
PCBs (mg/kg)	25	<b>6.</b> 0 10	) 4.5	ND N	D ND ND	8.2
Aroclor 1248 Aroclor 1254	" "	4.2 NI			D ND ND	ND ND

ND - Not detected at analytical detection limit (Ref. 19). NR - Not run.


TABLE 4-4 (Page 1 of 5)

## **SURFACE SOIL DATA SUMMARY (NOVEMBER 1991)** Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER	AMS8-17	AMSS-18	AMSS-19 A	RE MSS-19
VOLATILE ORGANICS (mg/kg) Methylene chloride	0.011 b	0.015 b	0.016 b	NR
Tentatively Identified Compounds	ND	ND	ND	NR
SEMIVOLATILE ORGANICS (mg/kg) Benzoic acid Di-n-butylphthalate Butylbenzylphthalate bis(2-Ethylhexyl)phthalate	0.027 J 0.370 0.010 J 0.100 J	ND 0.140 J ND 0.260 J	NU NU NU NU	NU NU NU NU
Tentatively Identified Compounds Trichloro biphenyl Isomer Tetrachloro biphenyl Isomer Pentachloro biphenyl Isomer Hexachloro biphenyl Isomer Unknown Unknown + hexachloro biphenyl Unknown aromatic Hexadecanoic acid	3.740 (3) j 13.440 (10) j 6.910 (6) j 0.750 j ND ND ND ND	0.260 j 0.200 j 0.350 (2) j ND 1.170 (3) j 0.180 j ND ND	NU NU NU NU NU NU NU NU	NU NU NU NU NU NU NU

Number of compounds in total.
 Found in associated blanks.
 Estimated concentration; compound present below quantitation limit.
 Not detected at analytical detection limit (Ref. 19).

NR - Not run.
NU - Not usable; see Appendix A for explanation.
RE - Reextracted analysis.



# **SURFACE SOIL DATA SUMMARY (NOVEMBER 1991)** Old Amenia Landfill NYSDEC I.D. No. 314006

VOLATILE ORGANICS (mg/kg)	The state of the s		
Methylene chloride	0.019 b	0.019 b	0.019 b
1.1.1-Trichloroethane	0.004 J	0.004 J	0.006 J
este a la companya de		i . Taşır .	بالمنافرة في المنافرة
SEMIVOLATILE ORGANICS (mg/kg)			
Benzoic acid	0.018 j	0.026 j	0.054 b
Di-n-butylphthalate	0.240 j	0.280 j	0.160 j
bis(2-Ethylhexyl)phthalate	0.041 j	0.050 j	4.100
Commence of the property of the	1		2. 域的
Tentatively Identified Compounds	ALD AND	No.	2 290 (7) 1
Unknown	NR NR	NR (III	2.380 (7) j 1.040 (3) j
Unknown aromatic	NR NR	NR NR	0.450 j
Unknown acid Unknown alkane	NR NR	NR	3.050 (4)

MS - Matrix spike.

NR - Not run.

MSD - Matrix spike duplicate.

Number of compounds in total.
 Found in associated blanks.
 Estimated concentration; compound present below quantitation limit.

**TABLE 4-4 (Page 3 of 5)** 

## **SURFACE SOIL DATA SUMMARY (NOVEMBER 1991)** Old Amenia Landfill NYSDEC I.D. No. 314006

MS MSD AMSS-18 AMSS-19 AMSS-19 AMSS-19 AMSS-20 AMSS-17 **PARAMETER** PESTICIDES/PCBs (mg/kg) ND 0.026 0.030 ND ND ND gamma-BHC (lindane) 0.028 0.032 ND ND ND ND Heptachlor 0.026 0.030 ND ND ND ND Aldrin 0.083 ND 0.068 ND ND Dieldrin ND ND 0.064 0.077 ND ND ND **Endrin** 0.170 ND ND ND ND ND Endosulfan sulfate ND : ND 0.063 0.074 ND ND 4,4'-DDT ND 0.120 4.600 d 0.140 ND 48.000 d Aroclor 1248

- Concentration recovered from diluted sample (Ref. 19).
- Not detected at analytical detection limit (Ref. 19).

MS - Matrix spike.
MSD - Matrix spike duplicate.



TABLE 4-4 (Page 4 of 5)

# **SURFACE SOIL DATA SUMMARY (NOVEMBER 1991**

Old Amenia Landfill NYSDEC I.D. No. 314006

DADAMETER	ANOC 47	AMSS-18	AMSS-19	DUP AMSS-19		NATIVE SOIL CONCENTRATIONS TYPICAL RANGE (n)
PARAMETER	AMSS-17	AM38-18	AMISSETS	AMSS-13	AMB3420	TTPICAL PANGE (II)
METALS (mg/k	(a)			্ৰান্তাৰ্থ - ১		
Aluminum	11,200	13,400	17,900	17,051	23,100	10,000 - 300,000
Antimony	9.1 B	11.8 B	15.5	13.3 B	19.1	0.6 - 10
Arsenic	6.7 SA R	5.8 SA R	8.3 SA R	5.0 R	8.2 SA R	1.0 - 40
Barium	39.4 B	54.6	45.8	43.5 B	68.7	100 - 3,500
Beryllium	0.56 B	0.45 B	0.45 B	0.56 B	1.0 B	0.1 - 40
Cadmlum	ND	ND	ND	ND	ND	0.01 - 7.0
Calcium	32,500	25,400	5,250	5,330	715 B	100 - 400,000
Chromium	13.2	16.1	19.6	17.9	59.6	5.0 - 3,000
Cobalt	16.5	19.2	23.4	20.6	18.9	1,0 - 40
Copper	35.7 E	35.3 E	32.8 E	30.1	62.6 E	2.0 - 100
Iron	34,800	40,300	38,500	39,000	41,700	7,000 - 550,000
Lead	60.6	91.1	38.6	37.6	164	2.0 - 200
Magnesium	18,700	20,400	12,700	11,400	8,400	600 + 6,000
Manganese	971 R	1,210 R	1,300 R	1,000 R	950 R	100 - 4,000
Mercury	ND	ND	ND	ND	ND	0.01 - 0.08
Nickel	41.6	33.9	39.3	40.3	41.6	5.0 - 1,000
Potassium	1,360	1,250	2,070	2,010	1,270 B	400 = 30,000
Selenium	ND N W	ND N W	ND N W	ND	ND N	0.1 - 2.0
Silver	ND N	ND N	ND N	ND	ND N	0.1 - 5.0
Sodium	ND	ND 🐇	ND ·	ND	→ ND	750 - 7,500
Thallium	ND N W	ND N W	ND N W	ND	ND N W	0.1 -0.8 (q)
Vanadium	17.0	18.2	27.5	25.5	33.5	20 - 500
Zinc	137 E	204 E	93.7 E	86.7	119 E	10 - 300
Cyanide	90.0 N d	123,1 N d	2.8 N	2.8	1.5 N	•

<sup>(</sup>n) - Ref. 20.

<sup>-</sup> Ref. 21,

<sup>Ref. 21.
Concentration recovered from diluted sample (Ref. 19).
Value is less than the contract-required detection limit but greater than the instrument detection limit.
Indicates a high percent difference on serial dilution.
Spiked sample recovery is not within control limits.</sup> 

R - Duplicate analysis not within control limits.
 W - Post-digestion spike out of control limits; sample absorbance is less than 50% of spike absorbance.
 ND - Not detected at analytical detection limit (Ref. 19).

<sup>-</sup> Value determined by the method of standard addition.

DUP - Duplicate sample analysis

TABLE 4-4 (Page 5 of 5)

## SURFACE SOIL DATA SUMMARY (NOVEMBER 1991)

Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER	AMSS-17	AMSS-18	AMSS-1,9	MS AMSS-18	MSD AMSS-19	AMS9-20	HAZARDOUS CRITERIA AND EP TOX STANDARDS
EP TOX ORGANICS (mg/l)		:	;	x v z	1 4.11	No.	
Endrin	<0.01	<0.01	<0.01	NR	NR:	<0.01	0.02
Lindane	<0.01	<0.01	<0.01	NR	NR	<0.01 👈	0.4
Methoxychlor	<1.0	· <1.0 ,	<1.0	, NR	NR	<b>&gt; &lt;1.0</b>	10.0
Toxaphene	<0.01	<0.01	<0.01	NR	NR	<0.01 (*)	0.5
2,4-D	<1.0	<1.0	NU	NR	NR	<1.0	10.0
2,4,5-TP3 (Silvex)	<0.1	<0.1	NU	NR	NR	<0.1	1.0
EP TOX METALS (mg/l)		•		• • • •	,		
Arsenic	ND	ND	ND	NA	ND	ND	5.0
Barium	0.176B	0.218 B	0.0664 B	NA .	0.0664 B	0.401 B	100
Cadmium	ND	: ND	ND	NA .	ND	ND	1.0
Chromium	ND	ND	ND	NA	ND	ND 🗟	5.0
Lead	0.022 B	ND	ND -	NA	ND	ND	5.0
Mercury	ND	ND	ND	NA	ND	ND,	0.2
Selenium	ND	<sup>'</sup> ND	ND	NA	ND	ND !	1.0
Silver	ND N	, ND N	ND N	NA	ND N	ND N	5.0
HAZARDOUS CHARACTER	ISTICS				j		
Corrosivity (inches/year)	<0.01	<0.01	<0.01	NR.	NR	<0.01	0.25+
Flash point	>212	>212	>212	NR	NR NR	>212	
Reactivity to cyanide (ppm)	<1	<1	<1	NR	NR	<1	250
Reactivity to sulfide (ppm)	<1	<1	<1	NR	NR	<1	500

<sup>The rate of corrosivity of steel at 131°F as determined by the NACE test.

Value is less than the contract-required detection limit but greater than the instrument detection limit.

Note that the same is a second of the same is seen as the same</sup> 

MS - Matrix spike.

NA - Not applicable.
ND - Not detected at analytical detection limit (Ref. 19).

NR - Not run.

NU - Not usable; see Appendix A for explanation.

MSD - Matrix spike duplicate.

which is below the contract-required quantitation limit (CRQL). No other TCL VOCs or tentatively identified compounds (TICs) were detected in the soil samples collected at the site.

4.4.5.2 Semivolatile Organic Compounds. Several phthalate acid ester (PAE) compounds were identified in the soil samples. Di-n-butylphthalate was detected in AMSS-17 at a concentration of 0.37 mg/kg. The concentrations of this compound in the other three samples collected were estimated at 0.14 to 0.28 mg/kg, below the CRQL. Butylbenzylphthalate, detected in only one sample (AMSS-17), was found at a concentration below the CRQL. All four soil samples contained detectable concentrations of bis(2-ethylhexyl)phthalate; however, only one sample (AMSS-20) had a concentration of bis(2-ethylhexyl)phthalate above the CRQL.

TICs were most prevalent in sample AMSS-17. This sample contained an estimated concentration of 13.44 mg/kg of tetrachloro-biphenyl isomers as well as estimated concentrations of trichloro- (3.740 mg/kg), pentachloro- (6.910 mg/kg), and hexachloro- (0.75 mg/kg) biphenyl isomer compounds. Sample AMSS-18 also contained concentrations of these chlorinated biphenyls below the CRQL, except for the hexachloro-biphenyl isomer, which was not detected. Several unknown semivolatile organics were present in three of the four soil samples (AMSS-18, -19, and -20) at levels below the CRQL. Sample AMSS-20 contained three unknown aromatic compounds at an estimated total concentration of 1.04 mg/kg as well as an unknown acid compound and four unknown alkane compounds at estimated concentrations of 0.45 and 3.05 mg/kg, respectively, all below the CRQL.

4.4.5.3 Pesticides/PCBs. No pesticides were identified in any of the soil samples from the site with the exception of 0.17 mg/kg of endosulfan sulfate in sample AMSS-20. Aroclor 1248 was detected in all four soil samples at concentrations ranging from 0.12 to 48.0 mg/kg. However, the Aroclor 1248 concentrations in samples AMSS-17 and -18 (48.0 and 4.6 mg/kg, respectively) were obtained from the analysis of samples that were diluted 50:1 and 10:1, respectively.

4.4.5.4 EP Toxicity. Extraction procedure (EP) toxicity analyses for both metals and organics were performed on all four soil samples. The results indicated that the EP toxicity

concentrations for all organics tested were below compound detection limits. For metals, none of the samples had concentrations above the maximum allowable levels, i.e., 100 times the drinking water standard for that particular metal. The only metals detected in the EP toxicity test were present below the contract-required detection limit; barium was identified in all four samples and lead was present in sample AMSS-17. Silver was not detected in any of the samples; however, the matrix spike (MS) sample recovery for silver was 56%, indicating that the results may be biased slightly low.

4.4.5.5 Hazardous Characteristics. In addition to the chemical analyses, analyses for hazardous characteristics, including corrosivity, ignitability, reactivity to cyanide, and reactivity to sulfide, were conducted on the samples. According to the tests, none of the samples exhibited hazardous characteristics. Corrosivity and reactivity to cyanide and sulfide were below measurable levels for all four samples. The flash point of each of the four samples was greater than 212°F.

4.4.5.6 Metals. Metals concentrations were compared with typical concentration ranges for native soils. Soil samples AMSS-18, -19, and -20 contained slightly elevated levels of antimony; the antimony concentration determined for sample AMSS-18 was below the contract-required detection limit. All four samples had elevated levels of magnesium, with concentrations ranging from 8400 mg/kg to 20,400 mg/kg. Typical native soil concentrations for magnesium range from 600 to 6000 mg/kg. All other metals detected were within the typical concentration ranges for native soils.

#### 4.4.6 Surface Water Data

Five surface water samples were collected at the locations shown on Figure 3-3. All sampling locations and methods were discussed with and approved by NYSDEC personnel before sampling proceeded, as discussed in Section 3.5.2. The samples were analyzed for VOCs, semivolatile organics, pesticides, PCBs, metals, cyanide, and conventional parameters, which included pH, specific conductance, chemical oxygen demand (COD), total dissolved solids (TDS), and total suspended solids (TSS). Five additional surface water samples were collected at each sampling location and submitted to Aquatec for low-level PCB analyses.

Table 4-5 summarizes the chemical data for the surface water samples obtained from the Old Amenia Landfill site (Ref. 19). The surface water samples were collected from the pond and stream located in the wetland area adjacent to the site, which has been designated as a Class C surface water body by NYSDEC. The standards applicable to Class C surface water bodies are included in Table 4-5, and the analytical data obtained were compared with these standards.

4.4.6.1 Volatile Organic Compounds. Methylene chloride was detected at low levels, i.e., below the CRQL, in three of the water samples; it was also detected in an associated blank, however, and is therefore attributed to laboratory contamination. Acetone was identified in three of the samples and in the associated blanks. No TICs were detected.

4.4.6.2 Semivolatile Organic Compounds. The only TCL semivolatile organics identified in the surface water samples were n-nitrosodiphenylamine and bis(2-ethylhexyl)phthalate. The former was detected in three samples at levels below the CRQL; however, it was also detected in the method blank, indicating laboratory contamination. bis(2-Ethylhexyl)phthalate was detected in only one sample, at a concentration of 1 µg/l, which is below the CRQL bis-(2-Ethylhexyl)phthalate is a known laboratory contaminant and is not considered to be the result of environmental contamination at the site. Several unknown TICs were detected in samples AMSW-01, -03, and -05 at concentrations below the CRQL. However, the field blank associated with these samples also contained low levels (22.1 µg/l) of unknown TICs, indicating that they are not the result of environmental contamination at the site.

4.4.6.3 Pesticides/PCBs. No pesticides were detected in any of the surface water samples collected from the wetlands area adjacent to the site. PCBs were not detected in the samples analyzed by Nytest (detection limits of 0.5 µg/l for Aroclor 1254 and 1.0 µg/l for Aroclor 1260). Aquatec performed low-level PCB analyses of the surface water samples (detection limit is 0.05 µg/l for Aroclor 1242): a concentration of 0.06 µg/l was detected in sample AMSW-03; PCBs were not detected in the remainder of the samples.

4.4.6.4 Metals. Iron levels in all surface water samples except AMSW-04 exceeded the NYSDEC standard of 300 µg/l for Class C surface waters. Values ranged from 363 to 776

**TABLE 4-5 (Page 1 of 3)** 

# SURFACE WATER DATA SUMMARY (NOVEMBER 1991) Old Amenia Landfill NYSDEC I.D. No. 314006

						MS	MSD	FIELD	TRIP	STAND	W CLASS C ARDS (h)
PARAMETER	AMSW-0	AMSW-02	AMSW-03	AMSW-94	AMBW-06	AMSW-08	AMSW-08	BLANK	BLANK	AQUATIC	HUMAN
VOLATILE ORGANICS (µg/l)			,				w		: ` {,		
Methylene chloride	ND	3 b j	26]	ND	2 b j	4 b j	∍ <b>6</b> b	ND -	2]	NS	NS
Acetone	13 b	11 b	ND	ND	10 Ь	: 14 b	22 b	ND :	ND	NS	NS
Tentatively Identified							1 1				
Compounds	ND	ND '	ND	ND	ND	ND	ND	ND	ND		
SEMIVOLATILE ORGANICS (µg/	1)				1				, e		
n-Nitrosodiphenylamine(¶)	2 b j	2 b j	2 b J	ND	ND	, ND	ND	ND	NR	NB .	· NB
bls(2-Ethylhexyl)phthalate	ND -	1 ]	ND	ND	ND	ND	ND	ND .	NR	0,8	N9 ?
Benzo(b)fluoranthene	ND	ND	ND	ND#	ND#	ND	ND	ND #	NR	NS.	N9
Benzo(k)fluoranthene	ND	ND	ND	ND#	ND#	ND	ND	ND#	NR	NS	NS:
Benzo(a)pyrene	ND	· ND	ND	ND#	ND#	ND	ND	ND#	NR -	0.0012 GV	
Indeno(1,2,3-cd)pyrene	ND	ND	ND	· ND#	ND#	ND	ND	ND #	NR	NS.	NS
Dibenz(a,h)anthracene	ND	ND	ND	ND#	ND#	ND	ND	ND#	NR	NS	NS
Benzo(g,h,i)perylene	ND	· ND	- ND	ND#	ND#	ND	ND	ND#	NR	NS	NS
Tentatively Identified Compound	ds						+ 1		•		
Unknown	53.5 (2) ]	ND	29 (2) ]	ND	8.5 J	NR	NR	22.1 (2) }	NR		•
PESTICIDES/PCBs' (µg/l)	ND	ND	ND	. ND	ND	ND	ND	ND	NR		•
CONVENTIONALS:		•							1.		
pH (standard units)	7.62	7.71	7,67	7.78	7.71	NR	NR	NR	NR	8,5 + 8.5	8,5 • 8.5
Specific conductance (µmhos/cm)	420	403	391	. 377	396	NR	NR	NR	NR	, NS	. N8
Chemical oxygen demand (mg/l)	17*	. 73	<3	17*	17*	NR	NR	NR	NR	. NB	** N8
Total dissolved solids (mg/l)	243	255	235	271	250	NR	NR NR	NR	NR	NB	N8
Total suspended solids (mg/l)	5	9	17	. 5	<b>4</b> ; .	NR	NR NR	NR	NR	NS .	NS

- Concentrations may exceed detection level;
- Concentrations may exceed detection level; see Appendix A for complete discussion.
  COD values should be considered estimates (biased high) as the absorbances for these values correlate with the 10 ppm standard.
  Cannot be separated from diphenylamine.
  Number of compounds in total.
  Hardness: 215 mg equivalent CaCO3/I.
  Niytest's analytical detection limits for PCB were 0.5 and 1.0 µg/I (Aroctors 1254 and 1260, respectively).

- b Found in associated blanks,
   j Estimated concentration; compound present below quantitation limit.
- MS Matrix spike.
  ND Not detected at analytical detection limit (Ref. 19).
- NR Not run. NS No standard,
- GV Guldance value,
- MSD Matrix spike duplicate.

TABLE 4-5 (Page 2 of 3)

# SURFACE WATER DATA SUMMARY (NOVEMBER 1991) Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER	AMSW-01	AMSW-02	AMSW-03	AMSW-04	AMSW-08	DUP AMSW-86	FIELD BLANK	NYSDEC SWICLASS ( STANDARDS (h)
	,							
METALS (µg/l) Aluminum	78.2 B	86.2 B	57.4 B	ND	ND	45.6 B	ND	100(i)
	76.2 B ND	ND	ND	ND	ND :	ND	ND	NS
Antimony Arsenic	ND W	ND .	ND	ND	ND ND	ND	ND	190
Barlum	ND VV	ND	ND .	ND	ND	ND ND	ND	N8
Beryllium	ND	ND	ND	ND	ND	ND	ND	1100
Cadmlum	ND	ND	ND	ND	ND	ND	ND	2.07
Calcium	54,100	53,400	53,000	52,800	53,200	53.800	ND	NS
Chromlum	ND	ND ND	ND	ND	ND	ND	ND	387
Cobalt	ND	ND -	ND	ND	ND	ND	ND	50
Copper	ND	ND	2.8 B	ND	2.8 B	ND	ND	22.7
Iron	776	503	363	290	400	409	ND .	300
Lead	ND	ND	ND	ND	ND	ND	ND :	8.48
Magneslum	20,100	19,900	19.800	19,700	19,700	20,000	ND	NS
Manganese	134	86.7	101	62.7	81.2	81.6	ND	NS
Mercury	0.26	ND	ND	ND	ND	ND	ND	0.20 GV
Nickel	ND	ND ·	ND	A ND	ND	ND	, ND &	171
Potassium	3,180 B	3,140 B	3,290 B	2,650 B	2,570 B	2.530 B	ND	NS:
Selenium	ND	ND	ND	ND	ND	ND	ND	1.0
Silver	ND	ND	ND	ND	ND ND	ND .	ND 1	0,1 (1)
Sodium	5,780	5,250	5,190	4,910 B	5,060	5,030	ND	NS
Thallium	ND W	ND W	ND W	ND W	ND W	ND A	ND 1	80
Vanadium	ND	ND	ND	ND	ND N	ND /	ND 1	14
Zinc	4.5 B	8.4 B	ND	ND	ND	ND	ND	20
Cyanide	ND	ND	ND	ND	ND	ND	ND	5.2 (f)

<sup>-</sup> Free cyanide, sum of HCN + CNT.
- Hardness: 215 mg equivalent CaCO3/i.

Value is less than the contract-required detection limit but greater than the instrument detection limit.

W - Post-digestion spike out of control limits; sample absorbance is less than 50% of spike absorbance.

GV - Guidance value.

ND - Not detected at analytical detection limit (Ref. 19).

NS - No standard.

DUP - Duplicate sample analysis,

## **TABLE 4-5 (Page 3 of 3)**

## SURFACE WATER DATA SUMMARY (NOVEMBER 1991) AQUATEC DATA RESULTS Old Amenia Landfill NYSDEC I.D. No. 314006

				MS	NYSDEC SW CLASS C MSD STANDARDS (h)
PARAMETER AL	MA 10-WEN	SW-02 AMSW-0:	3 AMSW-04	AMSW-05 AMSW-05	AMBW-06 AQUATIC HUMAN
LOW-LEVEL PCBs (µg/l) Aroclor 1242	ND	ND 0.060	ND	ND ND	- ND 0,001 N9

(h) - Hardness: 215 mg equivalent CaCO3/l.
 MS - Matrix spike.
 ND - Not detected at analytical detection limit (Aquatec's low-level PCB analytical detection limit was 0.05 μg/l).
 NS - No standard.
 MSD - Matrix spike duplicate.

µg1. No other metals were detected in the surface water samples at levels that exceeded the applicable NYSDEC standards.

#### 4.4.7 Sediment Data

Sediment samples were collected at locations corresponding to each of the five surface water samples (Figure 3-4). These samples were analyzed for VOCs, semivolatile organics, metals, cyanide, pesticides, and PCBs. Table 4-6 summarizes the analytical data obtained for the sediment samples (Ref. 19).

4.4.7.1 Volatile Organic Compounds. Methylene chloride was found at low concentrations in all of the sediment samples collected. However, as it was also detected in the trip and method blanks associated with these samples, this compound was most likely introduced through laboratory contamination and is not related to site contamination. Acetone was identified in one sample, SD-05, at a concentration of 0.15 mg/kg. Although this compound was not detected in the field, trip, or method blanks, its presence is probably due to laboratory contamination as acetone is a common laboratory contaminant. There were no TICs detected in any of the sediment samples.

4.4.7.2 Semivolatile Organic Compounds. Nitrobenzene was detected in only one sample, SD-03, at a concentration of 4500 mg/kg. Although semivolatile organic compounds were not detected in any of the other sediment samples, actual concentrations of several semivolatile compounds may be biased low due to poor (low) internal standard recoveries for these compounds. Low levels of these contaminants may have been present in the samples analyzed, but none were detected.

All five sediment samples contained low levels (below the CRQL) of unknown TICs; however, several of these compounds are suspected aldol condensation products. Thus, the source of these compounds is most likely laboratory contamination rather than actual site contamination. The only other TICs detected were found in sample SD-03, which had 20 mg/kg of a chloro-biphenyl isomer and 7.4 mg/kg of two dichloro-biphenyl isomers.

TABLE 4-6 (Page 1 of 2)

# **SEDIMENT DATA SUMMARY (NOVEMBER 1991)**

Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER	SD-01 .	SD-02	SD-03	SD-04	3D-05	M8 3D-05	MSD SD-05
VOLATILE ORGANICS (mg/kg)							
Methylene chloride	0.029 b	0.051 b	0.022 b	0.089 b	0.026 b	0.034 b	0.028 b
Acetone	ND	ND	ND	ND	0.150	0.200	0.120
Tentatively Identified Compo	ND	ND	ND	ND	ND .	NR	NR
SEMIVOLATILE ORGANICS (m	ng/kg)		The second second				
Nitrobenzene	ND	ND	4,500	ND	ND	ND	ND
Benzo(b)fluoranthene	ND#	ND#	ND#	ND# .	ND#	ND#	ND#
Benzo(k)fluoranthene	ND#	ND#	ND #	ND#	ND#	ND #	. ND#
Benzo(a)pyrene	ND#	ND#	ND#	ND#	ND#	ND#	ND#
Indeno(1,2,3-cd)pyrene	ND#	ND#	ND#	ND#	ND#	ND#	ND#
Dibenz(a,h)anthracene	ND#	ND#	, ND # 🧦	ND #	。◎ ND #为	ND#	: ND#
Benzo(g,h,i)perylene	ND#	ND#	ND#	ND#	ND#	ND#	ND#
Tentatively Identified Compou	nds	•,		· · · · · · · · · · · · · · · · · · ·			4
Unknown	54.0 J a	92.0 J a	32.0 j a 🗧	`150 J a	50.0 J a	NR :	NR
Unknown	9.4	54.0 (2) j	ND :	9.40 (2) j	3.20 (2) j	NR	. NR.
Chloro-biphenyl isomer	ND	ND	2.0 j	ND	ND	NR	NR
Dichloro-biphenyl isomer	ND	ND	7.4 (2) j	ND	ND	NR	NR
PESTICIDES/PCBs (mg/kg)			1 11 11 11 11 11 11 11 11 11 11 11 11 1				
Aroclor 1232	ND	ND	18.0	ND	ND	ND	ND
Aroclor 1248	0.510	1.80	5.20	ND .	$ND_{F_{i}}$	ND	ND

<sup>Concentrations may exceed detection level; see Appendix A for complete discussion.
Number of compounds in total.
Suspected aldoi condensation product.
Found in associated blanks.
Estimated concentration; compound present below quantitation limit.</sup> 

MS - Matrix spike.
ND - Not detected at analytical detection limit (Ref. 19).
NR - Not run.
MSD - Matrix spike duplicate.

# SEDIMENT DATA SUMMARY (NOVEMBER 1991) Old Amenia Landfill NYSDEC I.D. No. 314006

PARAMETER	SD-01	SD-02	SD-03	SD-04	9D-05	DUP SD-05
METALS (mg/kg) Aluminum Antimony Arsenic Barium Beryllium Cadmium Calcium Chromlum Cobalt Copper Iron Lead Magnesium Manganese Mercury Nickel Potassium Selenium Silver Sodium Thallium Vanadium Zinc Cyanide	10,800 48.4 8.4 N SA 74.8 B 3.6 ND 5,410 9.7 64.3 ND 128,000 23.4 SA 6,610 2,890 R ND N 144 1,640 B ND ND ND ND ND ND ND ND ND ND ND 17.3 B 347 ND N	22,600 24.5 B 8.2 N SA 118 B 2.2 B ND 20,100 25.6 38.5 79,500 A 9,930 1,170 N 88.5 9,930 R ND ND ND ND ND ND W 38.4 ND N	10,900 22.3 5.3 N 44.3 B 0.60 B 3.8 37,200 15.7 40.2 37,800 71,4 21,000 692 R ND N 43.8 1,180 B ND W ND ND W 17.8 253 ND N	8,900 969 R 5.4 N 81.8 2,890 B ND W ND	9,810 25,7 B 4,7 N SA 51,3 B 0,91 B ND 6,660 13,4 28,9 9,8 B 51,400 19,1 SA 5,280 1,320 R 1,320 R 1,320 R 1,320 R ND W ND W ND ND W 15.8 B 142 ND N	9,050 21.1 B 6.4 A 47.5 B 0.91 B ND 6,470 11.1 27.5 6.4 B 55,100 22.8 4,803 973 R 1.4 62.5 1,121 B ND ND ND ND 13.8 B 145 ND

- Value is less than the contract-required detection limit but greater than the instrument detection limit.
   Spiked sample recovery is not within control limits.
   Duplicate analysis not within control limits.
   Post-digestion spike out of control limits; sample absorbance is less than 50% of spike absorbance.

- ND Not detected at analytical detection limit (Ref. 19), SA Value determined by the method of standard addition.
- '- Duplicate sample analysis.

4.4.7.3 Pesticides/PCBs. Aroclor 1248 was detected in sediment samples SD-01, -02, and -03 at concentrations of 0.51, 1.8, and 5.2 mg/kg, respectively. In addition, Aroclor 1232 was identified in sample SD-03 at a concentration of 18.0 mg/kg. No other pesticides or PCBs were detected in the sediment samples.

4.4.7.4 Metals. A number of metals were detected in the sediment samples collected at the site. Native concentration ranges for metals in sediments are not available, and no standards applicable to sediments are currently available. Aluminum was present in all sediment samples at levels ranging from 9810 to 22,600 mg/kg. Antimony was detected from below the contract-required detection limit to 48.4 mg/kg. Arsenic was detected at concentrations of 4.7 to 16.7 mg/kg; however, the spiked sample recovery for these samples was not within control limits, indicating that these levels are estimated concentrations. A concentration of 3.6 mg/kg of beryllium was detected in sample SD-01; all other samples had beryllium concentrations lower than the contract-required detection limit. Only sample SD-03 contained cadmium, at a concentration of 3.8 mg/kg. Calcium was detected in the five samples at concentrations ranging from 5410 to 37,200 mg/kg. Chromium concentrations ranged from 9.7 to 25.9 mg/kg. Cobalt was present at levels from below the contract-required detection limit to 64.3 mg/kg.

Copper was detected in samples SD-02 and -03 at concentrations greater than the contract-required detection limit: 28.5 and 40.2 mg/kg, respectively. The iron levels in the sediment samples ranged from 37,800 to 128,000 mg/kg. Lead was also present in all five samples, at levels from 19.1 to 71.4 mg/kg. Manganese concentrations ranged from 692 to 2890 mg/kg. Mercury was detected in samples SD-04 and -05; however, the spiked sample recovery for these samples was not within control limits. All sediment samples contained nickel, at concentrations ranging from 43.8 to 144 mg/kg. Vanadium was present at concentrations above the contract-required detection limit in samples SD-02 and -03 only, with concentrations of 38.4 and 17.8 mg/kg, respectively. Zinc was present in all five samples at levels ranging from 142 to 347 mg/kg.

All other metals were present at levels below the contract-required detection limit or the instrument detection limit.

#### 4.5.1 Geophysics Survey -

Several conclusions may be drawn from the results of the magnetometry and electrical resistivity studies conducted at the site. The former landfill area appears to be located in the central portion of the site, excluding the peninsula north of the Sharon Oil fuel storage enclosure and the access road leading to the drum disposal area at the southern end of the site. The landfill contains a substantial amount of fill material that is magnetic. Materials located at depth within the former landfill area may consist of refuse, unconsolidated deposits saturated with lower conductive leachate, or unsaturated clay. Depth to groundwater may be greater than the level of the adjacent wetlands area; this would increase the conductivity, as was apparent in layer 3 of sounding location VES 4.

Several areas of the site exhibited magnetic field patterns indicative of large concentrations of buried metallic materials (Figure 4-1). As the information collected provides no depth or size correlation for these areas, it is difficult to identify those locations that may contain the largest amount of buried material. One magnetic anomaly spanned the site in a relatively wide swath between the helipad and the Sharon Oil enclosure, indicating that a relatively large amount of buried materials may be present in this area.

According to the geophysics survey results, bedrock is relatively shallow at the southwestern end of the site - approximately 15 ft below grade - and along the eastern portion of the landfill.

#### 4.5.2 Soil Gas Survey

The soil gas survey located three areas with substantial VOC contamination, as shown on Figure 4-2. When evaluated in conjunction with the geophysics survey data, the areas of identified VOC contamination appear to correlate well with the locations of suspect magnetic anomalies. Comparison of the geophysics and soil gas data indicates the presence of a

possible drum burial zone in the central site area between the helipad and the Sharon Oil enclosure, extending across the width of the site.

The existence of this zone is supported by aerial photographs of the site taken in April 1970 and April 1990 (Plate). The photos show the landfill as it appeared during the period of suspected industrial waste dumping and as it is now. In the earlier photo most of the site has been filled to approximately the present grade level, with the exception of a large area in the vicinity of the current Sharon Oil property. This portion of the site appears to be the active landfill area at the time. A comparison of shadows on the photo at the edge of the fill area with shadows of vehicles present at the site indicates that the face is approximately 10 to 20 ft high. Immediately south of the steep grade and active landfill area is a bermed area approximately 150 by 250 ft that appears to contain large quantities of organized, stacked drums. If in fact some or all of these drums were disposed of on-site, the most likely area would be in the active landfill portion apparent in the aerial photo, as the other portions of the site had already been brought to approximately the current grade level. The geophysics survey indicates that this area is the location of a very prominent magnetic anomaly. In addition, results of the soil gas survey have identified this portion of the site as an area of high VOC concentrations. Consequently, this location should be the focus of future site investigations, such as test pits or subsurface sampling.

#### 4.5.3 Surface Soils

Results of the mobile laboratory analyses conducted on the 20 surface soil samples confirm the presence of PCB contamination at the site. Fifteen of the 20 samples contained detectable concentrations of PCBs, with concentrations ranging from 2.3 to 250 mg/kg, substantially above the PCB standard of 50 ppm for toxic wastes as defined by the Toxic Substances Control Act (TSCA). The 250-ppm concentration was detected in sample SS-2B collected from the northwestern side of the site near the end of the Sharon Oil enclosure fence. This is near the location of a 1987 NUS Corporation sample that contained an Aroclor 1248 concentration of 170 ppm. Two other samples taken from the western bank of the landfill in this vicinity, SS-6 and -16, had PCB concentrations of 42 and 46 mg/kg, respectively. The remainder of the samples showing PCB contamination were collected on

the northern and central portions of the western bank of the site, with concentrations below 50 mg/kg. Results from samples analyzed by the mobile laboratory indicated that the PCB contamination did not appear to extend to the southern portion of the site along the access road leading to the drum disposal area.

The soil samples analyzed in the fixed laboratory did detect low levels of PCBs in the southern portion of the site. Sample AMSS-20, collected from the drum disposal area at the southwestern end of the access road, had 0.12 mg/kg of PCBs; sample AMSS-19, collected at the top of the rise in the southwestern portion of the central site area, contained 0.14 mg/kg. The other two soil samples collected for analysis in the fixed laboratory showed higher PCB concentrations. These samples were collected along the western bank of the site in the central and northern sections. The highest concentration detected by the fixed analytical laboratory was 48 mg/kg for sample AMSS-17, which was collected at the western end of the Sharon Oil enclosure fence in the area of the high PCB concentrations detected by the mobile laboratory.

Although these results confirm the presence of PCB contamination at the site, its extent and depth have not been defined. The range of PCB concentrations (5-250 ppm) detected and the widespread nature of the contamination indicate that it is most likely from PCB-contaminated oils spilled or disposed of at the site rather than from disposal of pure PCB product. Results of the literature search indicate that large quantities of what was reported to be cutting oil were handled at the site. The majority of the soil samples showing PCB contamination were collected along the western slope of the landfill; however, PCB contamination may exist in other areas of the site as well. In addition, all samples collected were surface soil samples from the first 6 in. of soil. Substantial PCB contamination may exist at greater depths.

Surface soil samples collected at the site did not show detectable levels of VOC contamination; however, the soil gas survey found moderate to high levels of VOCs present in the soil gas. These results may be explained by the high mobility of VOCs in soils. Volatile constituents in the surface soils are likely to have volatilized into the atmosphere or migrated to subsurface soils or groundwater. Thus, soil borings and/or groundwater

monitoring would be required to locate the source of the VOCs. The relatively high levels of VOCs detected in the soil gas indicate the likelihood of a substantial source of subsurface contamination.

#### 4.5.4 Surface Water/Sediment

Substantial volatile and semivolatile organic contamination was not detected in the surface water/sediment samples collected from the wetlands area adjacent to the site. Pesticide and metals contamination also did not appear to be significant in the surface water and sediments. PCBs, however, were detected in three of the sediment samples and in one surface water sample, indicating that PCBs are migrating from the site to the adjacent wetlands and have entered the surface water. Thus, PCB contamination does present a potential threat to aquatic life.

and the first of the second that he is a second that we have

#### 4.6 RECOMMENDATIONS

The results of this Phase II investigation of the Old Amenia Landfill site showed PCB contamination in 15 of 20 soil samples collected, at concentrations ranging from 2.3 to 250 mg/kg. In addition, PCB contamination was detected in three of five sediment samples and one of five surface water samples obtained from the wetlands area adjacent to the site. The New York State Division of Fish and Wildlife has concluded that these levels of PCBs indicate widespread contamination of significance to wildlife. Therefore, the Old Amenia Landfill has been classified as a Class 2 site (Ref. 24).

Based on the information obtained in this investigation, a remedial investigation (RI) of the Old Amenia Landfill is warranted. The goals of the RI should be to fully delineate the extent and magnitude of contamination present, assess the degree and rate of migration of contaminants from the site, and evaluate the threat posed to human health and the environment by the contamination. Activities to be conducted as part of the RI should include additional soil sampling, installation of test trenches, implementation of a groundwater monitoring program, and biomonitoring of aquatic species in the adjacent wetlands. These activities are described in greater detail in the following sections.

the state of the s

### 4.6.1 Soil Sampling


Additional soil sampling should be conducted to fully delineate the extent and magnitude of PCB contamination at the site. Samples should be collected in the areas of high concentrations of PCBs identified during the previous investigations. In addition, samples should be obtained from 6 to 8 ft deep to determine whether greater contamination exists beneath the surface. All PCB samples collected to date have been surface soil samples collected from 0 to 6 in PCB-contaminated materials may have been dumped onto soils that were later covered by a foot or more of clean fill; thus, greater PCB contamination may be encountered with depth at the site. Soil samples obtained from borings should be observed for oil stains; PCB analyses of those samples with visible signs of oil may confirm that the source of the PCBs was contaminated oil as opposed to pure PCB product. Subsurface soil sampling may also serve to locate the source of the VOC contamination identified in the soil gas samples obtained at the site.

#### 4.6.2 Test Trenches

Test trenches should be installed to locate buried drums, confirm the disposal of industrial wastes, and identify the source of VOC and PCB contamination at the site. Five preliminary test trench locations are proposed (Figure 4-3) based on an evaluation of the geophysics and soil gas data. Two test pits are recommended in the central site area between the helipad and the Sharon Oil enclosure as the largest identified magnetic anomaly was located in this area. The highest VOC concentrations detected in the soil gas were also obtained in this area, indicating that a contaminant source such as buried drums may be present at this location. One test pit is recommended for the base of the small rise on the southwestern side of the central site area, at the western end of the magnetic anomaly located in this area. Although no soil gas data were obtained for this immediate area, moderate concentrations of VOCs were detected in soil gas samples obtained at the top of the rise.

Two more test pits are recommended in the southern portion of the site. One trench should be located near the scrap metal disposal area at the northern end of the access road leading to the drum disposal area. The purpose would be to investigate the small magnetic anomaly

4-22




The test pits should be excavated to a maximum depth of 25 ft and continued horizontally as required to attempt to determine the number of buried drums existing at the site. Any drums or waste masses encountered will be sampled for full TCL organics and metals, full EP toxicity, reactivity, corrosivity, ignitability, and possibly TCLP. The trenches will then be backfilled and graded level after sampling. The results of the test trench investigation will be used to determine whether an interim remedial measure (IRM) should be performed at the site. The purpose of the IRM would be to excavate any buried drums on-site that are acting as contaminant sources and thereby eliminate the continued release of contaminants to the environment.

#### 4.6.3 Groundwater Monitoring

Implementation of a groundwater monitoring program is recommended to determine whether the contamination present at the site has impacted the underlying aquifer and whether contaminants are migrating from the site in the groundwater. In particular, the detection of relatively high levels of VOCs in the soil gas at the site indicates the potential for VOC contamination of the underlying aquifer. One upgradient well should be installed to provide representative background samples. A minimum of three downgradient wells should be installed to monitor groundwater flow as well as water quality in the underlying aquifer (Figure 4-4). The monitoring wells should be located based on the results of the Phase II investigation, including the geophysics survey and environmental sampling, and should be installed so as to provide pertinent data on site stratigraphy and groundwater regime. A site survey will also be necessary as part of the groundwater monitoring program.

Before any monitoring wells are installed, LMS recommends the installation of a geotechnical boring to identify the immediate site stratigraphy. The boring should be located in the vicinity of one of the downgradient monitoring wells and should be sampled continuously into the water table. Soil samples should be examined for physical characteristics, including color,



texture, grain size, angularity, relative moisture content, permeability, and depositional source. Also, each sample should be screened using an OVA and/or PID. Samples showing signs of contamination during field screening should be archived for possible chemical analysis. The boring should be advanced into the saturated zone until bedrock or impermeable strata are encountered or until a maximum depth of 80 ft is reached. It is estimated that groundwater may be encountered 20 to 30 ft below the landfill surface. This water may be related to a perched zone and, if an impermeable stratum exists below this water, it will be important to identify its limit. Bedrock is expected to be encountered at relatively shallow depths in certain areas at the site (south and southeast). Other site areas may contain a substantially thicker blanket of unconsolidated material.

If a less permeable layer is encountered, LMS recommends installing a screened monitoring well to that depth. If bedrock is encountered, the monitoring well should be installed as a screened sampling point at the borehole overburden interface. If neither an impermeable layer nor bedrock is encountered, the boring should be continued to 80 ft, where a solid PVC riser should be installed. A downhole conductivity probe (EM-39) should be used to determine the interval with the greatest conductivity change. The results will show the depth of the greatest concentration of conductive leachate.

and decomplished set the man

Following completion of the geophysics boring and analysis of the collected data, the actual depth at which the wells should be screened can be determined. Any remaining wells should be installed in a similar stratum. As stratigraphic conditions over a large distance may be dissimilar, it may be necessary to determine the depth in the field.

Recommended locations for three downgradient monitoring wells are along the expected downgradient side of the landfill (east). Although the overall groundwater flow pattern in this area is expected to be to the east, the elevated rise that has relatively shallow bedrock at the southern end of the site may induce a northerly component of flow off the slope. It may also be necessary to install a group of deeper wells to detect heavier compounds such as vinyl chloride.

There are several potential locations for the upgradient well. One is the central region of the swamp west of the site. Installation of a well at this location would need to be facilitated by a floating barge rig. If this is not feasible, an upgradient well located west of the site and wetlands area may be necessary. Although not an optimum location because of the overall distance between the wells, the well would provide background water quality samples.

the state of the company of the state of the

After completion, each well would be developed by pumping and surging or by the air-lift method. Following well development and subsequent sampling, each monitoring well would be slug tested to determine the horizontal hydraulic conductivity of the screened strata. If the monitoring wells are installed on the surface of unconsolidated bedding, which is considered to have greatly increased permeability from each boring, LMS would recommend collecting a Shelby tube sample. These samples would be submitted for triaxial vertical permeability testing to determine the effectiveness of this layer in preventing vertical migration.

## 4.6.4 Biomonitoring Program


Because of the PCB contamination in the sediments and surface water at the site, LMS recommends a biomonitoring program to determine the extent of bioaccumulation of PCBs in aquatic organisms in the wetlands adjacent to the site. An uncontaminated upstream community must be identified for the program; northwest of the site there is a potentially appropriate lake from which the stream flows.

A cost-effective biomonitoring program requires a two-stage approach. In the first stage a limited number of sample organisms (10 to 15) of up to three species would be collected from both the upstream, background location and the potentially impacted area. (Depending on the size of the organism and the sample size requirement for the analyses to be performed, more than one organism may be required to constitute a sample.) The samples would be analyzed for PCBs and the results reviewed to determine the nature of the second stage of the program.

The results from the first stage should provide information on the background levels of PCBs, the extent of variability in PCB concentrations among individual organisms, and the percent difference (if any) in the mean PCB concentrations between the background and potentially impacted organisms. The most appropriate species can then be selected for the second stage of the biomonitoring program. A species that appears to be bioaccumulating PCBs and that demonstrates a lesser degree of variability among individual organisms should be selected. The preliminary study can be used to determine the number of samples required to demonstrate with a given degree of confidence ( $\alpha$  and  $\beta$  levels) a statistically significant difference between the upstream and downstream organisms. For example, if a 20% difference between the mean upstream and downstream sample PCB concentrations is considered adequate to show a positive impact by the site on aquatic life, and the coefficient of variability (CV) determined in the preliminary study for a particular species is 0.30 (30%), the number of sample organisms required at a 95% confidence level ( $\alpha$ =0.05,  $\beta$ =0.10) would be 65 (Figure 4-5).

Two-stage biomonitoring facilitates an evaluation, based on preliminary data, of the degree of difference between background and potentially impacted organisms that is adequate to positively attribute bioaccumulation of PCBs in adjacent aquatic life to site contamination. Based on this evaluation, the number of sample organisms required to provide statistically significant results to make this determination can be obtained from Figure 4-5. In this way initial costs of the biomonitoring program are reduced and the overall costs are minimized through selection of an appropriate number of sample organisms. In addition, the state can review the preliminary data obtained to determine the degree of confidence and associated costs desirable for the second phase of the program.

In the initial stage of the biomonitoring program, the on-site pond and upstream lake may be electrofished to obtain the sample organisms. Up to three species present in sufficient abundance (e.g., crayfish, bullheads, or minnows) can then be selected for collection. As the pond is a relatively contained area, any species of fish present may be selected. In open rivers where fish may migrate from one area to another, using fish as the test species may not be appropriate; however, at this site fish would be preferable.



#### CV - Coefficient of variation

- α Probability of a Type I error (say there is a difference when there is none -- consequence is remediation where none is needed)
- β Probability of a Type II error (say there is no difference when there really is -- consequence is no remediation at a site that needs II)

#### FIGURE 4-5

## NUMBER OF SAMPLES REQUIRED TO DETECT DIFFERENCE AT α=0.05, β=0.10, AND VARIOUS COEFFICIENTS OF VARIATION

OLD AMENIA LANDFILL NYSDEC I.D. No. 314006 1992 PHASE II INVESTIGATION

LAWLER, MATURKY & SKELLY ENGINEERS Pearl River, New York Additional surface water and sediment sampling is also recommended in conjunction with the biomonitoring program to further delineate the extent of contamination in this area. Also, contaminant concentrations detected in surface waters and sediments may be used in applicable mathematical models to predict the extent of bioaccumulation in aquatic life.

#### REFERENCES CITED

- [1] Memo documenting interview of 26 November 1991 with Gerald Wilcox, longtime town resident, concerning past site activities. [Appendix B]
- [2] Lawler, Matusky & Skelly Engineers (LMS). 1991. Site inspection report.
- [3] Tetra•K Testing. 1991. Soil gas survey report.
- [4] Letter to Michael Komoroske, NYSDEC, from Sandra L. Foose, EPA Region II, regarding NUS Corporation sampling data for Old Amenia Landfill. 12 September 1990. [Appendix B]
  - [5] Lawler, Matusky & Skelly Engineers (LMS). 1991. Sampling report.
  - [6] Lawler, Matusky & Skelly Engineers (LMS). 1991. Health and safety plan.
  - [7] Newspaper clipping from the Harlem Valley Times. 23 June 1970.
  - [8] Dutchess County Department of Health (DCDOH). Memo to David Ruff from CH. Wright regarding presence of drums containing industrial wastes at the site. 1 July 1970.
  - [9] Letter to Salvatore Surico from David Ruff, Senior Sanitarian, DCDOH, regarding spillage of industrial wastes on ground at site. 23 October 1970.
  - [10] Dutchess County Department of Health (DCDOH) memo to Henry W. Scoralick from David Ruff regarding Surico refuse disposal site. 26 October 1970. [Appendix B]
  - [11] New York State Department of Environmental Conservation (NYSDEC) written confirmation of verbal communication between Jerry Wilcox, local resident, and Michael Komoroske regarding history of Old Amenia Landfill. 7 September 1990.
  - [12] New York State Department of Environmental Conservation (NYSDEC) Receptor Effects of Air Contamination Source from William McEnroe regarding Amenia Landfill site. 21 April 1971.
  - [13] Dutchess County Department of Health (DCDOH) memo to file from Ellis W. Adams, Assistant Project Director, regarding Surico Landfill. 27 April 1971.
  - [14] New York State Department of Environmental Conservation (NYSDEC) written confirmation of verbal communication between Karl Saliter, site owner, and Michael Komoroske regarding access to site. 6 September 1990.

**R**-1

### REFERENCES CITED

(Continued)

- [15] New York State Department of Environmental Conservation (NYSDEC) Refuse Disposal Area Inspection Reports for Amenia Landfill completed by E.W. Adams, DCDOH. 17 February 1972, 30 July 1973, 5 September 1973, 2 October 1973, 4 February 1974.
- [16] Gerber, J.G. 1982. Water Resources Study for Dutchess County. Final Report. Dutchess County Department of Planning.
- [17] Simmons, E.T., I.G. Grossman, and R.C. Health. 1961. Groundwater resources of Dutchess County, New York. U.S. Geological Survey and New York Water Resources Commission. Bulletin GW-43. Albany, NY.
- [18] INTEX. 1991. Geophysical survey report for Old Amenia Landfill site.
- [19] Aquatec Inc. and Nytest Environmental, Inc. 1991. Analytical data package.
- [20] Dragun, J. 1988. The Soil Chemistry of Hazardous Materials. Silver Spring, MD: The Hazardous Materials Control Research Institute. pp. 77, 79.
- [21] Bowan, H.J.M. 1979. Environmental Chemistry of the Elements. New York Academic Press Inc. pp. 60-61.
- [22] Lawler, Matusky & Skelly Engineers (LMS). 1991. Data usability summary. [Appendix A]
- [23] Data Validation Services. 1992. Data validation report.
- [24] New York State Department of Environmental Conservation (NYSDEC), memo to Daniel Eaton, Bureau of Hazardous Site Control, from Richard Koeppicus, Bureau of Environmental Protection, Division of Fish and Wildlife, regarding Phase II investigation of Old Amenia Landfill. 26 August 1992. [Appendix B]

#### LIST OF SUPPORTING DOCUMENTATION

#### I REFERENCE DOCUMENTATION

Newspaper clipping-from-the-Harlem Valley Times. 23 June 1970. [Ref. 7]

Dutchess County Department of Health (DCDOH). Memo to David Ruff from CH. Wright regarding presence of drums containing industrial wastes at the site. 1 July 1970. [Ref. 8]

Letter to Salvatore Surico from David Ruff, Senior Sanitarian, DCDOH, regarding spillage of industrial wastes on ground at site. 23 October 1970. [Ref. 9]

New York State Department of Environmental Conservation (NYSDEC) written confirmation of verbal communication between Jerry Wilcox, local resident, and Michael Komoroske regarding history of Old Amenia Landfill. 7 September 1990. [Ref. 11]

New York State Department of Environmental Conservation (NYSDEC) Receptor Effects of Air Contamination Source from William McEnroe regarding Amenia Landfill site. 21 April 1971. [Ref. 12]

Dutchess County Department of Health (DCDOH) memo to file from Ellis W. Adams, Assistant Project Director, regarding Surico Landfill. 27 April 1971. [Ref. 13]

New York State Department of Environmental Conservation (NYSDEC) written confirmation of verbal communication between Karl Saliter, site owner, and Michael Komoroske regarding access to site. 6 September 1990. [Ref. 14]

New York State Department of Environmental Conservation (NYSDEC) Refuse Disposal Area Inspection Reports for Amenia Landfill completed by E.W. Adams, DCDOH. 17 February 1972, 30 July 1973, 5 September 1973, 2 October 1973, 4 February 1974. [Ref. 15]

Gerber, J.G. 1982. Water Resources Study for Dutchess County. Final Report. Dutchess County Department of Planning. [Ref. 16]

Simmons, E.T., I.G. Grossman, and R.C. Health. 1961. Groundwater resources of Dutchess County, New York. U.S. Geological Survey and New York Water Resources Commission. Bulletin GW-43. Albany, NY. [Ref. 17]

Dragun, J. 1988. The Soil Chemistry of Hazardous Materials. Silver Spring, MD: The Hazardous Materials Control Research Institute. pp. 77, 79. [Ref. 20]

Bowan, H.J.M. 1979. Environmental Chemistry of the Elements. New York: Academic Press Inc. pp. 60-61. [Ref. 21]

R-3

Lawler, Matusky & Skelly Engineers

#### II SUBCONTRACTOR OR SUBCONSULTANT REPORTS

ILi Geophysics Survey [Ref. 18]

II.ii Soil Gas Survey [Ref. 3]

ILiii Data Validation Report [Ref. 23]

ILiv Analytical Data Package [Ref. 19]

#### III HEALTH AND SAFETY PLAN [Ref. 6]

- IV SITE INSPECTION REPORT [Ref. 2]
- V SAMPLING REPORT [Ref. 5]

APPENDIX A

DATA USABILITY SUMMARY

#### ... DATA USABILITY SUMMARY

The final report from Data Validation Services concluded that the samples collected from the Old Amenia Landfill site (LD. No. 314006) and analyzed by Aquatec-Inc. for low-level PCBs were in compliance with Analytical Services Protocol (ASP December 1989). The remaining analyses, conducted by Nytest Environmental, Inc., were in compliance with the following exceptions:

## Volatile Organic Compounds

• VOC continuing calibration standards (CCS) contained components with percent differences (%D) exceeding 35%, causing all of the VOC data, with the exception of sample AMSW-05, to be noncompliant.

TRANSPORTER TO THE WAS CARSO

- The matrix spike blank associated with sediment samples AMSD-01 through AMSD-05 had percent recoveries outside the allowable 75 to 125% range. Additionally, the initial calibration standards associated with these samples were not processed in consecutive order, causing these VOC analyses to be noncompliant.
- The method blank associated with AMSW-04 contained a tentatively identified compound (TIC) at a level exceeding 10% of the nearest internal standard, causing the VOC analysis for this sample to be noncompliant.

#### Base/Neutral Acid Extractables

- The BNA matrix spike blanks produced percent recoveries outside the allowable 75 to 125% range, causing all of the BNA results to be noncompliant.
- The BNA CCS contained components with percent differences exceeding 25%, causing AMSW-01, -02, and -03; AMSS-17, -18, -19, and -20; AMSD-01, -02, -03, -04, and -05 to be noncompliant.
- The BNA instrument performance indicates that some components could not be detected at the required contract-required quantitation limit (CRQL), causing AMSW-04 and -05; AMSD-01, -02, -03, -04, and -05; and the field blank to be noncompliant.
- The BNA analysis of samples AMSW-04 and the field blank produced slightly
  elevated surrogate recoveries; reextraction of these samples was not performed
  as required and therefore the data are noncompliant.

1

Lawler, Matusky & Skelly Engineers

 The initial analysis of AMSS-19 resulted in nonmatrix-related surrogate failure, and reextraction of this sample occurred well outside the required holding time, causing the data for both analyses to be noncompliant.

#### Pesticides/PCBs

- The pesticide/PCB aqueous matrix spike blank produced percent recoveries outside the allowable 75 to 125% range, causing AMSW-01, -02, -03, -04, and -05 and the field blank to be noncompliant.
- Samples AMSD-04 and -05 were analyzed for pesticides/PCBs at a 1:5 dilution without evidence of matrix or target compound chromatographic contribution, causing the data to be noncompliant.

After reviewing the data report and the validator's report, LMS concluded the following with respect to the noncompliant data:

#### Volatile Organic Compounds

- The continuing calibration standards percent difference components outside the required limit do not directly affect the reported data. Fluctuations in operating conditions of the gas chromatograph (GC), as well as temperature variations, can affect the CCS. The exceedances noted in the validator's report are not significant and therefore do not affect the overall usability of the reported VOC results.
- The matrix spike blank associated with the sediment samples produced two recoveries just below the allowable limit of 75%. However, as these suppressed recoveries are common for the matrix spike blank, the overall usability of the data is unaffected. Additionally, the improper processing of the initial calibration standards associated with these samples did not significantly alter the reported results and does not affect the final usability of the data.
- The reporting of a TIC at a level exceeding 10% of the nearest internal standard in the method blank associated with AMSW-04 does not affect the data usability.

#### Base/Neutral Acid Extractables

 The matrix spike blank violations that caused the BNA data to be noncompliant were not significant and therefore do not affect the overall usability of the data.

- The semivolatile CCS for this data package contained components with %Ds above 25% and, as indicated in the validator's report, do not affect the sample results as reported. Therefore, the final data usability is unaffected.
- The data affected by poor instrument performance, as indicated by the standards processed on 17 and 18 December 1991, should be qualified as estimated, as stated in the validator's report. These data are usable with the appropriate qualifications.
- Samples AMSW-04 and the field blank had slightly elevated surrogate recoveries that were noncompliant and should have been reextracted and reanalyzed; however, the failures were not significant and do not affect the data usability.
- The reextraction and reanalysis of the BNA fraction for AMSS-19 was performed 18 days outside the required extraction time. The reported data from the original extract and reextracted analyses were found to be noncompliant and unusable.

#### Pesticides/PCBs

- The matrix spike blank violation causing samples AMSW-01 through -05 and the field blank to be noncompliant appears to be the result of improper spiking, as discussed in the data validator's report, and therefore does not affect the data usability.
- The dilution of samples AMSD-04 and -05 may have caused low-level target compounds to be diluted out without evidence of matrix or target compound chromatographic contribution. These results are usable but the data are qualified to indicate that the absence of low-level contaminants cannot be substantiated.

The validator found the remaining data compliant with NYSDEC's 1989 ASP. Several other issues that could affect data usability were also reviewed by LMS. The results of that review are presented below.

The reported data for 2-butanone (reported as "ND") should be considered estimated because of poor recovery in the initial and continuing calibration standards. Methylene chloride, detected at 26 µg/l in AMSW-03, was not reported by the laboratory; this omission was subsequently corrected. The surrogate associated with extraction procedure (EP) toxicity herbicide analysis of AMSS-19 did not recover (0%). There can be no confidence that the reported results (ND) are accurate; therefore, the reported data for 2,4-D and 2,4,5-TP

(Silvex) are unusable. The surface soil samples are qualified to indicate that the cyanide results are potentially elevated because the matrix spike recovery was 218%; the sediment samples are qualified to indicate that the cyanide results are potentially depressed because the matrix spike associated with the sediments recovered at only 12%. The EP toxicity silver results are reported with an "N" qualifier as the spike matrix recovery (56%) is outside the control limits. The qualifier was added to the summarized data to indicate that the reported results are possibly biased low. A transcription error for the reported total dissolved solids (TDS) value (245 mg/l) for AMSW-03 was corrected to 235 mg/l in the summary report. The chemical oxygen demand (COD) values for AMSW-01, -04, and -05 are qualified as biased high because the COD absorbances were almost the same as that of the 10 mg/l standard.

Overall, the results of LMS' data usability review concluded that the BNA and the EP toxicity herbicide results for sample AMSS-19 are unusable. However, the results of the matrix spike performed on AMSS-19 can be used to determine the concentrations of nonspiked BNA compounds present in the original sample. The remainder of the data submitted for the Old Amenia site are usable with the appropriate qualifiers, as indicated in Data Validation Services' final report.

APPENDIX B
PERTINENT FILES OR RECORDS

REFERENCE 1

### INTERVIEW ACKNOWLEDGEMENT FORM

Site Name: Amenia Landfill, Route 22, South Site

T.D. Number: --314006

Person Contacted: Mr. Gerald Wilcox

Affiliation: Long-time resident of area,
Manager of Amenia Sand & Gravel, Inc.

Address: P.O. Box C
Amenia, NY 12501

Phone:

Person Making Contact: Sara Handy, LMS Engineers

Type of Contact: In person

Date: November 26, 1991

### Interview Summary:

Also in attendance at the interview was Roy Budnik of Roy T. Budnik & Associates, Inc., consultant for the owner of the site (John Segalla, owner of Amenia Sand & Gravel). Mr. Budnik has been conducting a literature and deed search regarding the sources and location of contamination at the site as well as potential liability for site conditions. Provided to LMS by Mr. Budnik (as attached) were a property ownership summary and copies of the attendant deeds, an historical summary of operations at the site as compiled by Budnik & Assoc. from their file review and from Mr. Wilcox, and aerial photographs of the site for 1970 and 1990. The latter were obtained from the Dutchess County Real Property Tax Office.

Operation of the Amenia landfill was very controversial in the Town of Amenia in the late 1960's and early 1970's. The owner, Ben Surico, reportedly intended to bring in waste from other counties (i.e., Westchester and Putnam, which were looking for additional disposal sites at that time as their existing landfills were approaching maximum capacity) for disposal at the Amenia landfill site. Some Town Council members supported this plan while others were opposed.

The Amenia landfill was frequently cited by the Dutchess County

Department of Health (DCDOH) for unsatisfactory operation, beginning in the 1940's and continuing until closure of the Conditions at the site included blowing landfill in 1976. papers, uncovered piles of trash, and unauthorized burning, and was generally considered to be a nuisance by local residents. However, during the period of operation/ownership of the site by Surico, these problems were remedied. The Town Supervisors were pleased with Surico-for meeting the requirements of the DCDOH, so they were tolerant of the drums of industrial wastes being The aerial photo for this period shows stored on site. approximately 200 drums present on the site in a bermed area. Drums were placed in an area of the site not visible from Route 22; Mr. Wilcox indicated that they were somewhat visible from the access road leading to the general dumping area.

Based on Mr. Budnik's review of files concerning the site and Mr. Wilcox's memory of what was common knowledge at that time in the Town of Amenia concerning the landfill, industrial wastes were present at the site from December 1968 to April 1971, during Surico's ownership of the property. Mr. Wilcox had no personal knowledge of the types of industrial wastes that may have been stored at or disposed of on site, the procedures for handling drums at the landfill, or the source of the wastes, as he was not present at the site. (Mr. Wilcox was an officer with the NY State Police in Dover Plains during this period.) only personal experience concerning the landfill in this period was driving past the landfill on a Sunday morning behind a truck carrying drums, which turned into the site. A spray of petroleum compounds coming from the truck hit his windshield. He could not provide any further information regarding this incident, such as any company names on the truck or the drums. The only other information he could provide regarding the possibility of industrial waste disposal at this site is that Mr. Surico is believed to have been connected with a Joseph Fierello of Poughkeepsie, NY, who had ties to Jersey City, NJ, where Mr. Wilcox believes the drums may have come from.

Mr. Wilcox provided the names of the following town residents or officials who might be able to provide additional information concerning the landfill:

- Caroline McEnroe: Justice for Town of Amenia during this period (1968-1971), currently works for Dutchess County.
- Paul Thompson: Town Supervisor during this period (1968 to 1971), currently a Justice for the Town, lives on Depot Hill Rd.
  - H. Bertram Miller: Former Postmaster for Town of Amenia.

Acknowledgeme	nt:	•			
I have read accurate summinterviewer,	ary of the	informat	ion verb	ally convey	red to the La
				•	
Revisions:					
		and a second control of the control	- Mary		

**REFERENCE 4** 



#### UNITED STATES ENVIRONMENTAL PROTECTION AGENCY **REGION II** EDISON, NEW JERSEY 08837

## SEP 1 2 1990

Mr. Michael Komoroske NYDEC Division of Hazardous Waste Remediation 50 Wolf Road, Room 218 Albany, New York 12233-7010

Dear Mr. Komoroske:

Per our conversation on September 10, 1990, pertaining to the Amenia Site, Amenia, New York, the following is enclosed: the sampling trip report, the sample location map, and the analytical data.

If you have any questions, please contact me at 201-906-6808.

Sincerely,

Sandra L. Foose, Environmental Engineer

Superfund Support Section

Attachments

#### SAMPLING TRIP REPORT

SITE NAME:

Amenia Site (Route 22 South)

TDD #:

02-8612-11

SAMPLING DATE:

February 25, 1987

EPA CASE NO:

6888

1. Site Location:

See Figure 1

2. Sampling Locations:

See Figure 2

3. Sample Descriptions:

See Table 1

4. Laboratories Receiving Samples:

Sample Type

Name and Address of Laboratory

Organics (Aqueous and Soil)

Clayton Environmental Consultants, Inc.

22345 Roethel Drive Novi, Michigan 48050

Inorganics (Aqueous and Soil)

Versar, Inc.

6850 Versar Center Springfield, VA 22151

5. Sample Dispatch Data:

Organic soil and aqueous samples were shipped by FIT personnel via Federal Express under Airbill No. 495160702 to Clayton Environmental Consultants, Inc. on 2/25/87 at 1830 hours.

Inorganic soil and aqueous samples were shipped by FIT personnel via Federal Express under Airbill No. 495164353 to Versar, Inc. on 2/25/87 at 1830 hours.

#### 6. Sampling Personnel

<u>Name</u>	Organization	Duties on Site
Gary Bielen	NUS Corp FIT II	Project Manager, Documentation
Jane Bullis	NUS Corp FIT II	Site Safety Officer
John Ducar	NUS Corp FIT II	Sample Management
Dan deBruijn	NUS Corp FIT II	Sampler
Roberta Riccio	NUS Corp FIT II	Sampler/Decon

7. Weather Conditions:


Sunny, 35°F, wind 0-2 mph.

8. Additional Comments:

All-samples collected during this investigation will be analyzed for Hazardous Substance List (HSL) Parameters. A total of thirteen (13) environmental samples were collected from the site. Four (4) soil, three (3) surface water and three (3) sediment samples were collected onsite. Three (3) groundwater tap samples were collected off-site. One aqueous QA/QC blank was obtained from the EPA laboratory in Edison, New Jersey and was shipped with the environmental samples. Sample packaging and shipping was performed in accordance with NUS OGM 4.19.

9.	Report Prepared By:	Gary Bielen	Date:	3/3/87
		,		

	•		)		· 1 1 _
10.	Approved By:	7Km1	kman	Date	: 3 16 87
			1		



(QUAD) AMENIA, N.Y.


SITE LOCATION MAP

AMENIA SITE, (ROUTE 22 SOUTH), AMENIA, N.Y.

SCALE; 1° = 2000'

FIGURE 1





SAMPLE LOCATION MAP

AMENIA SITE, (ROUTE 22 SOUTH), AMENIA, N.Y.

(NOT TO SCALE)

FIGURE 2



#### TABLE I

# SAMPLE DESCRIPTIONS AMENIA SITE (ROUTE 22 SOUTH) AMENIA, NEW YORK CASE #6888 02/25/87

Sample ID Number	Organic Traffic Report Number	Inorganic Traffic Report Number	Time (Hours)	Sample <u>Type</u>	Sample Location
NY66-GW1	BI994	MBI493	1010	Groundwater	Sample taken from
					spigot of Amenia's town well #4. Well located off Route 22 in Amenia.
NY66-GW2	B1995	MBI494	1021	Groundwater	Sample taken from
					spigot of Amenia's town well #3. Well located off Main Street (Route 343)
NY66-G7.3	BI996	MBI495	1110	Groundwater	Sample taken from faucet of private
					residence. Mr. Schiffer's home is located approximately one
*					to two miles south of the site.
NY66-51	BI987	MBI486	1400	Soil	Sample taken 25 feet from fence
			a to the control of t		that surrounds oil storage tanks. Fifteen feet from
					storage tank which is located outside the fenced area.
		· · · · · · · · · · · · · · · · · · ·			Sample depth is 0-6 inches.
NY66-S2	BI988	MBI487	1420	Soil	Sample taken six feet from end of fence that surroun the oil storage are

### TABLE I (CONT'D)

## SAMPLE DESCRIPTIONS AMENIA SITE (ROUTE 22 SOUTH) AMENIA, NEW YORK CASE #6888 02/25/87

	Organic Traffic Report Number	Inorganic Traffic Report Number	Time (Hours)	Sample <u>Type</u>	Sample Location
NY66-SW2	BI998	MBI497	1440	Surface Water	Sample taken
					approximately 100 feet from west side of landfill in pond.
NY66-SED2	BK 103	MBI501	1445	Sediment	Sample taken at same location as NY 66-SW2.
NY66-S3	BI989	MBI483	1455	Soil	Sample taken on west side of landfill approximately 25 feet from pond. Sample depth is 0-6 inches.
Y66-5W3	B1999	MBI498	1530	Surfacé Water	Sample taken approximately 40 feet from S3, upgradient from pond.
NY 66-SED3	BK 104	MBI 502	1540	Sediment	Sample taken at same location as NY 66-SW3.
NY 66-54	B1990	MBI489	1605	Soil	Sample taken on west side of landf approximately 10
4				-	feet from pond.  Sample depth is 0-6 inches.
NY 66-SW I	BI997 -	MBI 997	1620	Surface Water	Sample taken approximately 40

#### TABLE I (CONT'D)

## SAMPLE DESCRIPTIONS AMENIA SITE (ROUTE 22 SOUTH) AMENIA, NEW YORK CASE #6888

Sample ID Number	Organic Traffic Report Number	Inorganic Traffic Time Sample Report Number (Hours) Type	Sample Location
NY66-SEDI	BK 102	MBI500 1630 Sediment	Sample taken at same location as SW1.
NY66-BL1	BI587	MBI504 N/A Aqueous	Collected from EP/ Labs, Edison, N.J.

AMALYTICAL DATA
MAME: AMENIA LANDFILL
SAMPLING DATE: 2/25/87
CASE MUMPER: 6888

INUKGRNICS I														,	
SAMPLE HUMBER I TRAFFIC REPORT HUMBER I MATRIX I UNITS I	NY66-GW1 NRI 493 WATER UG/L		MY66-GV31 MRI 495 I WATER I UG/L		HY66-SW2    HBI 497     WATER     UG/L				•	•	•	INY66-SED1 I MBI 500 I SOIL	IHY66-SEDE	   M766-SED3   MBI 502   MG/KG	!
Aluninum I	[37]	i	 	[68]	   [159]	(63)	(51)	6600	10200	12800	   20600	1 9100	1 7050	l 12000	٠
Antioony I Arsenic I	•	<b>!</b> !	!   !		<b>!</b>	<b>!</b> !	] _ 1 	6.4	l ! I 10	] · · . I	l 	1	1 il i	i 1	!
Barium I Beryllium I	0	0	0 1	0 .	0 1	· Q	[4.4]	, a, i	[65]	- (74)	[84]	[36]	(37)	E373	i
Cadmium		'				) )		1	) · [	• • •	[1.1] 	l (5.2)	1 13E   	,   .	l
Calcium i Chronium i	48300	1 67100 I I 1	77000 l	47100	l 49500 ( l (	<b>i 39900</b>   I	<b>(649)</b>   	) 9 ( ) 8.6 (	1 0 1 1 · 16 1	i 0 1 17	1 G 1 24	1 0 1 (8.1)	! 0 	l 0 l 17	l l
Cobalt !	,	) i	l 1	1	f ' !	<b>!</b>	]	1 - <b>(12)</b> - (	(22)     (35)	[ [14]   50	(12)	( (28) ( (16)	(59)	[8.9]	ı
Iron I	0 * .	0	0	902	1860	0	(67)	20000	40900	33300	30600	58000	1 175000		
Lead I Magnesium I	24400	1 9.6   1 28100	23100 i	14800	1 16000 l	l 12800 1	i (1933)	14     10800						l i 36 l 5410	
Hanganese I Hercury I		1 188 i	(8.6)	310	1 590 (	175 f	l (	663 (	793	573	387	1 1380	1 1170	132	l
Nickel I								<b>26E</b>	52E	29E	(31)	1 76E	1 193E	[24]	l
Potassium I Selenium I	[1420]	I [2330]   I	[1620]   	[1430]	[1 <b>250]</b>    -	[1270]   	l . I .	[1100]   	{1470]   	l (1350) l	[984]  -	l [1530] l	1 [1440] 1	I (7323 I (	1
Silver		<b>I</b> [ ]	۱۰. ا	Ι.	<b>1</b> 1	1 , 1	l i	) :	l .	J ·	ı .	1	$\mathbf{I} = l_{E^{\infty}}$	1	ŧ

16^ | [7.5] | [13] | [9.9] | [18]

1 455

#### HOTES TO INORGANICS DATA:

Sodium Thallium Tin Vanadium Zinc

Blank space - compound analyzed for but not detected

- Q analysis did not pass EPA OA/OC requirements
- C1- compound present below specified detection limits, value is an estimate
- R compound found in laboratory blank as well as the sample and indicates possible/probable blank contamination
- E value estimated due to laboratory interference
- MR- analysis not required

ANALYTICAL DATA HAME: AMENIA LANDFILL SAMPLING DATE: 2/25/87 CASE HUMBER: 6888

#### SEMI-VOLATILES

SEMI-VOLATILES	' ''	!											1	•
SAMPLE MUMBER TRAFFIC REPORT MUMBER MATRIX UNITS CONC./DILUTION FACTOR	I KI 934     Water     Ug/L	I RI 995   I WATER	! NY66-GNJ!   PI 996     NATER     UG/L	NY66-SWI BI 997 WATER	I NY66-SW21 I PI 998 I I WATER I	M1 999     M1 999	I NY66-DL1 I BI 587 I WATER I I UG/L	MY66-S1     B1 987     S01L     UG/KG	I HY66-SE I DI 988 I SOIL	1 HY66-S3 1 B1 989 1 S01L 1 UG/KĠ	1 MY66-54 1 BI 990 1 SOIL	I SOIL	IHY66-SED2 I PK 103 I - SOIL	I INY66-SED I BK 104 I SOIL I UG/KG I 2
Phenol		 	 	 	 	 			 	!	l	.	] <del></del>	1
Bis(2-Chloroethyl)Ether	i											1		<u>.</u>
2-Chlorophenol		,	' ' I '		,							1	1	
1,3-Dichlorobenzene			, ,			,						1	•	1
1,4-Dichlorobenzene	i	,								,		!		1
Benryl Alcohol I											0	!	!	! .
1,2-Dichlorobenzene	<i>'</i> ;	i				1						!		1
2-Methylphenol (								 				1	, ,	!
Bis(2-Chloroisopropyl)Ether!	,	١.		ï	· · · · · · · · · · · · · · · · · · ·			1				1		1:
4-Methylphenol	• ;		, , , , , , , , , , , , , , , , , , ,	ï		- :		1		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		1	1.	11
H-Hitroso-Bi-m-Propylamine (	i		i	ï	•	i	· ·							
Herachloroethane :	i	i		i	1		,		· .	: <b>[</b>		1		
Mitrobenzene		i		i			·							i •
Isophorone						:	;					1 1		1
2-Mitrophenol		٠ :	' '		; ;		'			• 1				1
2,4-Dimethylphenol 1		i .								,	. 19	I		1
Benzoic Acid i		1				. !					<u>.</u>	l .	l i i	1.
Dis(2-Chloroethoxy)Methane 1					!		1	1	6703 1	15001	Q	ł		1
2,4-Dichlorophenol						· !	!				. 0	1	1	I ; .
		:	!	ı,	1		1	· .		· •	0	1	l ign - I	1
1,2,4-Trichlorobenzene . 1		!	!		. !	. !	!	,	1 - 1 - 1   1		. 0	I :	1   1	1
Haphthalene 1 4-Chloroaniline 1		. !	. !			!	!	. 1	· I	· · 1	. 0	f I	1	ļ .
Herachlorobutadiene 1	!	. !	!			!	!		· [	!	0	1 .	1	J
4-Chloro-J-Methylphenol I		- :	1		. !	. !	,	!			0	1		1
2-Methylnaphthalene I	, ,	,		• !			j			· .		i :		ηį ,
Herachlorocyclopentadiene		- !	- 1		1	!	!			Į.	0	! 1		1 .
2,4,6-Trichlorophenol I						!	, !				. 0		1	ĺ
e, 4,5-Trichlorophenol		'				!	!	!			g			j -
2-Chloronaphthalene I	:	. :					1		' !		8	i :		
2-Mitroaniline 1		;	;			1			- !		u a	I : 1		i .
Diwethyl Phthalate 1	. !		:							. !		! •		1 , .
•	- ' !		- !	. !		!	- !	; !			0	!		
Acenaphthylene I		, !		. !		5. I	Į.	. !	!		0	[    -	ı	1
J-Mitrosniline : I	· ' !		1	!	Į.	!	1.		l	!	0	<b>!</b> !	1	,
Arenaph thene						ļ	, I	· I	.1	1	0	1	, I	
F. C. Dinitrophenal	· •	•		!	. !	!	ŀ	ı	1	ı	0	! (	l	
4 Hitrophenol   1	. !	!		!	1	!	!		. !	, !	0	<b>!</b>	1	
Dibensoluese I			1			!	!	!	. !	. 1	0	. !	l	
2,4-Binitrotolores 1				'		!	,		!	. !	Ü	! ! ! !		
Brethylphthalate !			ï	- 1		<u>'</u>	,			. ' '		• I		
4 (hiorophenyiphenyi ether i			, i		:				. :			; l		7400
									. !			• I	' I	
fluorene I		1	,		- 1	1	· 1				0	i .	1	1

100097

ANALYTICAL DATA
MANE: AMENIA LANDFILL
SONPLING DATE: 2/25/67
COSE MUNDER: 6886

	S/Pra.

	I	l=====================================		,											
SAMPLE MUMBER TRAFFIC REPORT MUMBER MATRIX UMITS COMC./DILUTION FACTOR	NY66-GW1 BI 994 WATER UG/L 1	HY66-GW2    BI 995     WATER     UG/L	NY66-GV3    N1 996     Water     Ug/L	HY66-SV1   BI 997     WATER     UG/L     1	   HY66-SV2    BI 998     WATER     UG/L	   MY66-SW3    DI 999     WATER     UG/L	NY66-BL1	1 MY66-S1	NY66-52 N 1 988 SOIL	I NY66-S3	HY66-S4   BI 990   SOIL   UG/KG -	I PK 102 I SOIL I UG/KG	I BK 103 I SOIL - I	IINY66-SED. I BK 104 I SOIL I UG/KG	-1 31 1
Alpha-BHC Beta-RHC Delta-RHC	     	 		     		   	<del></del>	   0		1 0 (	0	   0 :			-1
Gamma-BHC (Lindane)   Heptachlor     Aldrin   Heptachlor Epozide	1 1 1	1	1	! !		 			 					0	
Endosulfan I   Dieldrin   Carlon   Carl	 	! !	1	1	1	 	   	0 1	 		0 1	0 1	1 0 1	0	
Endrin   Endosulfan II	1	1	! !	. 1	1 1	: : I I I	 	0 I	 	0 1	0 1	0 1	Q 1	0	1
Endrin Aldehyde ! 4,4°-DDT ! Methasychlor !	!	1	1	1	1	1 H	)   	0 i 0 i	! !	0 I	0 1	0 1	0 I	0 0	; ;
Endrin Ketone Chlordane Tozaphene Aroclor-1016	1			. ! !	 		1 1 1	1 0 1	1	0 I 0 I 0 I	0 1	0 1	0 1	0 0	
Aroclor-1232 Aroclor-1232		 		1	1 1. 1	1	j.	0 1	1	0 1	0 1	0 I 0 I	0 1	Q - 1	
Aroclor-1248   Aroclor-1254   Aroclor-1260	1	   	1 · 1	1	i 1	1	1	140007   Q   Q	ا   170000 .    -	9. 1 130007 1 0 1	0 1 0 1	0   3700J   0	9 I 0 I	0 I	

#### HOTES TO ORGANICS DATA:

Blank space - compound analyzed for but not detected

- 0 analysis did not pass EPA DA/OC requirements
- I compound present below specified detection limits, value is an estimate
- B compound found in laboratory blank as well as the sample, and indicates possible/probable blank contamination
- HR analysis not required

100098

jstilier .

ANALYTICAL DATA HAME: AMENIA LANDFILL SAMPLING DATE: 2/25/87. CASE MIMPER: 6888

SENT-VOLATILES	ļ. ·													, 
SAMPLE NUMBER TRAFFIC REPORT HUMBER MATRIX UNITS CONC./DILUTION FACTOR	HY66-GW1   DI 994   WATER   UG/L	   HY66-6V21   BI 995     WATER     UG/L     1	•							HY66-S3 H HI 989 H SOIL H UG/KG	HY66-S4 BI 990 SOIL UG/KG	2   WY66-SED1   BK 102   BOIL   UG/K6	INY66-SED2 I BK 103 I SOIL I UG/KG I 2	HY66-SED3 I BK 104 I SOIL I UG/KG I 2
4-Mitroaniline 4,6-Dinitro-2-Methylphenol M-Mitrosodiphenylamine	     					 		 	 	 		1 1 1	† 	 
4-Bromophenylphenyl ether Hesachlorobenseme Pentachlorophenol Phenanthreme	;   			)   	       	 	 	 	l t l	l ! ! !	1 0 1 0 1 0	1 1 1 1	1 1	
Anthracene Di-n-Butylphthalate Fluoranthene Pyrene	! !	i 1		15   15 	1 1	J   	 	 	1 540J I I	! ! !	1	1	1 de la	! ! !
Butylbenzylphthalate 3,3°-Bichlorobenzidine Benzo(a)Anthracene Bis(2-Ethylhezyl)Phthalate	1 1 1	1 1	     220	,   	,   	! !	 	i 1 1	i i i 1600	1 1	1 0	1 1	 	1 1 1 7301
Chrysene Di-n-Octyl Phthalate Benzo(b)Fluoranthene Benzo(k)Fluoranthene	1 1 1	1 1 1		 	1	! ! !	1	; ; ; 1	1 1 1	1	1 0		1	1
Benzo(a)Pyrene Indeno(1,2,3-cd)Pyrene Bibenzo(a,h)Anthracene Benzo(ghi)Perylene	1 1 1	1 . 1 1	t : t : 1	! !		1	1 1 1 1	1 1 1	 	   •   • •   • •	1 0		1	1

#### NOTES TO ORGANICS DATA:

Blank space - compound analyzed for but not detected

9 - analysis did not pass EPA OA/OC requirements

J - compound present below specified detection limits, value is an estimate

B - compound found in laboratory blank as well as the sample, and indicates possible/probable blank contamination HR - analysis not required

100099



HAME : "AMENIA" LANDEILL" SAMFLING DATE: 2/25/87 CASE NUMBER: 6888

VOLATILES - . :

	NI 994 WATER		HY66-GW31   BI 996     Water     Ug/L	HY66-SW1    BI 997     WATER     UG/L		BI 999 WATER	DI 587 WATER	BI 987 SOIL	1 31 988 1 SOIL	HY66-S3   BI 989   SOIL   UG/K6	91 990		IHY66-SED2 I BK 103 I SOIL I UG/KG I 1	IHY66-SEB3 I BK 104 I SOIL I UG/KG
Chloromethane Bromomethane Vinyl Chloride Chloroethane Methylene Chloride	0	 		1 1 1 1 0 1	9				i	i i i 0		! ! ! ! Q	1 2. 1 3. 1 3. 1 9. 1 9.	l   
Acetone Carbon Disulfide 1,1-Dichloroethene 1,1-Dichloroethane Trans-1,2-Dichloroethene Chlorofore	W		; \ \	; w		j   j 		• • • • • • • • • • • • • • • • • • •		• • • • • • • • • • • • • • • • • • •	• ! !		1	
1,2-Dichloroethane 2-Butanone 1,1,1-Trichlorpethane Carbon Tetrachloride Vinyl Acetate Bromodichloromethane	 	1 1 1 1 1		]	]	 	 	 	 		 	1 1 34 1 1 1	1 54 1 54	I 36 I I I
1,1,2,2-Tetrachloroethane 1,2-Dichloropropane Trans-1,3-Bichloropropene Trichloroethene Bibromochloromethane	 	 	1 1 1 1 1	j j	]		 		1	† 	       			: ! !   J
1,1,2-Trichloroethane Benzene Cis-1,3-Bichloropropene 2-Chloroethylvinylether Brownform 2-Hesanone	 	1 1 1 1 1		 	 	 	1 1 1 1 1	: ! ! ! !	I	;   	! ! ! !			
4-Methyl-2-Pentanone Tetrachloroethene Toluene Chlorobenzene Ethylbenzene	f f f 1	i I I I	 	 	 	 	 	 	1 1 1 1	 	 	 	1	
Styrene Total Xylenes	1 +	1	Ι,	1	1	! 	i	1		i		i	1	

#### HOTES TO ORGANICS DATA:

Blank space - compound analyzed for but not detected

- 0 analysis did not pass EPA DA/OC requirements
  J compound present below specified detection limits, value is an estimate
- B compound found in laboratory blank as well as the sample, and indicates possible/probable blank contamination

Huntene

REFERENCE 10

#### DUTCHESS COUNTY HEALTH DEPARTMENT

#### MEMORANDUM

TO:

Mr. Henry W. Scoralick

FROM:

D. Ruff

SUBJECT:

Surico Refirse Disposal Site

T. Amenia

DATE:

October 26, 1970

On October 22, 1970 between 2:00-2:30 p.m., I conducted an inspection at the above noted facility. All refuse was deposited in an area approximately 50' wide and 20' deep. Operation appeared to be orderly and covering and compacting was done satisfactorily. Mr. Surico questioned if covering could be done every other day and I stated it had to be done every day.

I did not observe anywhere where industrial wastes were dumped into or near surface waters. On the upper level at the south end are stored several hundred barrels of industrial wastes and covering an area of one acre. Some barrels had been punctured with the resultant discharge of chemicals upon the surface of the ground. Mr. Surico claimed that this was the result of vandalist. He also claimed that some spillage was due to barrels falling off of fork lift. The industrial waste on surface of ground was a brownish oily, black oily, bluish and reddish brown liquid plus a white powder. The following names of companies and contents were observed on barrels:

 Remington Rand Electric Shaving Div. 60 Main Street Bridgeport, Connecticut

Crystoton

2. U. S. Polymeric

P.F. Etchant Ferris Chloride

3. ALRAC Div. Radiation Research 649 Howe Street (P.O. Box 2109) Stamford, Connecticut

2 Pyorrolicate

4. The Hubbard Hall Chemical Co. Waterbury, Connecticut

Mineral Spirits

Mr. Surico stated that chemicals are pumped out of barrels and stated to New Jersey. Empty barrels are sold if not damaged. If damaged, barrels are crushed and buried.

In the summer, oil was used on entrance road to settle dust. There is a remote possibility that during a heavy rain some of this could have run cit in swamp at north end. I could see no trace of chemicals in swamp areas. Mr. Sirico claims all chemicals will be removed from site by November 1, 1970 and that business discontinued.

DTR/aed HD ADM **REFERENCE 24** 

## MEMORANDUM

August 26, 1992.

JORTHOL ZUCCERTE

TO:

Dan Eaton, Bureau of Hazardous Site Control, DHWR

FROM .

Richard Koeppicus, Bureau of Environmental Protection, Division of Fish and Wildlife

SUBJECT:

Old America Landfill, Site # 314006. Review of "Engineering Investigations at Inactive Hazardous Sites, Phase II Investigations, Old America Landfill, Town of America, Dutchess County, New York" dated June, 1992.

Amenia

I have concluded that there is sufficient information in this document to list this site as an actual or potential threat to the environment. I believe there is sufficient information to warrant a remedial investigation i.e., the site should have class step recommended on p3-22 by LMS to determine the classification of this site.

My conclusion is based on the data gathered to date that showed 15 of 20 soil samples had PCB levels from 2.3 to 250 mg/kg, 1 of 5 locations of surface water samples (AMSW-03) had a PCB level of 0.060 ug/l and 3 of 5 sediment samples had PCB levels from 0.510 to 5.20 mg/kg. These levels show widespread contamination and are of significance to wildlife.

Supervising Fish and Wildlife Ecologist

RK:rd

cc: J. Cooper

B. MacMillan

'K65.mem/rd26

# SUPERFUND STANDBY PROGRAM New York State Department of Environmental Conservation 50 Wolf Road Albany, New York 12233-7010

## TEST PIT INSTALLATION REPORT OLD AMENIA TOWN LANDFILL SITE

Site No. 3-14-006

Work Assignment Number D003060-21



Prepared by

TAMS CONSULTANTS, Inc.

The TAMS Building 655 Third Avenue New York, NY 10017-5617

OCTOBER 6, 1998

## TEST PIT INSTALLATION REPORT OLD AMENIA TOWN LANDFILL SITE CONTENTS

			<u>Page</u>
1.0	INTRODUCTION		1
1.1	SITE DESCRIPTION AND SURROU	NDINGS	
1.2	SITE HISTORY		1
1.3	PREVIOUS STUDIES		
2.1	TEST PIT PROCEDURE		3
2.2	TEST PIT DESCRIPTIONS		4
2.3	SITE RESTORATION		9

## LIST OF FIGURES

Figure 1 Site Location Plan Figure 2 Test Pit Locations

## **APPENDICES**

Appendix A Test Pit Photographs
Appendix B Test Pit Logs
Appendix C Field Notes

#### 1.0 INTRODUCTION



TAMS Consultants, Inc., under contract to the New York State Department of Environmental Conservation (NYSDEC), Superfund Standby Contract (D003060) performed an Immediate Investigation Work Assignment (IIWA), (WA#D003060-021) at the Amenia Town Landfill, Site #3-14-006, in the Town of Amenia, Dutchess County, New York. The investigation required the excavation of test pits/trenches throughout the landfill to determine the presence or absence of drums suspected to be buried at the Site.

The excavation of the test pits was performed by Environmental Products and Services (EPS), of Newburgh, New York, as a subcontractor to TAMS. EPS supplied the necessary equipment, labor, and health and safety equipment needed to complete the test pits/trenches.

## 1.1 SITE DESCRIPTION AND SURROUNDINGS

The Old Amenia Town Landfill Site is located on the west side of Route 22 in the Town of Amenia, Dutchess County, New York (Figure 1; NYSDEC Site #3-14-006). Except for a period between the end of 1968 and April 1971, the town used the 10 acre site as a municipal dump from the late 1940s until 1976. The northern portion of the site, currently owned by Mr. Karl Saliter of Sharon, Connecticut, is occupied by the Sharon Oil & Gas Company fuel storage enclosure, which consists of a number of above ground storage tanks within a fenced, bermed area. Mr. John Segalla of Amenia is the present owner of the southern portion of the site. With the exception of a small helipad and paved access road, the southern portion is, for the most part a well-graded, maintained, grassy area.

Fill material such as broken glass, scrap metal, tires, old appliances and empty drums are visible in a few areas around the site.

#### 1.2 SITE HISTORY

During the period of operation of the site as a landfill, the ownership of the property changed several times. The Town of Amenia rented the property from William and Mary Murphy for disposal of municipal wastes from approximately 1947 until December 1968, when the property was sold to Salvatore (Ben) Surico. The town discontinued dumping at the site and opened an emergency disposal area on the property immediately north of the site.

Industrial wastes were known to be present at the site during the time Mr. Surico operated the landfill, from 1969 until April 1971. Dutchess County Department of Health (DCDOH) inspection records, a local newspaper article, and an aerial photograph of the site dated April 1970 confirm the presence of a large number of 55-gal drums stored in a bermed area at the site. Industrial wastes were reportedly removed from the barrels and transported off-site in tanker trucks; the empty drums were sold or crushed and buried on-site. Local residents, however, noted oil on the surface of the water



REPORT.WPD

Page -

in the nearby wetlands area and oil-like odors emanating from the site. In addition, DCDOH inspection reports document that industrial wastes were leaking onto the ground surface from barrels stored at the site.

A more detailed discussion of the site operations and history can be found in the April 1993 "Phase II Investigation Report", prepared by LMS Engineers on behalf of the NYSDEC.

In 1971 the Town of Amenia assumed responsibility for the operation of the landfill when Mr. Surico filed for bankruptcy. The town continued to operate the landfill for the disposal of municipal wastes until it was officially closed on 16 April 1976. Closure of the dump involved application of a soil cover of unknown depth and grading of the site.

The landfill was listed with the New York State Department of Environmental Conservation (NYSDEC) as a Reported Hazardous Waste Site in 1980 based on a site inspection that revealed evidence of drums in the southwest corner of the site in an area with no vegetative growth. The U.S. Environmental Protection Agency (EPA) identified the Old Amenia Landfill as a Potential Hazardous Waste Site in 1981.

#### 1.3 PREVIOUS STUDIES

A Phase I investigation in August 1986 concluded that a Phase II investigation was needed to confirm the presence of hazardous wastes at the site and to determine whether any contamination present poses a significant threat to human health or the environment. In 1987 EPA collected a soil sample along the western side of the landfill during a limited field investigation. The sample contained 170 ppm of polychlorinated biphenyl (PCBs) (Aroclor 1248).

In April 1993 the Phase II Investigation was completed, which consisted of a geophysical survey; a soil gas survey; and surface soil, surface water and sediment sampling and analysis. Areas with high magnetic anomalies were delineated as a result of the geophysical survey. These areas correlated with many high concentrations of VOCs found during the soil gas survey. Buried drums of wastes could be responsible for these conditions. In addition, PCBs, ranging from 2.3 to 250 mg/kg, were found in surface soil samples but only low concentrations of VOCs were found. The surface water/sediment samples also contained low concentration of VOCs and SVOCs. Other compounds of concern found on site include vinyl chloride, benzene, toluene, TCE, and manganese. One of the recommendations of the Phase II study was to excavate test trenches to verify the presence of buried drums.

During the beginning of September. 1998, NYSDEC excavated test pits on-site to verify the presence or absence of buried drums on-site. A description of the field work performed and what was found on-site is the subject of this report.

## 2.1 TEST PIT PROCEDURE



Field work took place on-site from September 8, 1998, to September 15, 1998. The test pit locations (Figure 2) were laid out by NYSDEC and TAMS personnel on September 8, 1998. TAMS and EPS mobilized their field equipment and began the test pit excavations on September 9, 1998.

The installation of the test pits was performed in accordance with the Work Plan and the Health and Safety Plan that were prepared by TAMS. Prior to the start of the test pit excavation, a health and safety briefing was held on-site. Items discussed included the proposed excavation procedure; communications and hand signals; levels of protection and action levels.

Before the start of each test pit, a Photoionization Detector (PID) or Flame Ionization Detector (FID) was used to obtain background readings. The FID was used on September 9 as it was raining, and the PID does not work properly when there is high humidity present. The disadvantage with using the FID is that it detects methane which is usually present in landfills generated as a byproduct of decomposition. An exclusion zone was set-up by TAMS personnel using caution tape at a distance of twenty-five feet from the test pit in all directions. A decontamination station was placed at the entrance to the exclusion zone.

Test pits #1 and #2 were started in Level B, based on previous elevated soil gas readings. The remaining pits were excavated in Level C. The Site Safety Officer (SSO) set-up within each exclusion zone with the PID meter, a Lower Explosive Level (LEL) meter, a Combustible Gas Indicator, and a MiniRad meter. Each location began as a four foot wide trench, with EPS achieving the maximum depth from the start, and then progressing the length of the test pit.

EPS initially mobilized a John Deere 410D Extend-a-hoe backhoe to the site. However, the maximum excavation depth achieved by this machine was 12 feet below ground surface (bgs). However, as waste thickness was much greater than 12 feet, it was agreed by TAMS and NYSDEC personnel to replace the backhoe with an excavator. On the second day of field work, EPS mobilized a John Deere 590D Excavator with a reach of 20 feet. Those test pits completed on the first day with the 410D were re-excavated with the new excavator.

EPS laid out 10-mil plastic sheeting on the ground adjacent and upgradient from the test pit, on which the excavated soil was placed. The operator would allow the SSO and NYSDEC personnel to take readings from the pit and debris pile, and to take a closer look at objects removed from the hole. If a drum was encountered, readings and samples (if possible) were taken. The excavation was then expanded around the drum to determine the number and location of additional drums.

Once the test pit was completed to an acceptable depth and length with soil samples (if any) collected and photographs taken. EPS would backfill the garbage/ debris and soil removed, along with the plastic it was staged on, into the excavation. Personal protective equipment used during the field work (such as gloves and tyvek coveralls) was placed in a plastic bag and backfilled into the excavation. The bucket of the machine was used for compaction, and was cleaned between each test pit. On the last day of field work, EPS spread 6-12 inches of topsoil on each test pit, and TAMS



REPORT.WPD

Page - 3

personnel spread seed, fertilizer, and straw mulch over each location. The test pit excavations were marked with wooden stakes for future reference.

### 2.2 TEST PIT DESCRIPTIONS

## Test Pit # 1

Test pit # 1 was started on September 9. This pit was eight feet wide by thirty feet long, located in the northwest corner near Sharon Oil. This work was done in Level B personal protective equipment. There was only about 6 inches of bony fill (sandy gravel) material before glass bottles were found. This layer, sandy gravel, extended to about 3 feet in depth. At about 2.5 feet bgs there was a reading of 40ppm in the test pit. The garbage layer extended from the 3-foot depth to the 7 foot depth bgs. At about 4 feet bgs, there was a FID reading of 100ppm. A strong methane odor was detected between 4-5 feet bgs. After the garbage layer, there were another 2 feet of fill material. The rest of the excavation, from 9 to 12 feet bgs, contained garbage. A newspaper dated 1971 was found in the 7-8 foot level. There were a lot of small pieces of metal throughout the excavation, but no evidence of drums. The high readings on the FID meter could be attributed to the presence of methane gas. The depth of the test pit was 12 feet when using the backhoe. The hole was backfilled overnight for safety reasons.

On September 10, an excavator was used to complete the excavation of the test pit. Based on the readings from the previous day, and the fact that drums were not found, the SSO decided to downgrade the level of personal protective equipment from Level B to Level C. NYSDEC personnel decided that a small depression on the south west corner of test pit # 1 should be investigated. This excavation was perpendicular to the first hole, and only 4 feet wide by 15 feet long. A metal bedframe was found within 1 foot of the ground surface. A crushed 55-gallon drum was found at about 10 feet bgs. At the south east end of this excavation, at about 12 feet bgs, two PID readings of the soil in the excavator bucket were taken. They were 45 ppm and 100 ppm, respectively. A solvent type smell was also present. NYSDEC personnel took soil samples from this depth. Another bucket from the 14-foot level had a reading of 30 ppm. A crushed drum was also found at this depth. The maximum depth achieved for this test pit was 17 feet. PID readings at this level were 40 ppm and 140 ppm. NYSDEC personnel take a soil sample from this depth. Readings during sampling were between 100 and 300 ppm. Garbage was present in the bottom of the test pit. Upon completion of sampling, EPS backfilled the test pit as described previously.

## Test Pit # 2

Test pit # 2 was started on September 9, and performed in Level B personal protective equipment. This test pit was located east of pit # 1, along the Sharon Oil property. The first three feet of this excavation were the same bony fill material found previously, however, there was no garbage in this layer. At the northeast end of the excavation, on the north side, a 55-gallon drum was located about 10 inches bgs. It was empty and partially crushed. Since the test pit was going to be reopened the

REPORT.WPD

Page - 4





next day, the drum was left alone. There was also a 5-gallon pail found at about 3feet bgs located in the southern end of the test pit, with a FID reading of 8 ppm. A 2-gallon pail was found at 4.5 feet bgs, with an oily substance on it. There were no elevated readings on FID. Very little garbage/debris was found until the 5 feet bgs, where some glass, paper, plastic, and wood were excavated. A small bike frame was found at 7 feet bgs. At 9 feet bgs, a metered glass bottle and a bottle with a septum top were-found. It was assumed that it was an Intravenous Bottle from a hospital. A large piece of metal sheeting was also found at this depth. In the southeast end of the excavation, garbage and debris were found within 1 foot of the ground surface. The test pit was backfilled overnight.

On September 10, re-excavation began with the excavator, and was completed in Level C personal protective equipment. This test pit was centered around the drum found the previous day. The test pit was expanded to the north by 12 feet, at the northeast end. A metal bed frame and a 5-gallon pail were found within 2 feet horizontally of the drum found the previous day. Another 55-gallon drum was located approximately 8 feet bgs and directly below the first drum. The PID readings were 11 and 6 ppm. This second drum which was crushed and empty had "Remington Rand Shaver Division, 60 Main St., Bridgeport, CT," written on the top of the drum. "US Product", "09934", and "Pittsburgh" was also written on the lid. Maximum depth achieved was 17 feet bgs. NYSDEC personnel then took soil samples from this depth. Garbage was present in the bottom of the test pit. EPS backfilled the debris and soil into the excavation as described previously.

## Test Pit #3

Test pit #3 was completed on September 10. This excavation was started in Level B, but completed in Level C. EPS began excavation with the backhoe, and switched to the excavator once it arrived on-site. The first 3 feet of the pit were bony fill material. A washing machine was found at about 3.5 feet bgs. The garbage layer extended from 3 feet to about 5 feet bgs, then a 2-foot fill layer, with garbage down to 10 feet bgs. A newspaper dated 1970 was found at 7 feet bgs, and an automobile gas tank was found at about 9 feet bgs. At this point EPS switched over to the excavator. There was another 2-foot fill level at 11 feet bgs. Garbage extended from this point down to the bottom of the test pit (19 feet bgs). A 5-gallon oil container (Texaco) was found at 18 feet bgs, along with two newspapers dated 1968 and 1970. NYSDEC personnel took soil samples at 19 feet bgs. Upon closer inspection of the debris pile, a syringe was found: depth was unknown. EPS backfilled the test pit as described previously.

## Test Pit #4

Test pit #4 was completed on September 11, in Level C. This excavation was located south of pit #1, about 125 feet south of the Sharon Oil property. There was about 2 feet of bony fill material, then garbage down to 15 feet bgs, then fill material to 17 feet bgs. Several tires were buried in this test pit, along with small pieces of metal such as mufflers, pipe, etc. Also, two hot water heaters were found at the 8-foot level. All readings taken with the PID were 0 ppm at this excavation. NYSDEC personnel did not take any samples from this test pit; EPS then backfilled the test pit as described previously.



REPORT WPD

Page - 5 --

## Test Pit #5

Test pit #5 was completed on September 11, in Level C. This test pit was located in a large depression about 45 feet southeast of #1, and 50 feet west of the Helicopter pad. It was approximately 10 feet wide by 25 feet long. Garbage/debris was found within 1 foot of the ground surface. A car bumper was found at 2 feet bgs. About 25-30 garage receipts from the Sharon Garage, dated 1966 were found at 6 feet bgs. The debris layer extends down to the 6 foot level bgs, with fill material for another 5 feet. A small layer of debris, about 2 feet thick, was found containing glass, wood, metal scraps, paper, plastic, and another IV bottle. NYSDEC personnel took a soil sample from the 12 foot level bgs, which had a PID reading of 2 ppm. The rest of the excavation consisted of a sandy material. EPS excavated this test pit to 17 feet bgs. EPS backfilled the test pit as described previously.

## Test Pit #6

Test pit #6 was completed on September 11, in Level C. This test pit excavation was 5 feet wide by 25 feet long, and was located at the base of the small rise about 80 feet south of the Helicopter pad. There was 2 feet of the bony fill material on top, then 6 feet of garbage, and another 6 feet of gravely sand material to the bottom of the test pit. The garbage found at the 2-4 foot level consisted of bags of leaves, paper, plastic, glass, and wood. At 4 feet bgs, the soil color changed to a gray color for about 8-10 inches, with a PID reading of 1 ppm. A newspaper was also found at this depth, dated 1972. NYSDEC personnel took a soil sample at the 9-10 foot level. Since the material at the bottom of the hole contained no garbage, it was decided to stop at the 13-foot level. EPS backfilled the test pit as described previously.

## Test Pit #7

Test pit #7 was completed on September 11, in Level C. This excavation was located on the small rise, situated north-south, about 70 feet west of the large berm along Route 22. There was only about 10 inches of the typical bony fill material before garbage/debris was found. The garbage layer extended down to the 19 foot level bgs. The garbage consisted of paper, plastic, wood, and glass. It appeared slightly damp, possibly from surface runoff infiltration from the slope. A newspaper was found at the 8-foot depth, dated 1974. PID readings at this depth were 2 ppm. A large steel pressure tank, 36 inch diameter, 6 feet tall, was found at the 14-foot level. PID readings were 4 ppm from the soil at this level. Another 1974 newspaper was found at the 18-foot level. There was an abundance of mimeograph (purple) paper found throughout this excavation. NYSDEC personnel took a soil sample from the 19 foot level bgs. EPS backfilled the test pit as described previously.

**TAMS** 

retoor

## Test Pit #8

Test pit #8 was completed on September 11, in Level C. This excavation was located on the flat surface above the small rise, about 50 feet east of the woods, and 60 feet south of the edge of the rise. There was less than 1 foot of cover material at this location. A car bumper was found within the top foot of material. A large boulder, 4 foot by 6 foot, was found at about 2 feet bgs. The garbage layer extended for 3 feet, then a 5-foot layer of fill, then garbage to the bottom of the pit. A newspaper dated 1975 was found at the 12 foot level bgs. The soil from 12-14 feet was reddish in color, most likely from bricks. Readings from the PID were 0 ppm throughout the excavation. EPS excavated this test pit to 17 feet bgs. NYSDEC took a soil sample from the bottom of the test pit. EPS backfilled the test pit as described previously.

## Test Pit #9

Test pit #9 was completed on September 14, in Level C. This area was located on the west side of the access road to the adjacent property to the south. Five test pits were excavated in this location. EPS cleared an area about 25 feet wide by 140 feet long to begin this excavation. Starting in the southwest corner, in what appeared to be a fill in swale, there were 5 visible drums. No elevated PID readings were detected prior to the excavation of the test pits. During the clearing of the brush, another 7 drums were found partially buried.

The initial excavation (Test Pit #9) was located 10 feet east of the 5 visible drums. This test pit was 4 feet wide by 6 feet long. At about 2 feet bgs, a small plastic lined metal container containing a white powder was found. No markings were visible on the container. No elevated PID readings were detected. At about 3 feet bgs, the excavator ripped into a metal container, approximately 30 gallons, containing the white powder. It gave off a pesticide type odor. Many smaller metal containers and possible other drums were also buried here. Work was then stopped and it was decided to overpack this drum and the spilled white powder. This proved difficult, because during the overpacking process, the dry powder became airborne. It was agreed between TAMS and NYSDEC personnel to lay plastic sheeting over the white powder in the excavation and to backfill the test pit. White powder that was already excavated was placed in the 85-gallon overpack NYSDEC personnel took a sample of the white powder. At 3 feet bgs a top to a 55-gallon drum was also found that read "Geigy Agricultural Chemicals New York", "267334 C/1", "5#", "Made in Switzerland". Written in black marker was "10/3/67" and "#9005".

The next test pit excavation (Test Pit #9A) was located in the area of the 5 visible drums as described previously. One of the drums contained a solid cloudy substance. The material was broken into small pieces using a hammer and sampled by NYSDEC. This test pit was 4 feet wide, by 8 feet long. No elevated PID readings were detected. At 1.5 feet bgs, a drum that initially appeared to be empty gave a HNu reading of 100 ppm. It contained an oily, black liquid. NYSDEC personnel took a sample of the stained soil in the drum. This material is believed to be a solvent as the label that was placed on the sample jar using a Sharpie permanent marker became faded when the oily substance contacted the soil jar. EPS tried to overpacked the drum and stained soil. The stained soil was

REPORT.WPD Page - 7 TAMS

overpacked but the drum would not fit inside the 85-gallon overpack. Instead, the visible contents of the drum were removed by shovel and placed in the overpack. The sidewalls of this test pit contained drums. Another crushed drum gave a HNu reading of 20 ppm. The PID gave a constant reading of 15 ppm in the test pit excavation. EPS backfilled the test pit as described previously.

Test Pit #9B was dug approximately 30 feet to the north of Test Pit #9A. This test pit was 4 feet wide by 25 feet long by 4 feet deep. The soil from this test pit was sand with lots of roots. No drums were found in this test pit. No elevated PID readings occurred.

Test Pit #9C was dug approximately 15 feet to the north of Test Pit #9B. This test pit was 4 feet wide by 25 feet long by 4 feet deep. The soil from this test pit was sand with lots of roots. A crushed drum was found near the ground surface in this test pit. No elevated PID readings occurred.

Test Pit #9D was dug approximately 20 feet to the north of Test Pit #9C. This test pit was 4 feet wide by 6 feet long by 4 feet deep. The soil from this test pit was sand with lots of roots. No drums were found in this test pit. No elevated PID readings occurred.

There was garbage on the surface only between Test Pit #9B & #9C. In addition, several small metal lids were also found in this area. Test Pits #9B, #9C and #9D were backfilled with soil

Test Pit #9E was located approximately 30 feet north of #9C. A test pit was located here as there was a drum exposed in a berm facing west. This test pit was started about 10 feet north of the exposed drum in the small rise, at the northern end of the cleared area. Before digging, a hole was found on the east side of the rise where four more drums could be seen. The PID reading from the exposed drum was 400 ppm (inside). A drum was also found on the south side of this excavation. It was decided not to dig any deeper for fear that exposed drums would roll down the hill toward the swamp. This last drum contained an orange/red rubbery substance, however, no elevated PID readings were detected. A drum was located about 30 feet down the hill with a reddish/black substance, but much harder than the other material. EPS excavated the area out to about 20 feet to the east to find the extent of the drums. The last pit was dug on the south end to find the extent of drums there. The total dimensions of this area were 18 feet wide, by 25 feet long, with drums stacked both singly and doubly. Two more drums were found on the south end, and gave HNu readings of 30 and 12 ppm, respectively. One of the drums contained a thick, amber liquid with a PID reading of 4 ppm. NYSDEC personnel took a sample of this liquid. It is estimated that there are at least 10 - 12 drums buried in this area. This whole area (Test Pit #9E) was covered with 10 mil plastic sheeting and soil.

The overpacks from Test Pits #9 and #9A were buried in Test Pit #9A. Test Pits #9 and #9A were covered with plastic sheeting and secured with soil placed on top.

## 2.3 SITE RESTORATION



The test pit excavations and the surrounding areas that were disturbed had a 6-inch to 1 foot layer of imported topsoil placed on top. EPS imported topsoil from F. Palumbo, Dover Plains New York and from Richard Allen Sand and Gravel, Amenia, New York. The topsoil was placed, leveled and compacted using the backhoe. Subsequently, fertilizer and seed were mixed with the topsoil by using a rake. A layer of straw mulch was placed on top surface.


REPORT.WPD


TAMS

100115




# **FIGURES**







Appendix A


Test Pit Photographs




Above: Test Pit #1, Beginning Excavation.








Above: Debris Pile From Test Pit #1.









Above: Test Pit #1 After Topsoil, Seed, and Mulch.








Above: Facing West, Test Pit #2.




Above: Bottom Of Test Pit #2, Facing North.








Above: Uncovering Drum In Test Pit #2.









Above: Second Drum In Test Pit #2.








Above: Test Pit #2 After Topsoil, Seed, and Mulch.








Above: Test Pit #3, Facing South.









Above: Beginning Of Test Pit #4.


Below: Debris Pile From Test Pit #4.





Above: East Wall Of Test Pit #4.








Above: Beginning Of Test Pit #5.









Above: Facing Southwest. Test Pit #5.









Above: Facing West, Test Pit #6.









Above: Pressure Tank From Test Pit #7.








Above: Facing West, Test Pit #8.









Above: Drum Containing White Powder From Test Pit #9.




Above: Metal Container With Plastic Lining From Test Pit #9.








Above: Visible Drums In Southern Corner Of Test Pit #9. ( 9A








Above: Leaking Drum From Test Pit #9. (9A)







Above: Beginning Of Test Pit #9B.








Above: Leaking Drum In North Corner Of Test Pit #9. (9E)

Below: Buried Drums In North Corner Of Test Pit #9. (9E)





Above: Plastic Placed Over Drums In Test Pit #9. ( 9 & 9A )

Appendix B

Test Pit Logs

TAMS CONSULTANTS, INC.

	PROJECT: Old Amenia Landfill	CONTRACTOR: Environ. Products and Services	DA
	PROJECT NO.: 6130	LOCATION: Dutchess County, New York	TIM
	WEATHER: Rain	EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAN
	WATER LEVEL: N/A	Length 30', Width 8', Depth 17'	1
-	Depth (ft) OVA	SAMPLE DESCRIPTION, REMARKS AND STR.	ATUA

Ī	PROJECT:	Old Amenia L	andfill CONTRACTOR: Environ. Products and Services	DATE: Sept.9-10, 1998
	PROJECT N			TIME: 10:00 am
	WEATHER:		EQUIPMENT: JD 410D Backhoe. JD 590D Excavator	
. \	NATER LEV	/EL: N/A	Length 30', Width 8', Depth 17'	
- [	Depth (ft)	OVA	SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES
	į.	Readings	The second second from the second from the second s	TOWIGHANGES
T	ě ·			
- :		0 ppm	Very bony, gravely fill material, some glass bottles	
ł	4			
	1			
ı	·		Metal bedframe found (9/10/98)	The second secon
-	*1			
ŀ	2			
	1	Same of the first		
ŀ	1	40 ppm		
		******		
ŀ	3, 1, 1, 1		Garbagé and debris layer begins	
	1			
ŀ	į			
1				
ŀ	4	100 ppm	Mostly garbage at this depth, sheets, paper, plastic, bottles	
ı	1			
ľ		80 ppm		
1		125		
ľ	<b>5</b>	125 ppm	Strong methane odor when removing debris	
L				
Γ	Ì			
-	6	3 ppm		
		Оррии		·
-				grande de la Companya
				•
- -	7		Bony fill material begins again, metal lid found	اليون والتجا فيودو إطاعتها للا الالولاد ووالمعتقدة للا
1		:	- Contract to the contract to	[
ŀ	i .		Newspaper dated 1971found	
ı				
-	8	10 ppm	Large slab of material found, about 5' wide, 6-8" thick, dark gray color, looks	like subbase for road
ŀ				
- 9	9	.	Garbage and debris begin again	<del></del>
1				
ŀ	· :			
	IU	_	Crushed 55-Gallon drum (9/10/98)	
		.		
	•			
	.			
	''.			
پَا				
C	omments	*		

This test pit was started on September 9 with the backhoe. As only 12 depth was achieved, EPS re-excavated the hole on



TAMS CONSULTANTS, INC.	TEST PIT LOG	TEST PIT NO.: TP- 1
PROJECT: Old Amenia Landfill	CONTRACTOR: Environ. Products and Services	DATE: Sept. 10, 1998
PROJECT NO.: 6130	LOCATION: Dutchess County, New York	TIME: 1600
WEATHER: Sunny	EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAMS REP.: J. Egan, S. Deyette
WATER LEVEL:	Length 25', Width 4', Depth 17'	
Depth (ft) IOVA	SAMPLE DESCRIPTION, REMARKS AND STR.	ATUM CHANGES

	Old Amenia L	andilli		Environ. Products		TIME: 1600	
PROJECT NO.: 6130 WEATHER: Sunny		<u> </u>	LOCATION: Dutchess County, New York  EQUIPMENT: JD 410D Backhoe, JD 590D Excavator TAMS REP.: J. Egan, S. Deyette			- 0 D	
				ID 590D Excavato	or I I AMS HEP.: J. Ega	in, S. Deyeπe	
WATER LE	VEL:			th 4'. Depth 17'			····
Depth (ft)	OVA Readings		SAMPLE (	DESCRIPTION, RE	MARKS AND ST	RATUM CHANGES	
• • • • • • • • • • • • • • • • • • • •		Garbage and debris	s layer continues				
- 12	45, 100 ppm	DEC takes soil sam	nple, very strong,	sweet odor. (Test p	oit completed on 9	/9/98).	. ···
•	120 ppm (Hnu)						
- 13				• . •	·		
· .			٠.				
-14	30 ppm (Hnu)	Crushed drum foun	1 <b>d.</b>				
- 15		<u>-</u>					
r			· .	1 - <del>1</del> - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			
-16		Garbage and debri	is layer continues	.:			
-							
- 17	40, 140 ppn (Hnu)	Bottom of hole, DE	EC takes soil samp	ole, readings betwe	en 100-300 ppm	from bucket	
- 18					··· ,	-, · · · · · · ·	
- 19			•				
	'		.*				
- 20							•
						e de la companya de l	
- 21					•		£**
-	' ·		** <u>*</u>			Eligible Communication	
- 22	·						

## Comments

These depths were achieved in the new excavation of TP-1.

Test pit excavated on 9/10/98 in an adjacent location using an excavator.

TEST PIT LOG

TEST PIT NO.: TP-2

-		Old Amenia L	andfill	CONTRACTOR: Er	viron. Products and S	ervices	DATE: Sept. 9-10,	1998
	ROJECT N			LOCATION: Dutch	ess County, New York	<b>,</b>	TIME: 1550	
	EATHER:		1.	EQUIPMENT:JD 41	0D Backhoe, JD 5900	D Excavator	TAMS REP.: J. Ega	n, S. Deyette
/ W/	ATER LEV	EL: N/A		Length 35', Width 6	. Depth 17'			
De	epth (ft)	OVA -		SAMPLE DES	CRIPTION, REMARK	S AND STRA	ATUM CHANGES	
L		Readings		, <del>-15</del> , <del></del>				
· • • • .		0 ppm	Bony fill material for	top layer, no garbag	e			
							7 <del>7</del> 77.	
. [1		2 ppm	Found 55-gallon drui	m on its side on nort	h wall of northeast end	d of excavation	on, empty. Metal bed	frame found
į.		(Hnu)	about 2 feet north.					
:		0 ppm	<b>3</b> 1					
	de en			and the second of the second	المتعارف الم	a series of the series		
- 2	14						<u>.</u>	
. 1					e je sa kalika kalendar	Bara jara (jara)		
		8 ppm	Found 5-gallon pail,	crushed				
-3	4 · · · ·	,						
			$f_{i} = f_{i} + \cdots + f_{i}$			,	en de la companya de	
•								
					the second secon			
- 4	,							• • • • • • • • • • • • • • • • • • • •
		•						
-		0 ppm	2-gallon metal pail fo	und with oily substai	nce on it			
-								
- 5		* **.	Garbage and debris	ayer begins				
			, the way is a fire					• •
-	·					•		,
- i		*		والمستناء والمستناء	Committee of the second	: . <del>-</del>		
- 6		6, 11 ppm		the first of the				.•
1						•		
1								,
- 7			Small bike frame four	nd	• • • • • • • • • • • • • • • • • • • •			İ
			***		•	•		
	,	* * * * * * * * * * * * * * * * * * * *	The second of th					
								,
- 8		0 ppm	Another 55-gallon en	npty drum found: Re	mington Rand Shaver	Division writt	ten on top.	
		(Hnu)	بالمناه المستعدد المس		5			
			1.11				•	
	ļ	.						ł
1.9			A lot of glass, cans, t	ottles at this depth.	A possible IV bottle w	as found. Lar	rge sheet of metal ai	so found.
ŧ	į.			1				
1-!						-		
	,		***					
- 10	ı		,	•			.*	
1			· -	· · · · · ·				-
		ŀ	•			*		·
			- , 1					
	'		· <u>-</u>					

Comments

This excavation was started on September 9 with the Backhoe. Because only 12 feet was achieved. EPS re-excavated the hole with the excavator on September 10.



		= -		 and the second of the second	
TAMS	CONSULTANTS	, INC.	TEST PIT LOG		TEST PIT NO.: TP-2

	Old Amenia L	.andfill	CONTRACTOR: Environ.		DATE: Sept. 10, 1998
PROJECT NO.: 6130		LOCATION: Dutchess Co	unty, New York	TIME: 0930	
WEATHER: Sunny			EQUIPMENT: JD 410D Ba	ackhoe, JD 590D Excavator	TAMS REP.: J. Egan, S. Deyette
WATER LEV			Length 32', Width 6', Dept		
Depth (ft)	OVA Readings	. Law engl		ION, REMARKS AND STR	ATUM CHANGES
3.2		Fill material begins	again.		
-					
- 12		(Test pit completed	9/9/98)	*** **********************************	· ·
			-		7°° 1°° 1
•		••			
		4. , *** 4		and it agrees are distinguished in the control to the control of t	
- 13		Garbage and debris	laver starts again		
			ay or oranto again.		
• · · · · · · · · · · · · · · · · · · ·		-			
	,				
-14		Bony fill material be	gins again.		
Andry tea			- ·		- · · · · · · · · · · · · · · · · · · ·
• 1,	[ ·			•	
		<u> </u>		· · · · · · · · · · · · · · · · · · ·	
- 15	1.	*.			
			•		
_					
-16	0.3 ppm	, '			22.1
	(Hnu)	*	•		
<b>-</b> •	1		•	٠,	
. <del>.</del> .					•
- 17		Bottom of hole, DE	C takes soil sample.Some n	noisture at this depth.	:
•	İ	i ·			
		1			
- 18			•		
,		,		A second of the	
•		1		•	
40	, ,	*			
- 19				•	
	1			•	
-					•
- 20					
- 20					
	,		•		·
					4
- 21					
[ • •		· · · .		-	
<b>.</b>				•	
		1. 1. 1. 1. 1. 1. 1.	*		en en en en en en en en en en en en en e
- 22				**	•
- 44			•		
•		<b></b>		-	· · · · · · · · · · · · · · · · · · ·

Comments

<sup>\*\*</sup> Test pit excavated on 9/10/98 in same location using an excavator. Expanded test pit to include the 55-gallon drum on north wall.

TAMS CONSULTANTS, INC.

TEST PIT LOG

TEST PIT NO.: TP-3

PROJECT: Old Amenia Landtili PROJECT NO.: 6130			CONTRACTOR: Environ Products and Services	DATE: Sept. 10, 1998
			LOCATION: Dutchess County, New York	TIME:0930
WEATHER.			EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAMS REP.: J. Egan, S. Deyette
WATER LEVEL: N/A			Length 32'. Width 6'. Depth 18'	
Depth (ft)	HNu		SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES
	Readings	1 1 1 1		
<u></u>	0 ppm	Typical bony fill mate	erial	
<u> </u>			والرابات والمستريب والمتاري والمتار والمستمسين يستريب والأرابات	
				_
-		The State of the S		
- 2				
•	-		and the second of the second o	the first section is
* 1				
•3				which is a second of the secon
	• •	vvasning machine to	und, garbage and debris layer begins.	
		transport in the		
- 4				
				•
Í	2			
- 5		Fill material starts.		
- ·	•			
r				
- 6				
İ				
1				
				*
- 7	·	Newspaper dated 19	70 found, garbage and debris layer begins again	
			· ·	•
	·		en en en en en en en en en en en en en e	
- 8				•
-				
		* *		en en en en en en en en en en en en en e
- 9	0 ppm	Automobile gas tank	found	<del>-</del>
	` '			•
• .				
,				
- 10				
	٠	<del>-</del>		
,				
- 11		Fill Material begins ag		
; '		i iii waterial begins a	<b>jain</b>	
Committee	<u> </u>	<u> </u>		
Comments				

This excavation was started with the Backhoe, then finished with the excavator once it arrived onsite.

TAMS CONSULTANTS, INC.

TEST PIT LOG

TEST PIT NO.: TP-3

PROJECT: Old Amenia Landfill	CONTRACTOR: Environ. Products and Services	TIME: 0930			
PROJECT NO.: 6130	LOCATION: Dutchess County, New York				
WEATHER: Sunny	EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAIVIS REF., J. Egan, S. Deyene			
WATER LEVEL: N/A Length 32', Width 6', Depth 19'					
Depth (ft) HNu Readings	SAMPLE DESCRIPTION, REMARKS AND STR	ATUM CHANGES			
- 12					
- 13 Garbage a	nd debris layer starts again.				
-14 -18					
- 15 Newspape	er dated 1970 found.				
	becomes darker (brown).				
-16 Soil color l	becomes darker (blown).				
- 17		· · · · · · · · · · · · · · · · · · ·			
- 18 Found 5-g	gallon Texaco oil container, another 1970 newspaper, and a 196	8 paper			
- - 19 0 ppm Bottom of	hole, DEC takes soil sample				
	and the second of the second o				
- 20					
- 21					
-					
- 22	=				

Comments

A syringe was found in the debris pile, from unknown depth.

PROJECT NO.: 6130  LOCATION: Dutchess County, New York  WEATHER:Sunny  EQUIPMENT: JD 4100 Backhoe, JD 590D Excavator  TAMS REP.: J. Egan, S. Deyette  WATER LEVEL: N/A  Length 25', Width 6', Depth 17'  Depth (ft)  HNu  Readings  Typical bony fill material.  -1  -2  Garbage and debris layer begins.  -3  -4  -5  Several tires buried in this area, as well as small pieces of metal.	PROJECT:	Old Amenia L	andfill	CONTRACTOR: Envir	on. Products an	a Services	DATE: Sept.	11, 1998	
WATER LEVEL: N/A  Depth (ft) HNu Readings  Typical bony fill material.  -2  Garbage and debris layer begins.	PROJECT N	O.: 6130							
Depth (ft) HNu Readings Typical bony fill material.  Garbage and debris layer begins.			-			90D Excavator	TAMS REP.	: J. Egan, S	S. Deyette
Readings Typical bony fill material.  Garbage and debris layer begins.	WATER LEV	'EL: N/A				**	1		
Garbage and debris layer begins.	Depth (ft)	1		SAMPLE DESCR	IPTION, REMA	RKS AND STR	ATUM CHAN	GES	
-3 *** - 1 ***	-		Typical bony fill mat	erial.				· ·	
3	•	مدر شد							<del>ar</del> a mere. Tarih
-5 Several tires buried in this area, as well as small pieces of metal.	- 2		Garbage and debris	layer begins.					
Several tires buried in this area, as well as small pieces of metal.	· .								
- 5 Several tires buried in this area, as well as small pieces of metal.	-								
- 5 Several tires buried in this area, as well as small pieces of metal.	-4								4
	- 5		Several tires buried	in this area, as well as	small pieces of r	metal.			



Two hot water heaters found at this depth.

Comments



PROJECT: Old Amenia Landfill			CONTRACTOR: Environ.		DATE. Sept. 11,	1990
PROJECT NO.: 6130		LOCATION: Dutchess Co	ounty, New York	TIME: 0850		
WEATHER: Sunny			EQUIPMENT: JD 410D B	ackhoe. JD 590D Excava	itor TAMS REP.: J. B	gan, S. Deyette
WATER LEVEL: N/A			Length 25', Width 6', Dep	th 17'		· · · · · · · · · · · · · · · · · · ·
	HNu Readings		SAMPLE DESCRIP	TION, REMARKS AND S	TRATUM CHANGES	
		Garbage and debris	continue.		<u> </u>	
- 12			10 (10 (10 (10 (10 (10 (10 (10 (10 (10 (			
· •						
- 13 -						
-14						
<b>- 15</b>		Fill material begins	again.	水道です。 (*) 		
-16				est Popularios		
- - 17	0 ppm	Bottom of hole, no	soil sample taken.			
-		,		·		
- 18	-					· · · · · · · · · · · · · · · · · · ·
- 19					•	
-						*
- 20						
- 21 - 22	- -					
	1	. [	•			

. . .

TAMS CONSULTANTS, INC. TEST PIT LOG

TEST PIT NO.: TP-5

	٥.
200	
	ř
	,
_	


			CONTRACTOR: Environ. Products and Services DATE: Sept. 11, 1998				
WEATHER: Sunny			OCATION: Dutchess County, New York		TIME: 1030		
			QUIPMENT: JD 410D Backhoe, JD 5	90D Excavator	TAMS REP.: J. Egan, S. Deyette	-	
WATER LEV	/EL: N/A	Į	ength 20'. Width 5'. Depth 17'			_	
Depth (ft)	HNυ	4.	SAMPLE DESCRIPTION, REMAI	RKS AND STRA	TUM CHANGES		
	Readings						
<del></del>		Typical bony fill mater	ial, large depression.				
				·	<del></del>		
•		the transfer of the second			and the second of the second o		
_ 4		Garbage and debris la	wer hading	•			
	:	Garbage and debits is	lyer begins.	· ',,			
	[ · ·						
·							
		-					
- 2		Car bumper found.	Land of the first of the same of the same		By Assistance Company		
•				1. 1. 1.			
1			agent the same of the same		the grade with the second of		
-3							
\$ 1.4%.							
- 4			(1965년) 전환 12일 - 12일 전환 12일 (1965년)				
1							
	٠.		기본을 하다 하는 것 같은 것이다.				
n   i = +							
-5	**	* * * * * * * * * * * * * * * * * * * *		• .			
	•						
	1			•			
				-	• • • • • • • • • • • • • • • • • • •		
- 6	1 ppm	Pumla colored rag to	nd, 25-30 garage receipts from Sharo	n Carago datad	1066		
•	l' ppin	ir diple-colored lag lot	ind, 25-30 garage receipts from Sharo	n Garage dated	1900.		
<u>-</u>		Fill material begins ag	-i-	. •			
ī		Fili material begins ag	ain.				
- 7	· .						
					•		
<u> </u>				and the great of the	and the second s		
<del>-</del>  -	1						
			· ·				
		1.		A STATE OF THE STA	•		
8							
8							
8							
8							
-							
9							
9							
9							
9							
- 10							



AMS CONSULTANTS, INC. TEST PIT LOG TEST PIT NO.: TP

	NSULTAN		TEST PIT LOG  [CONTRACTOR: Environ. Products and Services	TEST PIT NO.: TP-5 DATE: Sept. 11, 1998
PROJECT: Old Amenia Landfill PROJECT NO.: 6130 WEATHER: Sunny			LOCATION: Dutchess County, New York	TIME: 1030
			EQUIPMENT: JD 410D Backhoe. JD 590D Excavator	
VATER LEV			Length 20'. Width 5', Depth 17'	
	HNu	Γ	SAMPLE DESCRIPTION, REMARKS AND STR	ATUM CHANGES
Depth (ft)			SAMPLE DESCRIPTION, NEWATING AND OTT	
<del></del>	Readings	Fill material continu	100	
				<u> </u>
• •		Another IV bottle fo	orio.	
			s begins again, DEC takes soil sample.	
12	2 ppm	Garbage and debri	s begins again, DEC takes son sample.	en en en en en en en en en en en en en e
				<del>-</del>
	. 1			
		<b>5</b> 7		
13		Fill material begins	again, much more sandy than previous fill layers.	
•				
	•			
		· / .		
4	ł			
*	<b>]</b>	1		
•	1			and the second s
15				
16				
•		Ť		
				er.
4-	0	Ballan of bala as	eeil eemele taken	
17	0 ppm	Bottom of hole, no	soil sample taken.	•
	1			
	p			
18	1			
		· ·		$\mathcal{L}_{\mathcal{A}} = \mathcal{L}_{\mathcal{A}} = $
19				
20				
1.0	1	1.		
•				
21 -				-
	1 .			
		•	•	
	-			
· 22 - <sup></sup>	_		en en en en en en en en en en en en en e	
- 22				
		1		

Comments



PROJECT:	Old Amenia L	andfill CONTRACTOR: Environ. Products and Services	Sept. 11, 1998
PROJECT NO.: 6130		LOCATION: Dutchess County, New York	TIME: 1200
WEATHER:		EQUIPMENT: JD 410D Backhoe. JD 590D Excavator	TAMS REP.: J. Egan, S. Deyette
WATER LEV	/EL: N/A	Length 25', Width 5', Depth 13'	
Depth (ft)	HNu	SAMPLE DESCRIPTION, REMARKS AND STRA	TUM CHANGES
1 1	Readings	territoria de la companya de la companya de la companya de la companya de la companya de la companya de la comp La companya de la co	
	0 ppm	Typical bony fill material.	
12		المن المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم المنظم	and the state of t
-11			
	ļ		
·			
<del></del>			المنافقة في المستقد والمنافقة المنافقة المنافقة المنافقة المنافقة المنافقة المنافقة المنافقة المنافقة المنافقة
2	:	Garbage and debris layer begins, bags of leaves, bottles, wood, and tires.	
		్ కార్పులో ప్రామానికి స్టాన్స్ ఉంది. స్టాన్స్ ప్రామానికి స్ట్రామ్ క్రామ్ క్లాన్స్ క్లాన్స్ స్ట్రామ్ కోస్ట్ స్ట క్లాన్స్ ప్రామానికి స్ట్రామ్ క్లాన్ క్లాన్స్ స్ట్రాన్ క్లాన్స్ క్లాన్స్ క్లాన్స్ క్లాన్స్ క్లాన్స్ క్లాన్స్ క్	
e Agentalia Barana Barana			
3			
1			
			化二烷医多类合物 數學學 化二氯化二甲基乙二
ģ.			
	1 ppm	Soil seems slightly damp, possibly runoff from the rise, soil appears gray in o	color, newspaper dated 1972
		found.	
4			
_			
<b>3</b>	· · · · · · · · · · · · · · · · · · ·		
1			
1		and the second of the second o	mages as
6	:		(x,y) = (x,y) + (x,y
N			
1			
ì			
7			
		and the control of the first position of the control of the contro	and the state of t
8		Gravely sand fill material begins.	
1			
}			
\			
9	,		
			wife in the figure
		DEC takes soil sample from this depth.	
	,		
10			
···			
	i		
1	•	and the control of t	The second secon



Comments

TAMS CONSULTANTS, INC. PROJECT: Old Amenia Landfill			TEST PIT LOG  CONTRACTOR: Environ	Products and	Services	DATE: Sept. 1	1, 1998	
PROJECT NO.: 6130 WEATHER: Sunny			LOCATION: Dutchess C	ounty New Y	ork	TIME: 1200		
			EQUIPMENT: JD 410D	Backhoe JD 5	90D Excavator	TAMS REP.:	J. Egan, S. Deyette	е
		<u> </u>	Length 25', Width 5'. Der	th 13'				
VATER LE		<del>' </del>	SAMPLE DESCRIF	TION DEMA	DVS AND STR	ATUM CHANG	FS	
Depth (ft)	HNu Readings		SAMPLE DESCRIP	TION, REMA		ATOM CHARG		
		Fill material continu	es.					
			-			,		
•								
12					••			
			•	•	-	-		
	1.							
			•					
13	0 ppm	Bottom of hole, no	soil sample taken.				•	
	1,							
		'					٧.	
2.5		ľ.						
14		/				*.*	* *	
411 4	4.17		÷	Υ.				
	,	<b>!</b>			· · ·	e e e		
			_,					
15					**			
						•		
•						•		
					•			•
16				,				
·•	1					•		
	1		•				•.	
						•	•	•
- 17					•			
•	İ							
						•	• •	
	. ]							
- 18		•		**				•
- 10					, ·			
	** .			•	•			
- 19		1			٠		•	
- 13				* .	•			
				-				
· .						•		
. 20	1		•					
- 20	1						And the second of the second	
						•	•	
•								
		*	•					
- 21	1-		- · ·		<del>-</del> ,			
· .		·	4				•	
-		-				. · .		
	1	-	- <del>-</del>					
- 22	- ~ <del>.</del>	1	•	-	•	-		

PROJECT: Old Amenia Landfill PROJECT NO.: 6130			TEST PIT LOG  CONTRACTOR: Environ. Products and Services	TEST PIT NO.: TP-
			LOCATION: Dutchess County, New York	TIME: 1355
WEATHER:			EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAMS REP   Legan & Dougha
WATER LEV			Length 30'. Width 6'. Depth 19'	Trans Her o. Egan, S. Deyene
Depth (ft)	HNu		SAMPLE DESCRIPTION, REMARKS AND STR	ATUM CHANCES
	Readings		Onwir EL DESCRIF HON, REMARKS AND STA	ATOM CHANGES
· .	90	Garbage and debris	s laver continues	
	<u></u>			<u>·</u>
÷ *	,		titi oli tai kantai kantai kantai sa marantai sa marantai kantai kantai kantai kantai kantai kantai kantai kan Marantai kantai	
12				
	1			
•				
· 13				
,				
	'			
14	0 ppm	Found steel pressur	re tank, 300-500 gallon, 36" diameter, 6' tall	
7				
15	4 ppm		회원 회원이 이 회사님의 그를 받는 생각이 되었다.	Marie Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Carlo Ca
	* 1			
16	3 ppm			and the state of t
			and the second of the second o	
17		e i cui me e è con e	and the state of the state of the state of the state of the state of the state of the state of the state of the	
7	•	•		
18	•	Found noweness d	-1-14074	
		Found newspaper d	ated 1974.	
			والمناب ومصيد والصوا	The state of the s
	•			
19		Bottom of hole. DEC	takes soil sample	
† -		Tanom of nois, DEC	ranes sull sample.	
				:
		*		
20				
· .	ĺ			and the second s
` :				
1		·		
21				
0		and the second		
<u>:</u>				
22				

Comments
A lot of min

A lot of mimeograph paper (purple) was found throughout this excavation.



"1001"

TAMS CONSULTANTS, INC. PROJECT: Old Amenia Landfill			Security of the security of th	Camb 11 1000
		andfill	CONTRACTOR: Environ. Products and Services	Sept11, 1998 · · · · · · · · · · · · · · · · · ·
PROJECT NO.: 6130			LOCATION: Dutchess County, New York	
WEATHER: Sunny			1	TAMS REP.: J. Egan, S. Deyette
WATER LEV	EL: N/A		Length 30', Width 6', Depth 19'	
Depth (ft)	HNu Readings		SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES
	0 ppm	Typical bony fill mat	erial.	
1	*.	Garbage and debris	layer begins.	
•				•
•	* *			a control of the cont
•			•	•
· <b>2</b>				
•	_ ·			
•	0 ppm			•
_		L . ,		d
3		Garbage and debris	is slightly damp, consists mostly of paper, plastic, woo	d, and glass.
		* * * .		•
		* *****		•
	• .			
- 4				
This eye				
•	0.5 ppm		•	
•				, 3
- <b>5</b>	- 1 m		معاصلها والمناف والمحمل والمناف والمناف المناف والمناف والمناف والمناف والمناف والمناف والمناف والمناف والمناف	er e e e e e e e e e e e e e e e e e e
	1			
•· , · · · · · · ·	1 ppm			
- 6	1			
	,	,	<del></del> -	
-		,		
- 7		· [ *		•
			and the second s	
-			•	
	•			
- 8		Newspaper dated 1	974 found	
-	2 ppm		•	•
•	PP	'	•	
- 9	1	1		
	1	<u> </u>	والمرابع والمرابع والمعارضين والمعتار والمعتار والمستوار والمرابع والمتابع	
_	1	4		
•				
- 10	1			

Comments

TAMS CONSULTANTS, INC. TEST PIT LOG

TEST PIT NO.: TP-8

	Old Amenia l		rvices   Sept. 11, 1998
PROJECT	NO.: 6130	LOCATION: Dutchess County, New York	TIME: 1545
WEATHER	: Sunny	EQUIPMENT: JD 410D Backhoe, JD 590D	
WATER LE		Length 25', Width 6', Depth 17'	
Depth (ft)	HNu	SAMPLE DESCRIPTION, REMARKS	AND STRATUM CHANGES
	Readings	Orani de Deborni, riori, richira no	
<del></del>	0 ppm	Typical bony fill material.	
	Оррии	Typical borry lift material.	
	1	The second of the second secon	
[ ]		Car bumper found, garbage and debris layer starts.	and the contract of the contra
-			
- 2		Large boulder found, 4' by 6'.	
	1		
-	0 ppm		
-3			
	1	The said of the state of the said of the s	
en en en en en en en en en en en en en e			
		Popu fill motorial basing again	
		Bony fill material begins again.	
	l	I 나는데 조한 설계활동한 및 함스 (111) 각 호텔 보호	
	0 ppm		
	1 2		
1-5	e de la companio	and the second s	and the state of the second section of the second of the s
-			The second secon
- 6	* ,		
j .	1.0		
-	0 ppm		
1			
1-7			
11.			
l_ {		ره و از این دست فیصدهای این در و محمدهای در از دیگرای و گردیست در میآن است و چوای آمریست این در در از در در از در در در در در در از گردی از در در در در در در در در در در در در در	
	1		
Ĭ			the second of th
]			
- 9	1	Garbage and debris begins again.	
	1	وه رئي صوبهٔ و دانده العربي مطبعه تبيره العباري بالرابط و الدين الراجي وبناه بيند الرابطي وصد	
- 1	1 .		
- 10			
<b>1</b> \$		The second of th	
1-1			
1 1 .	1		



TAMS CONSULTANTS, INC.

TEST PIT LOG

TEST PIT LOG

PROJECT: Old Amenia Landfill

CONTRACTOR: Environ. Products and Services

DATE: Sept. 11, 1998

PROJECT: Old Amenia Landfill						
PROJECT NO.: 6130		TIME: 1545				
WEATHER: Sunny	EQUIPMENT: JD 410D Backhoe, JD 590D Excavator TAMS REP.: J. Egan. S. Deyette					
WATER LEVEL: N/A	Length 25', Width 6', Depth 17'					
Depth (ft) HNu	SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES				
Readings						
Garbage and debris	laver continues.					
Newspaper dated 19	75 found.					
Tremspapor sales						
- 12 Soil has reddish cold	or, most likely from crushed bricks.					
12						
-13						
The same of the same						
-14						
- 15						
-16	<del>Production of the Control of the Co</del>					
- 17 Bottom of hole. DEC	C takes soil sample.					
- 18						
The second secon	and the second of the second o					
- 19						
- 20	en de la companya de la companya de la companya de la companya de la companya de la companya de la companya de La companya de la companya de la companya de la companya de la companya de la companya de la companya de la co	مست				
-21						
		- · ·				
- 22						
Comments						

This

	e sterome e to an idea of a constant of a co	And the second s	The state of the s		The first transfer of the second of the seco	Tables (MS) on descent which is a common with the common with the common way to be common with the common with the common way to be common with the common with the common way of the common way to be common with the common way of
Ā 4	a tangga di kabupatèn di Regional di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupat Regional di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn di Kabupatèn					e de la companie de la companie de la companie de la companie de la companie de la companie de la companie de La companie de la companie de la companie de la companie de la companie de la companie de la companie de la co
TAMS CC	NSULTAN	ITS, INC.	TEST PIT LOG	and the second of the second o	TES	T PIT NO.: TP-9
PROJECT: Old Amenia Landfill			CONTRACTOR: Environ	. Products and Services	Sept. 14, 1998	
PROJECT N			LOCATION: Dutchess Co	ounty, New York	TIME: 0840	
WEATHER:	Sunny		EQUIPMENT: JD 410D B		vator TAMS REP.: J. Eg	an, S. Deyette
WATER LEV	/EL: N/A		Length 6', Width 4', Depth	1 4'		
Depth (ft)	HNu Readings	.,	SAMPLE DESCRIP	TION, REMARKS AND	STRATUM CHANGES	
d de la constant de l	0 ppm	Typical bony fill mat	erial.			
1						
					u fire assign	
2	0 ppm			A STATE OF THE STA	en en en en en en en en en en en en en e	
<b>.3</b>		1	um found with *Geigy Agrico		•	
4		powder. This contain	etal container with plastic in ner was placed in an 85-ga ners can be seen in the ex	allon overpack.		ample of white
5						
⊹6						44 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4 - 4
	·					
- 7				-		· · · · · · · · · · · · · · · · · · ·
• • • • • • • • • • • • • • • • • • •		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			indigente de la companya de la companya de la companya de la companya de la companya de la companya de la comp La companya de la companya de la companya de la companya de la companya de la companya de la companya de la co	

- 10

11

Comments

No garbage was found in this excavation.



TAMS CONSULTANTS, INC. PROJECT: Old Amenia Landfill			TEST PI	T LOG		I		TEST PI	T NO.: TE	2-9A
			CONTRAC	TOR: Enviro	n. Products and	Services	Sept. 14, 1	998		
PROJECT N			LOCATION	N: Dutchess	County, New Yo	ork	TIME: 084	0		
VEATHER:	Sunny		EQUIPME	NT: JD 410D	Backhoe, JD 59	00D Excavato	r TAMS REF	.: J. Egan,	S. Deyette	
VATER LEV	/EL: N/A			Width 4'. Dep		-				
epth (ft)	HNu Readings	·	SAM	PLE DESCRI	PTION, REMAP	RKS AND ST	RATUM CHAI	NGES		
	0 ppm	5 drums are visible	at surface. 4	of the drums	are empty. 1 c	ontained a so	olid, cloudy su	bstance. Us	ed a	
<del></del>		hammer to break in	to small pied	es. DEC take	es sample of the	ese pieces.				
1 ,				-		- -				
	20 ppm	Drum found has a f	PID reading of	of 100 ppm. T	his drum conta	ined a black,	oily substanc	e. DEC take	s sample	
4	15 ppm	on the drum. The co	ontents from	this drum we	re placed in an	85-gallon ove	erpack There	are 5 more o	drums that	
2	15ppm	are visible in the wa								
+ #4				184		•		· ·	• •	
					٠.					
	15 ppm	/								
	13 × 13 × 1		1982		-	7	·			
							, -			
4		This is the bottom	of the below	no soil sampl	ac taken	•		÷ .		
<b>-</b>		This is the bollott	or the noie, i	io son sampi	es taken.	•		4		
								,	*	
•										
5										
_			•			-		'		•
							•			
6									•	
	ļ					-				
			•						•	
	•					5	•			
7.	1								-	
	· .									
8 .										
			•							
	i `									
9	1.	,							•	
	1	1 .					•			

Comments

No garbage was found in this excavation.

TAMS CONSULTANTS, INC PROJECT: Old Amenia Landfill			CONTRACTOR: Environ. Products and Services	Sept. 14, 1998			
PROJECT NO.: 6130 WEATHER: Sunny WATER LEVEL: N/A			LOCATION: Dutchess County New York	TIME: 0840			
			EQUIPMENT: JD 410D Backhoe, JD 590D Excavator TAMS REP.: J. Egan, S. Deyette				
			Length 25', Width 4', Depth 4'				
		·	SAMPLE DESCRIPTION, REMARKS AND STR	ATUM CHANGES			
Depth (ft)	HNu Readings						
	0 ppm	Sandy, brown fill n	naterial. Lots of root matter.	المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراقع المراق 			
-				Control of the second of the s			
1							
- 1			er i kaj la la la jegaj em p <del>eksy</del> i kaj ligaj k	المراجع المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج المحاج الم المحاج المحاج			
· .	-						
_				The second of th			
	1						
<u>- 2</u>	0 ppm						
i i	''						
- ·		<u> </u>					
-3		1 /					
1							
. 4							
· ·							
		1 .	garan kalendar kalendar kalendar kalendar kalendar kalendar kalendar kalendar kalendar kalendar kalendar kalend				
- 5	'			and the first of the second second second second second second second second second second second second second			
1							
-							
		Bottom of hole a	o soil samples taken				
- 6		Bottom of noie, n	o son samples taken				
	· **			en en en en en en en en en en en en en e			
7			ه هم المستقطعين و المن المحكل الحريف المستقطعين المنظم المستقل والمستقل والمنظر المنظم المنظم المنظم المنظم ال والمنظم المنظم				
<b>!</b>							
- 8	· ·			. 4			
- ·							
			بمستعظم الشباس الشاسيان أرار فيباغ ربية للبارك بسالينا				
- 9							
1							
<b>I</b> -							
- 10		. [		And the second second			
	, , ,						
-		-					
1	1 :						
- 11							
1	: "						
Comments		<u></u>		v .			

TAMS CONSULTANTS, INC.			TEST PIT LOG	TEST PIT NO.: TP-9C
PROJECT: Old Amenia Landfill PROJECT NO.: 6130 WEATHER: Sunny			CONTRACTOR: Environ. Products and Services	Sept. 14, 1998
			LOCATION: Dutchess County, New York	TIME: 0840
			EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAMS REP.: J. Egan, S. Deyette
WATER LEV			Length 25', Width 4', Depth 4'	
Depth (ft)	HNu-	<u> </u>	SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES
_ <b></b>	Readings	*		
	0 ppm	Sandy brown fill ma	aterial. Lots of root matter.	
<del></del>	0 ppm -	Crushed drum found		
	o ppiii -	Crushed druin loun	u.	
			<u> </u>	
. 1	·			
	l.	· · · · ·		
• . •				
- 2	0 ppm			
•		•		4
-3	4.4			
- 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
		The state of	* · · · · · · · · · · · · · · · · · · ·	
and the same				
- 4	0 ppm	Bottom of hole, no	soil samples taken. Drum lid found.	
	1 2 3			
-				
	1,1		•	
- 5			and the second of the second o	
	1	,		
-				
٠.				
- 6	-			
		. •	• •	• • • • • • • • • • • • • • • • • • •
_				
- 7				
			and the second of the second o	and the same and t
				•
				•
- 8			•	
				•
-	1			
- 9				
	1			
•				
	1			
- 10		_		
ŀ				
		1 .		

Comments

There was glass and plastic bottles in the top 6° of this excavation.



0 ppm

	ANIO CC	MOULIAN	113, INC.	FIEST PIT LUG	1EST PIT NO.: 1P- 9D		
	PROJECT NO.: 6130			CONTRACTOR: Environ. Products and Services	Sept. 14, 1998		
(A)				LOCATION: Dutchess County, New York	TIME: 0840		
-				EQUIPMENT: JD 410D Backhoe, JD 590D Excavator	TAMS REP.: J. Egan, S. Devette		
	WATER LEV	/EL: N/A		Length 4', Width 4', Depth 6'			
	Depth (ft)	HNu Readings		SAMPLE DESCRIPTION, REMARKS AND STRA	ATUM CHANGES		
·		0 ppm	Sandy, brown fill ma	aterial. Lots of root matter.			
	-1						
# P	- 2	0 ppm					

Bottom of hole, no soil samples taken

11

Comments

No garbage or drums in this excavation.



PROJECT: Old Amenia Landfill CONTRACTOR: Environ. Products and Services PROJECT NO.: 6130 LOCATION: Dutchess County, New York WEATHER: Sunny EQUIPMENT: JD 4100 Backhoe, JD 5900 Excavator NATER LEVEL: N/A Length 30', Width 20', Depth 6' PROJECT NO.: 6130 LOCATION: Dutchess County, New York WEATHER: Sunny EQUIPMENT: JD 4100 Backhoe, JD 5900 Excavator NATER LEVEL: N/A Length 30', Width 20', Depth 6' SAMPLE DESCRIPTION, REMARKS AND STRATE Readings O ppm 1 drum is exposed on the west side of the berm, and is leaking. Another 4 of the surface through a small hole in the berm. DEC previously sampled the state of the ber	ATUM CHANGES  drums can be seen buried beneath soil underneath the drum on 9/8/98.
VATER LEVEL: N/A  Depth (ft)  HNu Readings  0 ppm  1 drum is exposed on the west side of the berm, and is leaking. Another 4 contains red/orange mater (Drum)  Find another drum on the north end of the berm, contains red/orange mater (Drum)  12. 30 ppm  2 more drums are found on the south end of the berm. 1 of the drums contains red/orange mater takes a sample of the liquid. This drum had a PID reading of 4 ppm.	TAMS REP.: J. Egan, S. Deyette  ATUM CHANGES  drums can be seen buried beneath soil underneath the drum on 9/8/98.
VATER LEVEL: N/A  Depth (ft)  HNu Readings  0 ppm  1 drum is exposed on the west side of the berm, and is leaking. Another 4 of the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm, contains red/orange mater (Drum)  Find another drum on the north end of the berm, contains red/orange mater takes a sample of the liquid. This drum had a PID reading of 4 ppm.	ATUM CHANGES  drums can be seen buried beneath soil underneath the drum on 9/8/98.
Pepth (ft) HNu Readings  0 ppm 1 drum is exposed on the west side of the berm, and is leaking. Another 4 contains the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm, contains red/orange mater (Drum)  Find another drum on the north end of the berm, contains red/orange mater (Drum)  2 more drums are found on the south end of the berm. 1 of the drums contains takes a sample of the liquid. This drum had a PID reading of 4 ppm.	drums can be seen buried beneath soil underneath the drum on 9/8/98.
Readings  0 ppm 1 drum is exposed on the west side of the berm, and is leaking. Another 4 of the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled through a small hole in the surface through a small hole in the berm.	drums can be seen buried beneath soil underneath the drum on 9/8/98.
1 down is exposed on the west side of the berm, and is leaking. Another 4 of the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled the surface through a small hole in the berm. DEC previously sampled through a small hole in the berm.	soil underneath the drum on 9/8/98.
the surface through a small hole in the berm. DEC previously sampled the s  400 ppm (Drum)  Find another drum on the north end of the berm, contains red/orange mater (Drum)  2 more drums are found on the south end of the berm.1 of the drums contains takes a sample of the liquid. This drum had a PID reading of 4 ppm.	soil underneath the drum on 9/8/98.
Find another drum on the north end of the berm, contains red/orange mater (Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	rial with rubbery texture.
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
(Drum)  2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
2 more drums are found on the south end of the berm.1 of the drums conta takes a sample of the liquid. This drum had a PID reading of 4 ppm.	ins a thick amber liquid in it. DEC
takes a sample of the liquid. This drum had a PID reading of 4 ppm.	nins a thick amber liquid in it. DEC
takes a sample of the liquid. This drum had a PID reading of 4 ppm.	ains a thick amber liquid in it. DEC
takes a sample of the liquid. This drum had a PID reading of 4 ppm.	ains a thick amber liquid in it. DEC
takes a sample of the liquid. This drum had a PID reading of 4 ppm.	
	•
5	
5	
	•
- 6 Bottom of hole, no soil samples taken.	
- 6 βοποπ of noie, no soil samples taken.	
•7	
	•
.8	
	•
· · · · · · · · · · · · · · · · · · ·	en e e e e e e e e e e e e e e e e e e
	•
	, .

Com	m	en	ts

No garbage was found in this excavation. Estimate 10-12 drums in this area.

Appendix C

Field Notes

## PROPERTY OF

T13

Name TAMS CONSULTANTS, INC.

Address 300 APOADACUS DA BLOOMFIND, NJ 07003 Phone (173) 338-6680

This book is published on a fine 50% cotton content ledger paper, specially treated for maximum archival service, and protected by a water resistant surface sizing.


Pro	ects OLD AMENTA DWI	VL	ANL	Mu	SI	Œ	3
	WA # D003060-21		: 1	1 1		• • •	ŧ:
	NYSDEC STIT # 3-1		X		• • • •	• • •	•
	TTWA				• • • •	• •	
	9/9/98-9/16/98					• •	•
					• • • •	•	•

## MINGOLO PRECISION PRODUCTS, INC.

174 South Main Street HACKENSACK, NEW JERSEY 07601 (201) 488-6300 いまのいかないはありまない

	· · · · · · · · · · · · · · · · · · ·		skin july		Φ.
			7/8/98	Flows	
Projects (continued)	• • • • • • • • • • • • • •	• • • • • •	August Annumary	TETE KONSTOLE VNYSOE	E) Ray Buonuar
		-	TX ANDUININ RE		
			A CALL EPS AND	MATTY PROPRE LOUZE	CHARLES AND
			CER X		T W/EVOLYONE
		• • • • • •	TAKE DITE WOR	A POR GENERAL RYPOL	on sucrace
			Actor No	can aven to	
			CONTAIN TOS	HAS VISTOLE GARBAGE	and partiet
			" frames an oxu	[mb]	
					ATOM! ITIA
			I sha shanek a	SXC & ABOUT POPSUTE	
			AZUS OUT AROM		
			THE AXS A	our prompression of	excustar ant
·			FOR VERSTORS BAK	if hely paper and praces,	42xc resecvit ar
	•		1027 JULY		
				10 10 10 AV 10 45 M	Rausiva
			TITE HOPEN CO	vectibes At 1943.	
	• • • • • • • • • • • • • •		CAN CERTA	AT 1/05	
		• • • • • • • •			!    <u> </u>
					11111111
	• •				

HIPTER MARKET



	<b>3</b>
9/9/98 (wr) 49/98 (com) 48000	
JU 10 MG 40.55 1 MM2 "	12 MAY TOWARDS SU EUS,
- MATERS M VERY BONY, GRAVER, SOME GLASS BOTTLES DES NO LOX LIVE SECOND BRUM TOP	
N @ 1022 30 01 40 ppm (HOLE), O AT EXEWS LIMET - BEGENS PARADING HEAVELY PASINT 123	0
1	maples store to nom
1 3 1037 48' 100 pm (HOV), 1 AT LENGT DE TO PT STO END. WELL SU	AND DE WALKERS
MOSTLY GARRICE SHEET; BOTHES, PACE (ETC )	
5"19 1044 54" BOPPIN (HOLE), IA LINUT - 7 FILAR ( ) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	words cont its
1 (3) 1014 54 BOPPM (HOLE), 3 AT WINDT TO BE AT WAST 15 I I NOT PHORE	AND THE FEE TO
- STRONG METHYNE TYPE DICH WON PULLING - COOMS BEETH HOLE CONTROL	TA STANT
MATMINI OUT OF HOLE	
E 60 110 5 96" 10 ppm (HoLE), I AT LIMIT CHAIR THE OUTSTING AT A LIMIT	T 1410 0- Pm WELL
- LARCE PIECE OF CONCRETE ~ 8' DEPTH, 5' WE'DE, LUXINIA _ CHAIR TAKES PERIMETER REMOTINGS AROUND	STOCK PALE WHILL
	111 11 <sup>2</sup> 1 1 1 1 1 1 1
- CHRIS BRINGS SOMPLY OF SLAB; DX CRAY COLOR J COARSE - BACKHILL IN LEVEL &	
TEXTURE; THE 4 RUAD SUBBINSE? - EXCOUNTED WILL BE DINSTE AT 12 WOW	TUMOCRUW (9/19).
- NO READING ON FID OR HAW  - LARCE MIRSS LIPS FINALLY BROKEN THROUGH - 6-8" - BEGIN BACKTEU AT 430; END 1530	
- LARCE MIRS COMS FIRMED ISKNETS MILLIONS	
THICK, CONTRINED IN REBAR.	
- SOIL LATTING ARY LIMI DISTINCT B'LF BACKFILL, -	
~3-4' OF CHURACE, ~1-2' OF BROKFILL , -1' OF GREBACE -	
FOUND NEWSPARTE DATED 1971 FOUND 7-8' DE PTH -	

1 - Dang recommend to the contract of the cont	1. 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	alidae sum 60°
9/1/28 (CONT)	
-11 11 70 6 221 - 2	ARRAVE ONLITE DECC SAMPLENG EROW OWE 11E.
The mary concurs & Rosen Y	EPR OBETTI OBRS HAVE TO JUMP PRACHINE AKAIN
- FOUND 5 GAL METAL PAIL CRUSHED , 8 pp. 1.	
- COMPLETED TEST PLIT AT 1733) DECIMA SPRETERIOR	
END AT IECO (I CENT C).	SETT UP EXCLUSION ZONE - DEGON FOR TEST PLT 3
51/2 LEVEL B 10-1, 2:30-3:30, 3:45-5:	3d Jah Ku H. 015577   129/20
1/2 1000 ( 15.20-6.00)	
	370 CHRIS USTAY TID METER FOR ATE MUNITORING
2 LIVELD 8-10, 2-2:30 6:01-6:50	
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	25 D TANS O APAN AT HOLE
LWNCH 1:00 - 2:00	
	FOUND LARGE METAL APPLIANCE DIN WEST SIDE OF PIT WAS I SHE MEDITAL
Total 9.5 V	acasa on minimum and many and and many and and and and and and and and and and
	1 3-31/1 OF BONN FALL MATERIAL, START BRINGUP DEBRIS
	- WORKLAND MICHEARE ADMIND AT 31/2 DOPTH
	FOUND PATTO NEWSPAPER AT 17 DEPTH
	was a 1-2' FILL LAYER AT ~ S' DEDTH, GARBACE ALAIN A G'2-7
	FOUND TEWILICAR GAS TANK AT ~ 91/2
	(3) 1040 Oppm AT TO E
	I like the second of t
	EXCHAND DI BYRNEVEL AT 1085; EPS STORS DECUME AT 1045 41 BYRNEVE
	MAIN REGIONS PRECON OF BUNDET WILL FLATISH FLT WE EXCENDED IN

the state of the s

some a secondary of	The second secon				
<b>©</b>		han transmitte general years a first transmitted governor and several problem for	mangharana ina	The same of the sa	
9/10/98 (4)	m)		] ,		• ; ;; . • .
			,	19/10/98 (cour)	
TIST PIT 3	*			BARED ON READINGS WORK WELL PESTANT IN LEVEL C	
,				- RESTART DIECTING AT INDU	;
6'x 32'x18'				- EXCAVATOR IS 10590D (TOM DEEXE)	
			{	1 25 0.5 ppm   AT HULE, ~ 14'	
				SEEMS TO BE ANOTHER FALL LEVEL OF 12 AT 11 DEPTH	
				1970 WEISTAPER AT -15"	
			te	ACHTENO 18 DEPTH AT INDEPTHEND OF TP3	
				FOUND 2 CHUSHED TIECTS OF METHE AT 18 DU SOUTHERD UND	H 1P
				SOIL COLUMN PRELIMIES INTENTIT AT 16-18'	
			1	HOUND 5 GALLON TICKACO DEL CONTRAMA AT 18	
			,		
				momen 1976 www.mat at 18 south evi	
				A 19168 inchrepaper Found At 118 , Soluth Ended	1-1-1
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			SEC THALES SAMPLE AT 191", AT SOUTHER END.	
	16			- BICKSALC COMPLETED AT 1200 REPARSIACS TAKEN AT HOLE OPPO	┪╢
			1	ABLE TO EDITAL THE LEVEL DI FOR THOTOGRAPHS SYNCHUCE FORMS 1	[א
			, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Stuckette from winther kpd maximum Difety	
	1 22'	•		TESTIPET CONTAINED CLAIMAN RUGBISH, WENSPAUN, BOTTES	المعج
	<del>-0</del> 1 / · ·			MOD, SMALL PECCES of METHER !!	
	SHARON OIL			5 gallon when Prague PARAT PATE TOWN DOWNTHIS DE	4.
N					
			[		
•		•	• .		

	B
	B
	9/10/98 (401)
9/16/18 ((017))	<b>₹</b> ŢŸŢŸ\\`\\ <u>\\\\</u> \\ <del>\\\\\\\\\\\\\\\\\\\\\\\\\\</del>
BREAK FULL LUNCH AT 1230 I MAN FROM KPS TO STAY	COLUMN WITH THAT HIT S MOVING TOWARDS FRANCE
AND BACKFULL LEVEL C	The high land and coming legistic rectionation
BACKFOIL COMPLETE AT 1530 (MAN 1/2 WHERE); BOTH	PERDITION UN LAST BULKET FULL WORK IN FORM, FROM 46 NOTH
BUCKETS DECON'ED.	NOTHER REALING HEARN A PILE NEAR TO IT WAS GODING
BEGIN REDICGING TEST PIT 2 AT 1400; HENEL C	SECOND EXCONTROD AT TP 2
MOVE ~ - 2' NORTH OF DRUM, FOUND METAL BED FRAME	
FOUND 5 gal PATL OF "STRIPPOR CHANER", Oppose within	
1 1420 18", 1-2' N OF DRUM, Oppm	
The same country to the same of the same o	
DRUM WAS REMOVED FROM TEST PIT . TARTIFALLY CRUSHED, EMPTY,	
NO MARKERS, INITIAL REMAINS OF 2 APPLY INSIDE, THOU DOWN	
TO Oppm	
ANOTHER DRUM FOUND 6-8' DIWN, WHAT WATTON	
OF FIRST DOWN, SIDEWAYS DRIENTHIJUN -	
S REMANGTING PAND, SHAVER DIVERN, WRITHEN ON TOPOF DRUM	
2 GO MAIN ST , BRINGE PORT, CT.	
US PRODUCT (LUNKHOWN LOPETTING), PITTS BURG	
NO HUBERLY SOIT ELYINING WARMS DIWALL HALLENING FOR	<del>'' - - - - - - - - - - - - - - - - - </del>
\$ 09934 (PRODUC #).	

(E)		<b>(</b>
-9/10/98 (UNT)	9/11/98 50 Yumay 65	
FILL LAND WAS 6"- Y' IN THICKNESS	APOLITIE   DO 322	
DEBRIS LAYOR FROM 1'- C'	DAM FATON (DOC) CNETTE GTEO	
6-12 IS FILL MATERIAL	_   EP\$   callstifk   148 bc)	
	-  -  -  -  -  -  -  -  -  -  -  -  -	
CRUSHIED 55 gol Down ~ 10' IN MEADLE OF TUST PIT	_ suspended keps to prosmore nows AT TO 2	
	cousins trums with from Excavation is	
2 16 to , ~ 10 DEPTH , I PPM SE END	BECEN TPH AT 0850 LIEVEL C	
	HITT WATER AT 5 6' STILL IN GARAGES	APPRAIS
3 1630 7 11 DETTH , I PPM , MIDDLE OF PET.	MATER MAY HAVE BOSH TRAMPOS IN 2 LARGE TIPE	14 1 6 7 7 1 1 1 1
	BEDUELT WE TOOK READING OF YOUT - MATE	
BULLET FRUM 14' DEPTH HAD CONTACT RUPLINGOE SUPPRE	Opam	
ANOTHER CRUSHED DEWN TAYEN OUT AT THIS MPTH	QUETE A FON THREE BURTED IN THIS AR	AA ALSO
NOT MUCH DEREIS FOUND AT THIS DIPTH	SEVERAL SMALL PIECES OF THEM (MUFFER T	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
TOOK PLANTING FROM SOIL AT 17' AT. HOPPIN AND 140 PPIN		
	JOHN CONKND (CONKND) CERSCIENTE) CASTITO	ofi2s    _ _
DEC TAKES SAMPLE FROM 17' IN MINDLE OF THEIPET;	R NOT WATER HEATERS FOUND 78 DEPT	H
REPORTING OF BETWEEN 100-300 pm DUFENG SAMPLENG	<u></u>	
TP 1 COMPLETED AT 1700; BECIN BACKFILL	ERS COMPLETED REPRURIENC NEBRES AT TO	2 + B   AT 0915.
BACKETU COMPLETED AT 1780	++	
	DOBS -11, KAUDING FROM BANKER TOO	2.1 d. de lumite un
DEC PERSOUNCE GEFSITE AT 1735	- Oppm	
EPS PITTE WILL OFF SITE AT 1735	The state of the s	
ISS OFFSETT AT 1735	TO ITOKY 14, WE WORLD EAD OF EXCUMU TO	
1		


MILLENET D 8:30-9:30, 130-200

LUNCH 12-1230

...

....

THE RESERVE THE PARTY OF THE PA



(22)	A constant		<b>2</b>	
9/11/28 (LOUT)	á ,	9/1/98 (LOV)		ገ :
BESTU TOG AT 1200 (LEVEL C)		becan backeric of TPL AT		-
2' OF BONY FILL MATERIAL ON	907 (	REGION THE EXCAUNITION AT	-  -  -  -  -  -  -  -  -  -  -  -  -	
GALBASE AT 2' LEVEL, BASS OF V	TAVET, GLOKS ROTTLES	-11' BON FILL MUTELIAL E	TOP GARTINGE STURTS	-
MOD, TILETS, ETCSOIL ~4 SEEMS A LITTLE MARE	MOJET PESSERLY			
PLINOTE FROM RASE		D 1400 , 23 , 0 pm (45)	MOUTH END	
GLAY SOIL FOUND AH', I ppm		BACKETLL OF THE COMPLE	TH) AT 1405	
THE PARTY FOUND AT H, PALLED	1872			
THE PERSONAL OF BUCKET AT 122	DIN (NORMAN)	(A) 1407 45' D.5 mm (1400		-
DEC TAKES SAMMAN FROM SOLL	PLUE FROM 9-10'DEPTH	B 1910 5 4 1 1 pm (104)	<mark>╙╃╃┧╃╂╄╂╇╟╫╀╀╢╢┼</mark>	-
The inter surished I while days	20 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			1
3' GEMPL TOPLANT		- GALLECT CONSISTS MOSTLY	DI DAME MON PURTIC, NOON,	$\dagger$
6' 6 PRIBACE		CLYPS, ETC. APPENES SUIGHTI NEWSPHAR DATES 19:19	Homo -8, Distry	
SAND (	BOTTOM OF HOU!	MEMBLAIAF DWANT		_
and and are		1 1416 8-91 2 pm (H	Hard)	4
COMPLETED TPG AT 1225		3) 430 - 5, 4 pan (M)	E- CENTURE FROM BULLET)	+1.
				4
LUNGH 1230-130		PAMENT CHAT COM THE	AN OLD PRISSURE THANK (300-500	3
		ROM THE DIPLIFE BO	_ px#m, .4_9	
**		(6) 1500 14 DETTH 3 ppm	(Haur) MISSON OF PIT	
		- 12 13 VI - 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
17	1 1	<del></del> •		

		A STATE OF THE PARTY OF THE PAR	
9/11/98 (4)11		9/11/98 (10/17)	
TEST PIT 48	N	COMPLETED IP B AT 1620	
6'XZ5'X 1'		DET THEOR SHOWN FURET AT IT	DEPTH
		EDS CREW THUES EXAMINATED BACK TO THAT	W BLEIN CIENTING
	SMALL RISE	BACKESUL BA TPT COMPLETED TO	
		BECTO BOULFU OF THE 650 (LEV	TUS) COMPRESED AT 1 1
		DEC CREW COFFETE 1700	
3 50 >			1700 (779)
Pag So		crew stopped cuanting work at	
	1975	14 NEVER C 830 1230, 30-430 - LUNCH	1230-130
		130-510	
	LAGE		
	718		
100181			
<b>3</b>			

1.1	
- 45 <u>₹</u> 1	
4.	
10.1	
74742. (1.4)	
3. 存籍:	
	•
1	
1.54	
145	
1.3	
. · · ·	
1	٠
4. 4	
Page	
<b>:</b>	
16-57	
11.44	
	٠
- 14	
1.1	
1 1:1	,
· .	
, F. (	
\$ 1	
2.1	
i = i	
4.4	
100	
4	
18.91	
100183	
1	
	•
$\equiv$	
. 🛏 🗀	
~	
$\mathbf{\omega}_{i}$	
CO.	

July July July

	The congress of the condition of the
9/14/98(por)	HAB CONT)
YERY STRING PESTILEDY TYPE OLOR COMENG	
FROM FXCAVATION AND METIAL AND POWDER ROMOUS &	AND THEIDE ST" DILLIM HAND METER TELLED SLALE, BLACK
From HOE NO CONDENS ON HALL	121 SUBTINUE INSIDE DEPTH OF 2-2'12 (100 ppm)
DRUM THAT EXCAVATOR RIPPED INTO IS LINED	
WITH PLATTE (SAM AS SMALL CAN)	BOME LIGHTO SARSHED OUT HEG WILL SAMAK SUIL FOR
DECIDES THAT OVERTHENIAS TOWNER WAS NOT	
PRODUCTIVE: 100 MUCH WAS BLOWING AWAY OR	THES DUMN WAS CHERPHENE'S BH EAS , SMELL SETTING TO
SPELLING. DECLY TO REBURY PRODUCT	FORME AS TP1, WHITE HORDINGS WELL BETWEEN IN 310 pan.
AND MARK FOR FUTURE REFERENCE THIRE	N ADJITION TO THE 5 VISCIBLE MILLIMS IN THIS
WETLE MARKY SMALL METAL CONTACHINES CONTACHING	RATEON THERE 3 HURE PURIEN HERE
WHITE POWER IN THIS AREA	
BEGIN EXCAMPTING ON WIST SIDE OF POWDER	D 1140, reverso beum, ROppom!
DUMPING AMEN WHERE 5 VISIBUE DRUMS AND	
	LOUSTANT REMOTING OF 15 ppm IN EXUMPTION CAN SEE
(1) 1635 READING FROM DRUM REMOVED FROM INUITY	I HETET IS DRUMS IN WALL OF EXCAVATION (BOTH STREET)
Defin	I LIGHT IS DRUMS IN WALL OF EXCAVATION (BOTH STRES)
(2) 1039, 30 Deum, Oppm	young per 1 DEP ON ENS STEE OF TRANCH 2 DEEP ON NEST STEE.
3 1043, 41th meum, 1 ppm	
	lectrical Febri musch At 1:00, PECIN DICGING AT 1330
TRAPERTY DUNCE FROM PROPERTY TO THE SOUTH	
DE NS STOPPED BY (BUT ROY BUDILY) TO BE SUIT	THEN PIT, - 30, NORTH OF TO DIC (SEE DEORENIN 6 83).
WE KNEW WHERE PROPERTY BOWNAY IS. SAND	10 1550, west wy (two inequal forum), ~21, Opport
HE BELIEVES THAT FORMER HONDTILL OWNER HAD	
DUZER BACK HERE TO THES AREA IN HE DOSAT	AFOUND TOO TO DOWN, DAPON
BELIEVE LANGE PIBE IS NATURAL!	

	33)
9/15/ 9/14/98 (100T) 9/15/	'
nactv	vi byliti p735,     -     -   -   -
DISTRING NOTICE COST COST COST COST COST COST COST COST	OULLIFE UEZS WIFERST LOAD OF TOPSOIL
BOTH STAVIL AND NOUBLE LANDING.	T AND PURCHASED 5 LAS OF SHREDDED STRAND, 25 bx DT
Milli A Diming Lord The wast been a feet and the little of	51 PERUNNEAL 27561245 AND A 2016 BAC OF 13-25-12
	EN FIRSTIJEER FROM HEUERTON AGWAY
TO DOWN TOWN TO LINE TO THE THE	
Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Maria Ma	TA 6m PHASTIC OIS DRUM AREAS AT THE, AND
STOPPED EXLANATION OF TP9 AT 1635.	5   Housery   Hortzitt   8044"
restainant in-12 hours to THES AREA	MUCD TP2 LUTTA STAKES AND PLEBON, AFTER SED.
Baketiy Compute AL 1 180	TLIZET ANY STRAW LIKE APPLIED.
FR OFFSITE AT 745 4 12-1: lund	
	123 0 BAGTAYS DECON OF EXCAVATOR AT 1150 COMPUTED
2 HRS UNZ D 9:15-9:30; 1:n-1:30 17:30-12:45 124	
815 - 930 level D 141	12 AND 2 HAD TO PROFY RECOMP
1 a:20 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	13-8 HAD TOPSOIL FROM ALLEN SAND + GRAVEL
	3-8 HAD TOPSOEL FROM ALLEN SAMU + GRAVEC -
	PROIL INSTRUMPTION COMPLETE AT 1580
	PK DEGONG BACK HOE TO LINGS
	TR OFFIS TE AT 1689
	RSD OFFS TO AT 1630
	Continues explaines programmes and programmes and programmes and programmes and programmes and programmes and p

大陸のはないないと、一般に対して、 大はい

	<del>2</del> 7 -	<b>&amp;</b>
TRILOGY PERENNIAL RYEGRÁSS BLEND	ONLY (	1 15/18/16pT
PURE SEED:  PENHANT II PERENNIAL RYEGRASS 39.13% 90 11/97 OREGON  WIZARD PERENNIAL RYEGRASS 29.51% 90 12/97 OREGON  ICE PERENNIAL RYEGRASS 29.29% 90 10/97 OREGON	2 8	(g, 1 <sup>7</sup> )
OTHER INGREDIENTS: OTHER CROP SEEDS INERT NATTER 1.48 Z UEED SEEDS .03 Z	F/ON	
NOXIOUS HEED SEEDS: NONE FOUND  LOT# L6-1681  NET WEIGHT: 50 LBS.	From POLOMES SAND + GRAVEL	
CARDVAIL  ORAHER B, \$31 ROUTE 28  HIVERVILLE, HY 12130	SHWD + GRAVEL	
	SEED OF	<u>6</u> 20 8
	LA ALISA Emale with Emale with	
	7 2 2 2	
	1 THE STATE OF THE	
	A 7 0	_ _ _
231001	= ₹ ₹ 1001	<u> </u>

New York State Department of Environmental Conservation

Division of Environmental Remediation, Room 260B

50 Wolf Road, Albany, New York 12233-7010 Phone: (518) 457-5861 FAX: (518) 485-8404



Mr. Richard Caspe
Director
Emergency & Remedial Response Division
USEPA, Region II
290 Broadway
New York, New York 10007-1866

Dear Mr. Caspe:

RE: Amenia Town Landfill Site (#3-14-006)

Amenia (T), Dutchess County Request for Emergency Removal

The New York State Department of Environmental Conservation (NYSDEC) hereby requests the United States Environmental Protection Agency (USEPA) to perform an appropriate CERCLA/SARA authorized emergency response action at the Amenia Town Landfill located on Rt. 22 in the Town of Amenia in Dutchess County, New York.

The site is located in a relatively rural area although portions of the Island Green Country Club golf course are located less than 1000 feet from the southern portion of the site. The majority of the site consists of an open field but the site also includes a paved helicopter landing pad and a small fenced propane and oil storage facility. The southern portion of the site includes an access road which runs through a wooded area of the site. A steep ravine runs along the entire western side of the site and descends into a wetland.

Previous site investigations by NYSDEC standby contractors have uncovered numerous buried and partially buried drums in the wooded southern portion of the site near the top of the slope to the wetlands. An estimated 30 fifty-five gallon drums of spent solvents, pesticides, and other unknown wastes were identified. The total extent of drum disposal in this area is unknown. Evidence of past and ongoing releases were witnessed and documented by NYSDEC staff during the test pit investigations.

Due to indications that a release is both ongoing (i.e., visible stains originating from containers, solvent odors, deteriorating/bulging containers) and imminent, it is necessary that a timely response action be undertaken to stabilize, identify, and dispose of these materials properly.

A site meeting and walk over has been scheduled for October 7, 1998. NYSDEC staff will provide EPA staff with additional site information at that time. If you have any questions, please contact Jeffrey Konsella at (518) 457-0414 or Thomas Vickerson at (518) 457-7878, both of my staff.

Sincerely,

Michael J. O'Toole Jr.

Director .

Division of Environmental Remediation

c: B. Sprague - USEPA Region II, Edison, NJ

R. Salkie - USEPA Region II, Edison, NJ

G. Zachos - USEPA Region II, Edison, NJ

bcc: M. O'Toole (2)

T. Quinn

A. Klauss - NYSDEC, Region 3

R. Pergadia - NYSDEC, Region 3

R. Rusinko - NYSDEC, Region 3

E. Belmore

C. Jackson

J. Konsella L

H. Koelling

T. Vickerson

Dayfile

TJV discI:epaamenia.wpd



**EPA** 

Superfund Removal Program

Region 2

Amenia Town Landfill Amenia, New York

December 1998

#### INTRODUCTION

The U.S. Environmental Protection Agency (EPA) has stabilized hazardous substances found at the Amenia Town Landfill Site (Site) located on the west side of Route 22, 1.5 miles south of Route 44 in Amenia, Dutchess County, New York. Buried drums and contaminated soil identified, in two areas of the landfill, by the New York State Department of Environmental Conservation (NYSDEC) have been excavated from the landfill, secured, sampled and prepared for removal from the Site.

Because the hazardous materials found were stored in leaking or deteriorating containers, EPA was concerned that they could pose a danger to the environment and wildlife if left at the landfill in the condition in which they were found. Rainwater runoff from the landfill, which could potentially pick up the contaminants. drains onto a wetland adjacent to the Site.

EPA began the cleanup on October 15, 1998 and completed the work on November 20, 1998. A total of 197 drums were excavated from the Site. Thirty of these drums were found to be empty. The additional 167 drums were repackaged in proper containers in order to secure the materials they contain. These drums are being temporarily stored on the north end of the Site. Approximately 220 cubic yards of contaminated soil was also excavated and is temporarily stored at the Site. The pile is covered with a plastic tarp and a berm was constructed around the contaminated soil pile to reduce additional contamination from rainwater runoff.

Currently, samples of the materials in the drums and the excavated soil are being analyzed to determine the appropriate method of permanent disposal for these materials. EPA plans to remove the materials for permanent disposal over the next several months. Though only temporarily being stored at the Site, the materials are safely contained in their current condition.

EPA is addressing this Site under the Superfund removal program. To date, approximately \$160,000 has been spent for the clean up of the Site. Additional funding will be required for the disposal of this material.

Representatives for the Town of Amenia and the NYSDEC as well as the property owner have visited the Site to monitor EPA activities and examine the material being excavated

### **BACKGROUND**

The landfill was operated as a municipal landfill from the late 1940's to 1976 when it was officially closed.

A Phase I investigation was conducted by the NYSDEC in August 1986 to identify potential hazards at the Site. This investigation concluded that sampling was necessary to confirm the presence of hazardous wastes at the Site and to determine if the contamination presents a significant threat to human health or the environment.





In-the fall of 1991, the NYSDEC conducted an investigation -at-the landfill -during-which-they performed a geophysical and soil gas survey, in addition to soil, surface water and sediment sampling and analysis. The results of these tests were reported in the April 1993 Phase II Investigation Report which indicated several areas of suspected buried drums. In September 1998, test pits were excavated in these areas to verify the presence or absence of buried drums on Site. Drums containing material were found in the southwest portion of the property. Samples collected from the drums and nearby soil were found to contain solvents, pesticides, and other wastes. Upon determining that the drums and surrounding soil contained these hazardous materials, NYSDEC referred this portion of the Site to EPA for cleanup under the Superfund Program.

# Irmee Huhn On-Scene Coordinator

U.S. EPA 2890 Woodbridge Avenue, MS-211 Edison. New Jersey 08837 (732) 906-6813 Huhn.Irmgard@epamail.epa.gov

Jenine Tankoos
EPA Community Involvement
Coordinator
290 Broadway, 26th Floor
New York, NY 10007-1866
(212) 637-3677
Tankoos Jenine@epamail.epa.gov

# OTHER SOURCES OF INFORMATION

Information Repository\_

EPA will establish an information repository where members of the community can review documents related to EPA's activities at this Site. The information repository will be available for review at:

Amenia Library

Main Street, Amenia, New York 12501

Phone: (914)373 - 8273

Hours: Mon, 10am-5pm, Tues, 1pm-6pm; Wed 10am-12pm & 3pm-7pm; Th, 1pm-6pm; Fri, 10am-5pm; Sat, 9am - 2pm; Sun, closed

## Superfund Ombudsman

EPA, Region 2 has designated an ombudsman as a point-of-contact where the public can call to express their concerns or register complaints about the Superfund program. To support this effort, the agency has established a 24-hour, toll-free number. The ombudsman for EPA's Region 2 office is:

George H. Zachos U.S. EPA, Region 2 2890 Woodbridge Avenue MS-211 (732) 321-6621 Toll-Free 888-283-7626

For general information on EPA, Superfund, and other environmental topics:
<a href="http://www/epa.gov/Region02">http://www/epa.gov/Region02</a>